COMMERCIAL CAR JOURNAL

THE MAGAZINE FOR FLEET OPERATORS

FEBRUARY 1948

Read: Analysis of A.T.A. Roadeo Results—Pgs. 30-31

Exclusive "More-Load" design paid off for REO drivers at the A.T.A. National Roadeo. "More-Load" design shortens wheelbase and turning radius—means easier maneuverability in the tight spots such as this illustration shows. Operators save time . . . get greater payloads . . .

longer tire life. No wonder both driver and fleet operator cheer for REO—
"The Truck of Champions!" Reo Motors, Inc., Lansing 20, Mich.

REO




Much That's New...and "Job-Roted", too!



1. More Safety from the All-'Round Vision of New "Pilot-House" Cabs!

Note the tremendously increased vision of new Dodge cabs. Windshields and windows are higher and wider. New rear quarter windows are available, adding still more to vision and to safety. You get true "Pilot-House" vision in all directions. They are the safest cabs ever built.



2. More Comfort from New Adjustable "Air-O-Ride" Seats!


"Air-O-Ride" seats give the kind of comfort you want. You may have a "soft" seat . . . or you can ride on a "firm" or "medium" seat. You control cushion "give" by a lever at the bottom of the front seat. Seven full inches of seat adjustment provide the right legroom for every driver.



3. More Safety ... More Comfort ... from New All-Weather Ventilation!

Whether the thermometer is ten below or a hundred above—you're comfortable! That's because of the availability of an ingenious combination of fresh air intake, newly designed hot water truck heater, with powerful fan and defroster tubes, vent windows and cowl ventilator.





4. Easier Handling because of New Chassis Design!

By moving the front axle back, under the frame, and moving the engine forward, Dodge has greatly improved maneuverability and weight distribution. Also, a wider front axle tread plus a new type of cross steering permit a full 37° turning angle to left or right.

5. ... And Your New Dodge Truck will be "<u>Job-Rated</u>," too!

Every unit of your truck . . . from engine to rear axle . . . will be "Job-Rated" for economy, dependability, performance, and long life. The 248 basic chassis and body models are engineered and built for gross vehicle weights up to 23,000 lbs., and for gross train weights up to 40,000 lbs.



COMMERCIAL CAR JOURNAL

with which is combined Operation & Maintenance

Reg. U. S. Pat. Off.

Published monthly

Acceptance under the Act of June 5, 1934, authorized

December 18, 1934

Vol. LXXIV Philadelphia, February, 1948 No.

Julian Chase, Vice-Pres. and Directing Editor
George T. Hook, Editor
A. W. Greene, Managing Editor
Charles B. Rawson, Associate Editor
M. K. Simkins, Technical Editor
Joseph Geschelin, Detroit Technical Editor
Leonard Westrate, Detroit News Editor
Marcus Ainsworth, Statistician
Howard Kohlbrenner, Art Director
Gene Hardy, Karl Rannells, George Baker
Washington News Editors
R. Raymond Kay, Pacific Coast Editor

EDITORIAL CONTENTS

Copyright 1948, by Chilton Company (Inc.)

CCJ Render Digest		0
FEATURE	ARTICLES	
Splash Guards for Nor	thwest Operators 3	4
Vehicle Replacement—Capi		6
Centralized Equipment Con		8
The Conference Corner—En		0
Scattered Dairy Maintenance		2
Toll Roads-Fleets Should		8
Fleet Experience Handbook		9
Truck Application—Step 8		1
Trouble Shooting Engine I	Bearing Failures 5	3
Reflective Materials		8
9 Ways to Reduce Sludge .		4
Fifth Wheel Kingpin Offse	et 6	6
Trailer Manufacturers Meet		8
Chevrolet Announces Refin	ements for '48 8	19
	RTMENTS	
Shop Hints 44	Washington	
The Overload 47	Runaround 7	4
Laugh It Off 57	Truck Specifications . 7	7
Free Publications 60		0
New Products 61		2
CCJ Quiz 71		6
Datroit Dianatah 79	Floatman's Library 14	0

G. C. Buzby, President and Manager, Automotive Division E. W. Hevner, Cir. Mgr. E. H. Miller, Adv. Mgr.

REGIONAL BUSINESS MANAGERS
RUSSELL W. CASE, JR., Philadelphia
E. E. ELDER, Detroit
JOHN C. HILDRETH, Cleveland
JOHN C. HILDRETH, Cleveland
JACK C. HILDRETH, Cleveland
C. H. WOOLLEY, San Francisco
AUGUST HAURIN, JR., Los Angeles

C. H. WOOLLEY, San Francisco
OFFICES
Philadelphia 39, Pa.—Chestnut & 56th Sts., Phone Sherwood 7-1424
New York 17, N. Y.—100 E. 42nd St., Phone Murray Hill 5-8600
Chicago I, Ill.—Rm. 916 London Guar. & Accident Bidg., Ph. Frankin 4243
Detroit 2, Mich.—1015 Stephenson Bidg., Phone Madison 2090
Cleveland 14, Ohio—1030 Guardian Bidg., Phone Cherry 4188
Washington 4, D. C.—1091 and 1093 National Press Bidg., Phone District 3110
San Francisco 5, Cal.—605 Market St., Rm. 608, Phone Sutter 1-4951
Los Angeles 1, Calif.—6000 Miramonte Bird., Phone Lafayette 5525
SUBSCRIPTION RATES: United States and United States Possessions and all Latin-American countries—35.00 per year. Canada and Poreign—510.00 per year. Single copies—50 cents. April issue, \$1.00.

Owned and Published by
CHILTON COMPANY (INC.)

Executive Offices
Chestnut and 56th Streets, Philadelphia 39, Pa., U.S.A.
Officers and Directors
Jos. S. HILDRETH, President

EVERIT B. TERHUNE
THOMAS L. KANE
WILLIAM H. VALLAR,
HARRY V. DUFFY

Vice Presidents

P. M. FAHRENDORF
G. C. BUZBY
CHARLES J. HEALE
Treasurer
JOHN BLAIR MOFFETT, Secretary
T. W. LIPPERT
FRED V. COLE

GEORGE MAISWINKLE, Asst. Treas.

PAUL WOOTON, Washington Member of the Editorial Board



Hard Knocks-

the tailgate gets more than its share!

Opening freely and closing tight in spite of years of hard knocks—that's the body tailgate's part in keeping St. Paul users coming back for more.

Heavy Duty Tailgate illustrated has angle steel frame with box-type vertical braces. All St.Paul 'gates are double acting—hinged top and bottom. Hinges and fittings are heavily flanged steel castings. Spreader chains may be set for any opening desired.

There's a St.Paul Body and Hoist for every earth moving job!



DUMP UNITS...TRUCK PATROLS

ST.PAUL HYDRAULIC HOIST DIVISION
GAR WOOD INDUSTRIES, INC.

2207 University Ave. S. E. • Minneapolis 14, Minn.

ne

ht

de

SS

ng

m

b-

re

cle for





←CHESTER W. SMITH, left—winner of National Truck and Full Trailer title —has been driving for 19 years (five years with the Reliable Transportation Company of Los Angeles, four years without accident). Like other two first place winners, all three national runners-up, and 22 others of 49 state champions, he drove a REO to win championship.

Three-time winner of the Tractor Semitrailer division Charles W. Zimmerman, left—congratulates Alex E. Adamski, fellow Chicagoan, the new Straight Truck Champion. Zimmerman, 39, has 16½ years experience, 14 years without accident, drove for Cushman Motor Delivery Company. Adamski, 34, has a three-year accidentfree record with George F. Alger Company, Chicago.

lin je sr mP of fir u li n o

1

Analysis of ATA National Truck Roadeo Results



Kenneth Clay, John R. Winter, Norbert Totzke—three more champions who prefer REO. Winners of second places in (respectively) Truck and Full Trailer, Tractor Semi-trailer, and Straight Truck events. Each is top man in his class in his own state. Totzke, of the George F. Alger Company, Chicago, came in only half a point behind Champion Adamski in the finals. Winter (Dohrn Transportation Company) is from Rock Island, Illinois. Clay drives with the Associated Trucking Lines, is Michigan Champion of Truck and Full Trailer Class.

Why did one make of truck star in all events? Here are some interesting conclusions from an examination of Roadeo results.


THE PHENOMENAL skill of the contestants in the finals of the National A.T.A. Truck Roadeo provided genuine thrills for the crowd of 5,000 who witnessed the contests. The winners, pictured on these pages, are without doubt among the world's best drivers . . . as to driving skill, courtesy, safety, knowledge.

The contests themselves are of great value to the trucking industry. They bring public attention to the professional proficiency of the drivers... and all drivers get a goal of safety and expertness to shoot for.

While Roadeos have answered the question, "Who are the best drivers?"—they have brought up other questions. One was: "Why did 28 out of 49 Champions win their titles driving one make of truck, when every major make was available?"

That 53% of the state champions won their honors in REO trucks through pure coincidence seemed unlikely *before* the national contests. In the light of REO'S 100% sweep of first and second places at the national Roadeo, it's obvious that there are other reasons.

It would be foolish, of course, to assume that REO trucks were altogether responsible.



1. Offset Alley Problem: to test driver's ability to get through the limited space of an offset alley at a 45° intersection. Fined for jerking or stopping (here's where that REO Gold Crown Engine's smooth power pays dividends) and for scraping or running over markers (REO's full-vision is a godsend here). 2. Straight Line Problem: to see if driver can accurately maneuver his right wheels over a straight, narrow path. Demerits for wavering from line (the fine balance of a REO and its straight-line stability—due to the "More-Load" design—help to hold a die-straight course). 3. Forward Serpentine: to test driver's ability to steer his truck in close limits. Continuous forward motion, exceptional visibility again needed for top scoring. Easy and accurate steering with smooth-operating steering gear counts for plenty in this event. 4. Parallel

Parking: a really difficult parking test, calling for everything a driver can get from his vehicle. REO's "More-Load" design offers a shorter wheelbase, shorter turning radius; means less jockeying, fewer maneuvers. 5. Alley Dock: to test ability of driver to back down narrow alley to within six inches of loading dock. Quicker response to turns, smooth operation of Gold Crown Engine, excellent visibility, shorter overall length mean more points in this event for REO driver. 6. Fire-fighting Problem: roomy cab and wide doors give easy entrance and exit in emergencies. 7. Diminishing Clearance and Stop Line: another tricky bit of steering; calls for true and stable steering gear and a well-balanced chassis. Exceptional over-the-hood full-vision and reliable, smooth-working brakes can reap some extra points.

Twenty-three of the twenty-nine contestants who drove a REO in the finals did not win firsts.


Champions in the trucking field, like champions in sport, become more particular about their equipment the better they become—and more likely to demand features not found in all equipment. This was amply borne out at both State and National Roadeos. The higher the

contest level, the fewer makes of trucks were selected by the drivers. In the state contests, for instance, almost 50% of the winners were divided between trucks other than REO; while in the Nationals, every winner and runner-up chose a REO to help him win!


"More-load" design is an exclusive REO feature. Its advantages are not all felt in the Roadeo. But the maneuverability it gives a REO is believed to be one reason so many Roadeo champions picked REO.

"Truck of Champions"





Diagrammatic representation of REO "More-Load" design. This exclusive REO feature gives all REO trucks extra time-saving maneuverability, fine balance, better load distribution, and greater load capacity per inch of wheelbase.



REO Model 25 with trailer, being backed into make-believe alley-dock at a Truck Roadeo. Stop must be made within six inches of the simulated dock. Like other REO models, it has exceptional visibility; roomy, comfortable cab; readily accessible engine.



INTERNATIONAL TRUCKS are completely specialized. Here's how:

They're Performance-Co-Ordinated. That means that engines, transmissions, axles and all other components are expertly fitted to the work each is to do.

They're Load-Co-Ordinated, by the exclusive International Truck Point Rating System. That means an accurate statement to each operator about the amount of payload that will be most profitable for bis trucks on bis particular operation.

Yes, International Trucks are sold right, speci-

fied right and serviced right.

Add the foregoing to the 41 years of demon-

strated International Truck performance, economy and dependability, and you have the reason why:

More new heavy-duty Internationals have been purchased by American commerce and industry for the last 16 years than any other make.

INTERNATIONAL

Motor Truck Division

INTERNATIONAL HARVESTER COMPANY 180 North Michigan Avenue

Chicago 1, Illinois



Tune in James Melton on "Harvest of Stars." NBC Sundays.



DO YOU KNOW THE ANSWERS?

CHECK YOUR KNOWLEDGE

How much have Dodge & Ford raised prices? P. 72

Splash Guards in the Northwest

By S. C. PUFFER

BOTH Oregon and Washington now enforce laws requiring the installation of splash guards on all vehicles. The general requirements are that they be as wide as the rear wheels and extend downward to at least 16 in. from the ground. Operators are left to their own devices as to how they comply with the requirements. Results reveal a variety of guards fabricated, in the majority of cases, from surplus rubber material formerly used in airplane gasoline tanks, and, in the case of tank trucks, from sheet steel. Surplus belting and canvas strips have also been used.

Virtually all of the fleetmen in these states agree that the splash guards accomplish little from a safety standpoint, diverting spray out the side where it may be even more dangerous than to the rear. But many, especially the largest operators, feel that the guards do have a definite good-will value. See page 34.

Vehicle Replacement

by JOEL DEAN, Prof. of Business Economics, Columbia University

THE problem of when to replace a truck is essentially a problem of control of internal capital investment. A new truck must compete for funds with alternative capital projects on the basis of profits. The capital budgeting plan is based on the projection of future expected costs for both old and new vehicles. The behavior of costs with increased use of vehicle is the key to determining the savings that should govern replacement.

This plan not only shows how projections of future costs may be used to determine the ideal replacement point, but also, how the projection may be adjusted to variations in disposal value due to market conditions and to increased costs for such items as wages, productivity and prices. See page 36.

Centralized Equipment Control

by LESLIE D. CONYERS, Consolidated Freightways, Inc.

WITH its new ultra-modern dock and shop facilities, Consolidated Freightways management recognized the need for a highly-accurate centralized control system to assure maximum speed in the handling of all over-the-road vehicles at its big Portland, Ore., terminal. As a result, the office of the Equipment Coordinator was set up with full authority and all devices necessary to accomplish this end and at the same time to referee any disputes arising between dock management and shop management.

Feature of the control room is a huge panel laid out to conform with the physical aspects of the Portland yard. On it are pins and tabs which correspond to the actual location of each vehicle. There are also zone panels showing the routes over which each vehicle not in Portland is travelling, as well as the necessary dispatch and control forms necessary to keep pace.

It is the coordinator's job to assure maximum usage of both dock and shop facilities. Normally inbound vehicles are first routed across the service pits where 1 hr. 30 min. is the maximum time allowed. If more time for repairs is necessary or if more vehicles than the shop can handle are in, adjustments are made on the spot to assure most efficient handling. This requires that every movement be reported to the coordinator over an intercommunications system. After approximately one year of operation, the control system has been described as highly successful. See page 38.

Experience Guides Oil Change Schedules

by A. W. GREENE, Managing Editor, Commercial Car Journal

THE nation's top fleets rely upon their own experience, more than any other factor, when it comes to deciding on oil change periods for their vehicles. Of the 10 factors listed by the Board of Experts, 33.96 per cent work on this experience basis. Predetermined mileage schedules and discolorations are the next two most frequently mentioned factors.

Table 1 lists all 10 oil change factors according to vocational groups. Table 2 gives the oil change frequency schedules.


What fleets are doing with their used crankcase oil is shown in Table 3. The trend, based on pre-war practice, is in the direction of reclaiming and selling. See page 49.

Figuring Fifth Wheel Offset


by MERRILL C. HORINE, Mack Mfg. Corp.

PROPER location of fifth wheel with relation to tractor rear axle affects many characteristics of the performance of the vehicle train, including load distribution, steering, traction, braking, turning radius, maneuverability and riding qualities. At the same time the location is strictly limited by vertical clearance angle, cab clearance, clearance of underbody trailer parts and coupling heights.

This article presents formulae for the determination of both the ideal location and the practical location as determined by existing design practices which place the maximum offset at approximately 14 in. ahead of the rear axle center. See page 66.



SHEET METAL guard, welded to tank is used by Petroleum Transport Co. of Seattle. This one is Kenworth design



SURPLUS RUBBER guard, reinforced with stainless steel strips, is choice of Consolidated Freightways in Portland

Splash Guards:

How Northwest Operators Equip Their Vehicles

IN 1937, Washington passed its first "Splash Guard" law: "Every vehicle shall be equipped with a device adequate to effectively reduce the wheel spray or splash of water from the roadway to the rear thereof." (Chapter 5, Sec. 44 - 1937.)

Rigid enforcement began in April, 1946. Why not until then? The war; difficulty in obtaining splash guard material; or some other reason you can think of—but whatever the reason, on April 1, 1946, every truck owner was notified by letter and immediately thereafter the law was enforced, at first by warnings,

by S. C. PUFFER

CCJ Special Correspondent

and after July 1, by outright arrests.

Today it is the rare exception to see a truck on a Washington highway without some sort of splash guard attachment. There is no requirement as to the material. Guards may be made of canvas, rubber, leather, composition material or metal plate.

It is required that the guard extend downward to within not less

than 16 in. from the ground, and that they be as wide as the tire, or tires which they cover.

of

is

th

th

Ta

hi

ty


sta

th

Fi

The larger fleet operators have pretty well standardized on a composition material which is being sold as war surplus. It is a rubberized bullet-proof material used on military planes for gasoline tanks.

For the average truck or trailer, covering two wheels on each side, two pieces, 26 in. wide and 35 in. long are required. The material is approximately ½ in. thick. A pair of guards of the above size will weigh approximately 30 lb and cost in-






SGT. BLACK of Washington State Patrol checks 16-in. minimum ground clearance of conventional flap guard



COMBINATION guard used by Lee & Eastes, Portland, has sheet aluminum top, composition shoe sole bottom

Fleetmen find surplus rubber, belting or canvas best for regular rigs, light steel or aluminum for tankers, in complying with newly-enforced Oregon and Washington laws



stalled from \$12 to \$14 per pair.

There are two common methods of installation: one, where the guard is bolted to the truck frame, one bolt at each top corner of the guard; the other, by attaching an angle iron to a frame cross member and bolting the guard to the iron.

Eight fleet operators in the Seattle-Tacoma area using conventional highway rigs were queried as to types of guards and methods of installation. Seven of the eight used the composition material described above. One used secondhand leather belting. Five of the operators at-

tached the guard directly to the truck frame, three used angle irons.

None of the operators queried reported any trouble with guards coming off or being torn, except dump truck operators.

Tankers Are Different

SPLASH guards for oil transports and trailers are of an entirely different type owing to the shape of the rear end. Here the guard is usually of metal — welded to the tank with ½ in. angle iron braces to support the weight.

(TURN TO PAGE 114, PLEASE)



OLD BELTING does the trick for splash guards on dump truck of Halroyd Sand & Gravel Co., Tacoma

METAL & BELTING fills the bill for Ross Island Sand & Gravel Co.'s mixer but damage is heavy in this service



d

or

ld

d

n.

is

ir

gh



Using the Capital Budgeting System

A noted economist presents a new concept of timing vehicle replacements based on the projection of expected returns from capital investments

WHEN to get rid of a vehicle may not be the most important problem of motor vehicle management, but it is clearly the most controversial one. Dozens of articles and papers have been written on it. They present such widely different solutions that there appears no basis for agreement. And current practice is probably even more varied.

The principle justification for an addition to this imposing array of discordant doctrine is that this paper presents the solution of an economist. Viewing the problem as essentially one of applied economics, and looking at the matter through the eyes of top management, truck replacement is approached in this paper as an integral part of the broader problem of budgetary control of all the company's internal investments.

For simplicity the analysis summarized here is restricted. First, it is predicated on normal market conditions (i.e., availability of new trucks and market values of used vehicles normally related to new). Present abnormal conditions will not last much longer; hence the replacement problems of the future must be

by JOEL DEAN*

Professor of Business Economics Columbia University

met under the assumed normal conditions. Second, the discussion is focussed on the fleet operator and is confined to replacement of existing trucks. Third, it concentrates on concepts, principles and the basic method and does not deal with procedures and forms.

The plan presented here was developed for a large fleet operator and is now in use.

The problem of when to replace a truck is essentially a problem of control of internal capital investment. Decisions on truck replacement should be an integral part of a company-wide capital expenditure budget which is designed to control and ration the company's limited capital funds among rival investment projects. A new truck must compete for funds with alternative capital projects and must prove its survival worth on the basis of profits i.e. earnings on the replacement investment that are superior to alternative uses.

Capital Budgeting

FI

BRIEF sketch of the basic theory A of sound capital budgeting is therefore an essential prelude to our analysis. Opportunities for profitable internal investments will, if management is alert, exceed the company's This will limited capital funds. create a problem of capital rationing. Rationing should be on the basis of prospective profitability. Each candidate project should be made to stand on its own merits as measured on its future net return on capital. Capital should be apportioned by arranging projects in a ladder of profitability and by working down from the most profitable toward the least profitable.

The cutoff point on this rate-of-return ladder ought to set so that the standard of minimum return will remain stable over the business cycle. Carry-back and carry-forward provisions should take up the shock of year-to-year changes in need and supply of funds. Short-term borrowing should take care of a temporary excess of capital projects whose rate of return exceeds the standard. By this approach a company can make sure that the struggle for survival among alternative uses of capital funds will

(TURN TO PAGE 150, PLEASE)

^{*}Excepted from a paper presented at the SAE annual meeting in Detroit, Jan. 12-16.

Annual Costs of Keeping Old Truck Additional Years




FIG. 1. Basic chart shows cost of keeping the old vehicle. Capital wastage curve is based on market-price depreciation

Cost Savings From Truck Replacement




FIG. 2. Comparison of old and new truck cost. New truck cost is based on total estimate divided by life expectancy

Capital Wastage Derived From Disposal Value




FIG. 3. Normal disposal value of light truck at end of each year (top curve) and annual loss in value (lower bars)

Shifts in Disposal Value Function




FIG. 4. Compensation for future economic changes is provided by present-level curve A and future-level curve B

Annual Depreciation and Capital Wastage




FIG. 5. Actual market values (bars) and book depreciation (curve D) will eventually be equal. Difference is in timing

Shift in Maintenance Cost Caused by Wages, Productivity, Prices




FIG. 6. Expected changes in costs can also be projected. Projection involves hopping between curves and age brackets

ry

is

ur ole

ge-

ill ıg.

of dind its tal

ng

ity

ost

le. rehe

re-

ele. ro-

of

ıp-

ng ex-

of his are ong vill

NAL




Fig. 1. The author, Leslie Conyers, (standing) briefs his assistant, A. O. McMurry on exact status of every vehicle in Portland area. Two of the five zone panels may be seen at far left. Enlarged drawing (below) shows details of control board. For full explanation, see text

by LESLIE D. CONYERS
Equipment Coordinator
Consolidated Freightways, Inc.
Portland, Ore.

NEW and ultra-modern loading dock and shop facilities at Consolidated Freightways' headquarters in Portland, Ore., offer the very latest methods in handling freight and the servicing of equipment. Since these two departments are housed in separate buildings, it requires the greatest cooperation and coordination in unloading and servicing, and reloading equipment to assure the successful operation of both maintenance and freight handling departments with minimum cost and maximum schedule performance. About 460 over-the-road vehicles based at Portland are involved.

Realizing the problems involved, and that efficient operation depends on the coordinated movements of the equipment while these operations were in progress throughout the day, company officials set up the Equipment Control Room, supervised by the "Equipment Coordinator." This office was to have absolute control of "over-the-road" equipment while in the Portland area, and no equipment was to be moved without the consent of the Coordinator.

It was also the duty of the Coordinator to be the judge or referee in disputes that might arise between the



foremen of these departments, and his knowledge of the issues in question must be such that his decision would be fair and to the advantage of all concerned. Also, his decisions as to the distribution of equipment must be quick and correct; mistakes on the part of the Coordinator could cause loss of time, increased costs and poor schedule operation, which in turn would have its effects on delivery of freight to outlying stations.

The Equipment Control Room was officially opened on Oct. 15, 1946,

and the Coordinator was given all the time necessary to acquaint himself with the supervisors of the different departments affected by his office, and to study the operations and the problems confronting the shops and dock.

After several months of study, experiment and hard work, a carefullyworked-out plan was drafted and is now in successful operation.

These are the basic objectives of the plan:

1. Orderly flow of equipment

	O	CONSOLIDATE	D FREIGH	TWAYS, INC	<u>.</u> 0	Form 665
,	DAT	ILY EQUIPM	ENT CO	ORDINATION	SHEET - SHOP	194
		Time Eq	nipment			Time
Trir. Loads	Loads Entered Service Line	Rel's'd to Dock	Ret'd to Serv. Floor	Cause of Service Delay	To Dock	
225	Termenal 4	6=AIN	7:15am	12:50 PM	5 Broke Reliner	3.30 /
85	Miscellaneone	8:209M			Service Only	850a
389	Jerm 1	3:40 PH			v , it	420 A
369	West Coast Term	2. Pm	3.15 Puc	3:40 Pm	one Brace Reline	3.50 F
327	Miscelleneous - La	sht 415/4	34	1 Perm	Repaired on Lita	6. 19

	DAT		IDATED F		rs, inc. sheet - 1	DOCK	Form 675	
				quipment			Nov. 28, 1947	
Truck Trailer No.	Loads Specify City or Dock		Released	Depart to Pickup or Del.	Returned to Dock	Return to Shop	Causes of Delay	Shop Service Completed
225					12:45 Pm	12:50 PM		3:30 PM
\$5	Misellowoos		9:50 Am			V	11 12 21	8:50 am
399 369	Terminal /	11.500 =					Nelsell to food	8:50 Post
327	Wirellaneon Ligh	1.500	64W.	1130 am	3:40 Fm		Mulote for stay An	

Fig. 2. Form 665 (top left) records vehicle movements in and out of the shop areas, explains causes of delays

Fig. 3. Form 675 (lower left) gives corresponding data for same vehicles at dock areas. Together with the "big board" (opposite page), they give complete whereabouts of each vehicle

Fig. 4. Dispatch Priority Sheet (below) gives destination, tractor, trailer and schedule numbers for outbound trips

	COMSOLUDA	TED FREIG	PTWAYS. I	Form 150 NC. Rev. 10/1
Date:/2-/4-97	COLUMN STATE	XXXX BUILT	はない 田井か	
Destination	Trk. No	Trl. do	Sch.	Remarks
	70	NB 1 - OH		-
	742		-	
Bend,	144	65	21/4	
Redound	422	4/1	202	201
Coquille	102	770	202	617
Enterprise	30	127	222	4
Hood River	Buch	704	226 -	want co
Medford	16	471	20ls	
Pendleton	272	261	212	
Roseburg	86	483	206	
The Dalles	59	69	220	
Onterio	175	1991	228	
A Sec. Rel.	396 20	NE/27 OJ	200 LJ	ST HOC. CHAN AS
Coos Ray-Oak Medford-Cak	354	47.5	306	1/9
Medford-Oak	198	1924	308	140 479

CENTRALIZED

Equipment Control

Coordinates Shop and Dock Activities

Control room referees departmental disputes and schedules movements to assure maximum efficiency in loading and servicing of some 460 heavy over-the-road trucks and trailers.

through the service line, service floor and to the dock.

2. Elimination of slack periods in the maintenance and repair department of the Portland terminal.

3. Release of as many units by the shop to the dock as early as possible each day.

4. Prompt delivery of all full load lots to customers.

5. Prompt unloading of all LTL cargo.

6. Release of all equipment daily, that hasn't been serviced as early as

possible, by the dock to the shop.

Prompt return to the dock of all road equipment out on big mark pickups.

8. Maintenance of a higher degree of on-time schedule performance.

In implementing the plan the

Equipment Coordinator was given charge of the movement of every piece of road equipment through the Portland terminal until such time as it is released to the dock for final loading. No moves from service line

(TURN TO PAGE 108, PLEASE)

is

f

Experts Answer Fleetmen

We have been asked—"Do engine governors cut horsepower?" Knowing that this problem has been tossed around a great deal and that many times controversial answers have come up, CCJ has asked factory engineers for their views. Here are the answers as provided by the experts.

There are many such problems

There are many such problems troubling fleetmen today. This department has been originated for the purpose of clearing up just this sort of problem. Letters from fleetmen have already initiated other studies for The Conference Corner. Send us your question and let us give engineers a chance to discuss it on these pages.

chance to discuss it on these pages.

Next month technicians will discuss the question: "Are down-draft carburetors more efficient than updraft types?" Watch for an interesting discussion.

The Conference

QUESTION: Do Engine Governors

Horsepower and

ci

Any Loss Is Hard to Detect

by F. E. Williams General Sales Mgr. Zenith Carburetor "Generally speaking, the characteristics of all velocity governors, due to the throttle plate angle at which they operate, do cut into power a little bit. This loss, however, would be hard to detect in operation as it would be about two to three horsepower at the peak power point.

"Drivers generally don't like governors but this is largely due to lack of education. If they learn that the purpose of the governor is to protect the engine, rather than to 'cramp the style' of the driver, they do not object. Drivers of governed vehicles must be given schedules which they can make with the governor in operation with reasonable allowances for traffic and necessary stops. A lot of drivers resent governors because they cannot make up the time lost by delays. That kind of driver is the one who needs the governor most if the engine is to be protected.

"With a good governor it is not easy to attain excessive down-hill speeds to carry the truck up a succeeding grade. This means a bit more gear shifting but it does protect the engine and that is of vital concern to the fellow who has to foot the repair bills. The governor is not intended to make life easy for the driver. It is intended to protect engines. However, it does make the driver's job easier to the extent that he does not have to watch carefully engine speeds to keep within a safe operating range."

Affect Top Speed Not Pulling Power by C. E. Johnson Hoof Products Co.

"Up to the speed at which the governor is set, there is no loss of engine power through the use of the Hoof Governor because there is no restriction of the effective area of gas passage in the governor as compared to the carburetor

and manifold openings. There are some governors, better classified as restriction devices, which are notorious "power stealers"—but modern governor construction makes possible the same engine power output within ½ to 1 hp at the governed speed, that it is possible to secure from the engine without the governor installed. (In speaking of the modern

Verdict of Conferees

Some engineers say that any velocity type governors cut horsepower to some extent because of the restriction of the effective area of gas passage in the governor as compared to the carburetor and manifold openings.

Others insist that this type of governor affects top-speed—not the pulling power of the engine. Another manufacturer implies that loss of power would be hard to detect—if the engine is in peak operating condition.

Centrifugal governors, properly made, properly installed and properly set do not materially affect hp., says another.

governor, this constitutes the few governor manufacturers who have developed full power governors and have adequate laboratory facilities and testing equipment to prove this conclusively.) While it is true that an engine is capable of developing more power at 60 mph than it develops at 40 mph, this power is reflected only in speed and not in pulling ability or power on the hills. Any horsepower available beyond the point of torque peak is simply momentum. These factors depend upon torque rather than power, and the peak of the torque curve is invariably reached at some speed below the governed speed of the vehicle. A governor, therefore, affects only the top speed in the various gears, not the pulling power of the engine on hills or heavy going."


Centrifugal Types
Do Not Cut Power
by C. K.
McCullough
Plerce Governor Co.

"There is a certain amount of animosity among operators toward governors because of possibly some previous experience where horsepower was affected, but it is our opinion, substantiated by many exhaustive tests, that centrifugal governors, properly made, properly installed, and properly

set do not materially affect horsepower. We have installed engine speed centrifugal governors where the regulation between complete load and complete no-load has varied as little

Corner

Cut Peak Operating Efficiency?



"The above comments do not hold true in regard to the so-called velocity of vacuum types of governors, of which we have built considerable numbers, for the simple reason that general practice dictates that the valve must be placed in somewhat of an angle to the air stream in order for the air, which is the prime mover, to impinge on the valve and therefore cause it to start closing. This, in itself, causes some restriction and some attendant loss of power.

"Further, as this class of governor starts to travel, at the governed point the valve tends to move slowly at first and restricts the opening and offers additional horsepower loss. Upon complete throttling at the governed point the valves usually tend to open slowly after a rather noticeable loss of power.

"It has been our general reaction that the operators' comments on this class of control equipment are quite right and that horsepower losses will range from 5 per cent on up to as high as 20 per cent depending upon the speed and the efficiency of the governing medium being used.

"None of the above comments apply to the straight centrifugal governor, either road speed or engine speed, as their valves are completely out of the air stream and inoperative up to the approximate point of governing."

They Cut Possibly Two Horsepower by W. J. Potter Service Manager King-Seeley Corp.

"The application of a governor on an engine in peak operating condition, results in the loss of effective horse-power not to exceed two horse-power and sometimes, incidental to the characteristics of the governor and engine, less than that.

"To this extent, the application of governors sacrifices horsepower, but in evaluating this sacrifice, it should be kept in mind that the various accessories on the engine, all of them, require more horsepower than this amount. Such accessories as the fan, generator, water pump, air cleaner (incidentally, this horsepower loss is one of the problems in the development of air



cleaner design) and that, furthermore, engine condition as to bearings, valve lashing, timing, varnishing, et cetera, can cause a far greater sacrifice of horsepower than a governor application. Such things as defective steering, wheel balance, tire inflation, brake adjustment, also are reflected in far greater losses in horsepower than the governor application.


"The problem as expressed by fleet operators and drivers, we believe, is engendered by a resentment to any sort of control. The classic argument used by them, is that they cannot 'pull certain hills,' after a governor is installed, that they could pull in high gear prior to governor installation. We have investigated such complaints a number of times and have always found that such claims were based on excessive speed, known as 'running the hills' downhill in advance of a climb so as to acquire sufficient momentum to roll over the next hill without the necessity of shifting down through the gears. This excessive speed is injurious to the engine, dangerous to the equipment and constitutes a major reason why vehicle owners and maintenance superintendents employ governors, in that they prevent overspeeding beyond the recommended maximum engine speed set by engine manufacturers."

A Review of
Several Types
by Robert H.
Thorner
Sales Engineer
Mallory Electric Corp.

"Experience has proven that engine governors can be extremely valuable to fleet owners in reducing maintenance and accident costs. However, the advantage of engine governors cannot be realized unless the fleet operator understands the requirements of governers in general, as well

as the two basic classes of governors now being manufactured to meet these requirements.

(TURN TO PAGE 136, PLEASE)



Left. Company filling station, at El Paso shop provides centralized record control for home-based fleet

Below. Timing light is used regularly as part of 7-point PM program



O. P. Bond



Scattered Dairy Maintenance



116-vehicle fleet with well-equipped central shop and excellent PM program finds farmedout service best for branches, own repairs most economical for home-based vehicles

by O. P. BOND

Superintendent of Transportation Prices Creameries, Inc., El Paso, Texas WITH seven branches, and approximately one third of our fleet operating out of these branches only, our biggest maintenance problem is that of deciding what work is to be handled in our headquarters shop and what is to be farmed out. How it is to be farmed out, making the right contacts on this branch work, and keeping reliable unit records on branch units are corollary headaches.

There are 116 units in our over-all fleet. Our main headquarters and shop at El Paso, Texas, handle the operation and service of 70 units. Our seven branches, located from 40 to 200 miles from headquarters, are all in New Mexico: Roswell with 15 units; Portales with 10; Hobbs with 4; Carlsbad with 4; Las Cruces with 6; Hot Springs with 3; and Demming with 4.

A vehicle breakdown shows that 10 of the units are semi-trailers with tractors; 50 are 1½-ton, special-body wholesale trucks; 25 are ½-ton retail trucks; 16 are farm-to-branch, stake-body, 1½-ton pickups; and 15 are special-type, ¾-ton city delivery

Right. Maintenance record form $(8\frac{1}{2})$ x 11 in.) gives all basic data as well as mechanical history of each truck

Below. Mechanic checks distributor with dwell angle tester and tachometer

CO. NO. MAKE &YR.	MODEL	SERIAL NO.	ENGINE NO.	TYPE	CAP'Y. WEIGH		
cyl. Sizes	Rod Sizes	Main Si	zes	B.Dm	m Sizes		
Dist. Make	No.	Carb.	Make	No.			
Gen. "	No.	Fuel Pu		No.			
Volt.Reg.	No.	Aux.Bra		No.			
Starter "	No.	Aux.Tre		No.			
Trans. "	No.	Aux. Ax	le "	No.			
Oil Filter"	No.			-			
DATE SPEEDO. OPERA		DETAI	LS				



trucks used in El Paso, Texas, only.

The garage and repair shop at El Paso headquarters is kept open and operating 24 hours a day. Here we have one foreman, two master mechanics, one lubrication man and steam cleaner, one painter, and two night wash and grease men.

Branch Work Farmed-Out

WE make three regular inspection trips a year to all the branches, spending sufficient time at each to make full inspection on all units. The branch manager and the truck driver form the team at each branch which is responsible for the individual unit.

At the time of the inspections we decide what work is needed in the way of minor and major overhauls. Fully 90 per cent of this is farmed out and the contract for the work made while the headquarter's shop foreman is at the branch. The truck to be repaired is taken in to the independent shop and, with the manager, driver and myself, the whole layout is checked, an estimate on the

work obtained, and the work contracted.

A report is madeup and brought back to the El Paso office. After the work has been completed and the statement presented, this is checked with the examination-contract report before the bill is paid.

For repair needs between inspection trip dates, the branch manager and the driver take the unit to an approved repair shop.

On all units which are to be retired from branch use, or are to be traded in, the truck is brought to the El Paso headquarters and an exchange made. However this accounts for only a small percentage of the units repaired from branches.

Comparative Costs

SHOP work vs. farmed-out work is also a tough nut to crack at head-quarters. At present we do all repair and handle all major and minor rebuilding except body work and tire work.

Formerly we farmed out all of our reboring work. We bought a reborer

for the shop at a cost of \$355 and set it up on a ten-year depreciation rate—\$35.50 per year charged off.


Today we do all of our own reboring. On the average six cylinder job we rebore 6 cylinders in less than four hours at a cost to us (except for depreciation charge) of between \$5 and \$6. When we farmed out this work it cost us \$2 per hole, or \$12 for the block. This charge has been raised now to \$2.50, or a total of \$15.

Here is a unit savings of between \$9 and \$10 and we do 30 jobs per year, meaning a savings of \$250 per year (with equipment depreciation figured in at \$35.50 per year). Besides the savings, we get the work done when we need it and we know that the job is right. And our own rebore jobs have been standing up better than the former farmed out work.

Before the war we did our own body work. This was discontinued during the war. Our war-time experience was such that we have decided on a farmed-out program for all body work from now on. A body man who can handle all of our work can make \$5 per hour. With our fleet total we cannot afford to keep a full time body man. Nor can we afford second rate body work when good work is needed.

Rigid Tune-Up

THE 70 units which are serviced out of our El Paso headquarters receive a complete motor tune-up on the average of each four months. We expect our master mechanic assigned to the unit to spend an average of (TURN TO PAGE 118, PLEASE)



1. Hub Puller

by Lewis Condon Rainbow Bread Co. Brookfield, Mo.

Here is a puller we have made to remove truck rear hubs (full floating) when bearings have become damaged and frozen. This type of tool has been in use in our shops for ten years and will do any job.

Dimensions will depend on the size of the hub and the axle housing. The puller is made from three parts. A flanged thrust plug slips inside the end of the housing with flange bearing against end of housing. A threaded plate is drilled and bolted to the hub at the axle studs. A threaded shaft screws through the plate to exert pressure on the thrust plug.

Any shop can make up a tool of this type at little expense.

2. Wheel Carrier

by Robert L. Moore Major, Ordnance Dept.

Here really is a "Giz-Mo" for removing and carrying heavy truck wheels. The device is simply an adjustable jack mounted on four wheels or casters. Four metal uprights of angle iron 3 ft. long are bolted to the axles and are brought to a common point, where either a rigid or a bumper jack is welded on.

A piece of angle iron is welded to the jack and fashioned so it will fit into the end of the axle tube. Thus the carrier can be wheeled to the truck, the projecting arm adjusted to the height of the axle tube and the wheel slid onto the arm. No handling is necessary, and the carrier can be used to wheel the assembly anywhere about the shop.

3. Hydraulic Press


by F. W. Green Machine and Repair Shop Oshkosh, Wis.

A home-made hydraulic press can be made from an old truck frame or the ends of a frace that has been left over when shortening wheelbase. A regular hydraulic jack is mounted on a cross piece as shown. This cross piece, as well as the one above, is fastened to the frame with removable bolts so that it can be readily adjusted to the work. Dimensions will vary with the work requirements.

4. Tire Chain Tip

by Robert S. Orr Manufacturers' Light and Power Co. Brownsville, Pa.

To prevent tire chains from tearing emergency brake cables off Chevrolet 1½ ton trucks, I make a spacer and





SHOP HINTS FROM FLEET SHOPS

insert it between the backing plate and brake cable flange.

These spacers may be made of hard wood or iron. I have put as much as a 11/4 in. spacer in and have averted this common trouble.


5. Fifth Wheel Ground by Frank E. Seftchick Swift & Co., Brooklyn, N. Y.

A long battery ground strap makes an excellent ground between the fifth wheel and tractor. It can be attached anywhere out of the way but must be long enough to allow for movement of the fifth wheel.

6. Head Lifting Fixture

by W. M. Kendrick Acme Laundry Co., Chatham, Mass.

When removing or replacing Chevrolet cylinder heads, this fixture makes the job much easier,



OF THE MONTH

U-Bolt Wrench Guide

by Joe H. Ragan East Tenn. Packing Co. Knoxville, Tenn.

Enclosed is a sketch of a handy wrench holder to be used when U-bolts are tightened.

A common coil spring is equipped with wire hooks so it can be suspended from the leaf spring and hooked to the wrench handle, thus leaving the mechanic's hands free for pulling on the wrench. The guide holds the wrench to the nut and saves a lot of time and trouble in this job.

especially on C-O-E model trucks.

Take a piece of 2 x 4, 18 in. long and bore a 3/8-in. hole 25/8-in. from each end. Remove the rocker arm shaft and push the 2 x 4 over the long studs and bolt securely. This makes a handy handle with which you can roll, lift or tilt the head as required without damaging the gasket.

7. Regulator Tool

by R. M. Shelton Safety Convoy Co., Dallas, Tex.

A handy bending tool for setting Ford voltage regulators can be made from a Ford oil gage stick. Saw out a slot with a hacksaw to the required (TURN TO NEXT PAGE, PLEASE)

SHOP HINTS

(Continued from page 45)

dimension to fit the spring tension arm and bend the handle to any convenient shape.

8. Wiper Tip

by Tim Vahle Iowa Ordnance Plant Burlington, Iowa

We have experienced the inconvenience of inoperative windshield wipers when going up hill or with wide-open throttle and have devised a system to eliminate this.

I simply cut a T into any convenient place between the vacuum tank and the check valve and connect the wiper hose to this T. All our trucks with vacuum booster brakes or hydrovacs have been changed in this manner; it takes less than ½ hour and will insure proper wiper action at all times.

9. Spare Tire Rack

by Jean Babin, Shop Supt. Columbian Laundry, Newark, N. J.

We find that the tire rack on our 1½-ton trucks is in an unsatisfactory location because the bolts become rusted, drivers fail to keep the spare inflated and they get dirty when changing a tire.


As a result we have made a tire rack and located it inside the panel body.

A 2-in. strap iron plate 24 in. long is drilled to take three lag screws or metal screws to secure it to the body. One half in. bolts 10 in. long are welded or bolted through this plate and fitted with wing nuts. These are spaced so that they meet the holes in the wheel. The tire is rested on the floor and tightened in place. Now the spare is always clean and ready for instant use. If space does not permit this location, it can be just as well raised to any height desired.

10. Battery Charger

by T. J. Hourihan Moulten & Holmes, Boston, Mass.

Here is a shop hint I have found very useful. We have a small battery



charger which we use to charge the batteries without removing them from the vehicles. It is a slow charger, and we have rigged up a timer so we can shut up shop at night and leave it on. The automatic shutoff will stop the charger at the time designated.

I purchased a conventional time switch at a cost of \$6.80. I wired this with a receptacle and plug so that the clock can be set to shut off the charging. Now the shop can be closed while the battery is being charged.

11. Air Brake Tip

by Luther Noe Hageman Transport Co. Laurel, Mont.

Having had considerable trouble with our air compressors pumping oil

and depositing it in reservoirs, we have developed a scheme for eliminating this condition.

Ro

the

du

sha

car

ex

hu

sp

m al he

th

We knew the condition resulted from dirty air filters, so we started from there. We remove one of the air intake caps and drill a hole suitable for either 5%-in. tubing or 3%-in. pipe which is welded to the cap.

We remove the top section of the intake manifold on the diesels and drill and tap the \(^3\)\(_8\)-in. pipe, placing a 4-in. nipple in it, and then connect the two with a heater hose. This allows the compressor to secure an abundance of air clean from the intake manifold on the diesels and from the intake pipe on the gasoline jobs. This has proved highly successful and completely eliminates the cleaning of our air compressor air cleaners.



The OVERLOAD

For the Record: New Records . . . GVW Rating Progress . . . Kingpin-Offset Benefits

by GEORGE T. HOOK Editor

THE phenomenal total of 1,219,446 motor trucks were manufactured in the United States in 1947. This is a new record. The previous high was in 1941 when 1,094,000 trucks were produced.

U. S. truck operators bought up their share of this production as fast as it became available, but there is nothing phenomenal in this fact. It was to be expected. Truck users are hungry for more of the same. In fact they are hungry for some models that are conspicuously in short supply, viz and to wit: sedan and panel deliveries. But since such models use up as much or more steel than goes into a more profitable passenger car, it will be some time before the big mass producers find it good business to divert sheet steel to the light commercial models.

When the new truck registration figures for 1947 are in they will show that about 890,000 trucks were bought and registered. This, too, is a new record. It compares with the previous high of 640,697 in 1941.

Although there continues to be a shortage of some parts for some truck models that are 10 or more years old, the overall replacement parts situation is much improved. The reason for this is another record-breaking output of parts. The 1947 dollar volume of parts will be at least \$2½ billions, as compared with \$1¾ billions in 1946, the previous peak year, and approximately \$¾ billion in 1941.

And what of the year 1948? Truck manufacturers are ready to produce another 1½ million trucks. Truck users are ready to buy as many and more than in 1947. But not until Congress determines upon the extent of U. S. aid to Europe can the situation with regard to materials be gaged.

At the moment it looks as if truck production would be as great in 1948 as in 1947. Also that domestically the various sizes of trucks will be available to the same extent as this year.

AUTOMOTIVE progress is made in stages. Bill Stout once contended that this could not be true of engine position, that the engine can't be moved gradually from the front of a car to the rear. Literally true. But so far as public consciousness is concerned it can be done in stages. It is being done with the currently popular styling. The "new look" is so much alike front and rear, that eventually the engine can be switched from fore to aft without the public's being aware—appearance-wise—of a revolutionary change.

Another example of progress in stages is the truck industry's conversion from tonnage to gross vehicle weight ratings. It is almost 20 years since this publication denounced the practice of tonnage-rating trucks by pulling numbers out of hats, and advocated gross vehicle weight as the only sound rating method. Tonnages were removed thereafter from the CCJ Truck Specifications Table and GVW substituted. Manufacturers went along. So have many states. Some operators have resisted it in states for fear of upsetting registration fee setups.

In 1941 the American Association of Motor Vehicle Administrators recommended the universal adoption of gross vehicle weight for registering and licensing purposes. And as of Jan. 1 most truck manufacturers have been attaching identification plates to new trucks containing the GVW and net HP ratings. The next stage is for 23 states (10 of which use net weight and 13 of which use tare weight) to join the 26 that use gross vehicle weight rating.

. . .

CONSIDERING all the advantages that accrue when the kingpin on a tractor-semitrailer is set a proper distance ahead of the tractor rear axle, it is amazing why the practice is not insisted upon by truck operators.

* * *

The attitude of drivers is, of course, one reason for operator inertia. Drivers don't like rigs that steer hard and that is their complaint when the kingpin is offset. There have been some operators who have been compelled to change kingpins from the offset position because of driver reaction. And back of the driver there is always the union. It becomes expedient to "compromise" when there is danger of disturbing labor relations.

But the foremost reason for operator inertia is, to put it baldly, ignorance. Top management has not been aware of the advantages of kingpin offset, and even many fleet engineers, on whom top management depends for sound transportation engineering advice, have not kept themselves properly informed.

Articles on the subject have been published before, and a new one—thorough in its approach to the subject—is published in this issue. It discusses the effect of kingpin offset on load distribution, traction, braking, steering, turning radius, maneuvering and riding. The advantages are all with kingpin offset.

The article should be read and absorbed by every fleet owner and every executive who has anything to do with the selection and purchase of vehicles. It should be used as a document to convert drivers and their representatives to a realization that the ease with which a vehicle is steered cannot take precedence over factors that have a direct bearing on safe and economical operation.



TOLL ROADS

Fleets Should Oppose Them

Because: 1. They offer only a temporary, not a permanent solution to highway congestion.

2. They require double taxation—the highway user already pays for adequate roads through vehicle taxes.

3. They intensify problems on paralleling roads because the free roads, which must continue to bear the bulk of the traffic, cannot be improved too much without impairing the toll road's financial success.

4. Only in rare instances can a toll road expect to pay off its indebtedness. If it fails, the state has to assume a bonded indebtedness bearing high interest rate, and highway users will have to pay the bill.

5. Toll roads may prevent completion of the great free interstate highways program of the Federal and state governments.



by ARTHUR C. BUTLER

Director National Highway Users Conference

AT ABOUT the time you read this, legislatures of eight states will be beginning regular sessions. Highway legislation always makes up a heavy percentage of their lawmaking tasks. In dealing with highway problems, some of these legislators will see potent magic in the words "toll roads."

That was the experience last year, anyway, when lawmakers of seven states enacted toll road legislation. In at least some of these cases, tolls were regarded as the easy answer to admittedly tough highway and highway finance problems.

The surface attraction of toll-road

proposals, therefore, needs to be combatted again this year by highway users, or we will again be buying, piecemeal, a very runty pig in a very expansive—and expensive—poke.

States which have particular stretches of road calling for drastic improvement always find this mysterious pig-in-poke bargain waved alluringly under their noses very early in proceedings. If there is an unpleasant odor emanating from the bag, there is also the seductive perfume known as "Something for Nothing," with which the sack has been liberally anointed.

This perfume may in some cases be applied by investment firms, eager to handle toll-road bond issues.

Under the heady influence of this perfume, legislators and even governors sometimes come to believe that \$100 million highways can be built absolutely for nothing, and that the \$100 million can then be spent for something else.

This being the case, let us peek into the toll-road poke and examine the less fragrant contents.

Only Temporary Solution

en oi th Pr ne 15

fa

Je

C

C

11

IN the first place, the toll road offers only a temporary, not a permanent, solution to highway congestion. While the toll road can expedite the movements of some traffic, it can never attract the bulk of vehicles—most vehicles are debarred from use because most of their trips are "local," not of turnpike length. This being the case, turnpikes cannot eliminate the necessity for good free parallel highways.

But when toll roads are built, immediate prospects for states improving these paralleling free highways sink swiftly. States with toll roads would naturally be loath to improve free roads to standards which would hurt their turnpike's revenues. So instead of helping to ease congestion on free roads, turnpikes may help to perpetuate it.

Not Something for Nothing

IN the second place, the toll roads are not giving something for nothing. The people who use them are victims of double taxation—while paying tolls they are also paying all the regular highway-user taxes. This is an especially important consideration to those whose highway costs

(TURN TO PAGE 107, PLEASE)

Fleets Rely on Own Experience for OIL CHANGE PERIODS

Schedules best suited to operating conditions are employed by 33.96%; next most frequently mentioned factor is mileage tie-in with maintenance

Analysis by A. W. GREENE, Managing Editor, Commercial Car Journal

THE NATION'S TOP FLEETS rely upon their own experience, more than any other factor, when it comes to deciding on oil change periods for their vehicles. Of the 10 factors listed by the Board of Experts, 33.96 per cent work on an experience basis. Predetermined mileage schedules and oil discoloration are the next two most frequently mentioned factors. As shown in Table 1, 15.09 per cent work on a mileage basis, and 14.15 per cent change when the oil gets "dark."

Fleetmen who study this table carefully may wonder why 10 headings were set up when, actually, there are but four major factors indicated. Therefore, it is necessary to point out that the studies comprising the Fleet Operators' Experience Handbook are based on actual statements made by members of COMMERCIAL CAR JOURNAL'S Board of Experts. All information obtained is tabulated, as exactly as possible, as stated in the surveys. Of course,

inasmuch as space limitations make it impossible to quote each member of the Board verbatim, a certain amount of interpretation is necessary. This, however, is reduced to the minimum.

Thus, while the term "experience" implies experimentation with mileage intervals, time intervals (such as weeks or months), outside advice or personal findings from periodic inspections—or any combination of these factors—the heading Experience was set up because the term was either actually used or implied in the individual reports. "Our experience shows this oil change period is best suited to our operation," is a typical quotation of fleetmen tabulated in this group.

A typical comment of the fleetmen whose comments are tabulated in the Mileage column is, "We decided on this mileage because it fits our maintenance schedules, which are based on mileage."

(TURN TO NEXT PACE, PLEASE)

Leading Factors Responsible for Engine Oil Change Schedules 33% work on experience schedules, 15% use mileage as a guide, 14% watch color

Table 1 VOCATIONAL GROUPS	Number of Fleets Report-	Experi- ence	Mileage	Color	Advice of Oil Testing Labora- tory	Truck Manu- facturer Recom- mendation	Inspec-	Type of Work Being Done	Time Basis (hrs, days, wks, mos)	Process of Elimi- nation	Contami- nation	Not Reporting Reasons
	ing	Per Cent	Per Cent	Per Cent	Per Cent	Per Cent	Per Cent	Per Cent	Per Cent	Per Cent	Per Cent	Per Cent
COMMON CARRIER GROUP Local and Over-the-Road	40	55.00		12.50	20.00	2.50	5.00	*****		2.50		2.50
Food Products	36	22.22	22.22	22.22	13.89	2.78	5.56	2.78	2.78		2.78	2.78
GOVERNMENT GROUP State, County, Municipal, Federal CONSTRUCTION GROUP	59	40.68	22.03	8.47	1.69	6.78	1.69	3.39	1.69		3.39	11.86
Builders, Quarries, Gravel	5		20.00	20.00	20.00	40.00						20.00
Local and Over-the-Road PETROLEUM GROUP	2	50.00		50.00		50.00		******		*****		
Producers and Distributors	9	55.56	33.33				*****	*****	*****	*****	*****	11.11
PUBLIC UTILITY GROUP Gas, Power, Water and Telephone RETAIL DELIVERY GROUP (Other than Food) Dry Cleaning,	32	21.88	15.63	15.63	9.38	6.25	15.63	9.38		6.25	3.13	3.13
Laundry, Newspaper, Coal and Ice, Department Stores, Beverage TRUCK RENTAL GROUP	15 5	20.00	20.00	20.00	13.33	40.00	13.33		20.00	6.67		28.67
TRUCK AND BUS FLEETS, MIXED.	9	11.11	11.11	11.11	44.45		11.11		*****	11.11		
TOTALS AND AVERAGE	212	33.96	15.09	14.15	11.32	6.13	6.13	2.83	2.36	2.36	1.89	7.55

t

don

Il

Average Engine Oil Change Frequency is Approximately 2000 Miles Light trucks average 2000 miles between changes, medium 1900, and heavies 2200

Table 2			LIGHT T	RUCKS		N	MEDIUM	TRUCK	S		HEAVY T	rucks		P	ASSENGI	ER CAR	S
		MI	LES			MI	LES			MI	LES			MI	LES		
VOCATIONAL GROUPS	Number of Fleets Report- ing	Range in Thou- sands of Miles	Average in Thou- sands of Miles	Weeks	Months	Range in Thou- sands of Miles	Average in Thou- sands of Miles	Weeks	Months	Range in Thou- sands of Miles	Average in Thou- sands of Miles	Weeks	Months	Range in Thou- sands of Miles	Average in Thousands of Miles	Weeks	Month
COMMON CARRIER Local and Over-the-Road FOOD DISTRIBUTION	40	1-6	1.9	2	1	1-6	2,2	1.5	1	1-7	2.5	1.5		1-6	2.1	2	1
Bakeries, Dairies, Meats and Other Food Products GOVERNMENT	36	1-3	1.6	2	3.6	.8-3	1.5	2	2.8	1-6	1.9	1.5	4.1	1-6	2.0	2	4.2
State, County, Municipal, Federal	59	.5-6	1.5	1.6	1.5	- 5-6	1.4	1	1.5	.5-6	1.3	1	1.5	.7-6	1.5	1	1.5
Builders, Quarries, Gravel	5	1-5	2.0			1-2	1.6	1		1-2.5	1.8	1		1-2	1.2	*****	
Local and Over-the-Road	2	2-5	3.5			2-5	3.5			2-5	3.5	******		2-3	2.5		
Producers and Distributors PUBLIC UTILITY	9	1-2	1.2			1-5	1.0	1		.8-3	1.2	1		1-2	1.3		. 1
Gas, Power, Water and Telephone RETAIL DELIVERY (Other than Food) Dry Cleaning, Laundry, Newspaper,	32	.5-10	2.8	6	3.7	.5-10	2.8	6	3.8	.5-10	2.7	6	2.7	.5–10	3.0		3.3
Coal and Ice, Department Stores, Beverage	15 5	1-4 1-2	2.0 1.4	1	2.1	1-3 1-2	1.4 1.2	1		1-4 1-2	2.5 1.3	3.5	3	1-5 1-1.2	2.4 1.2	1	2
MIXED	9	2-2.5	2.1			2-2.5	2.1			2-6	3.1			1-2.5	1.9		
TOTAL AND AVERAGE	212	.5-10	2.0	2.5	2.4	.5-10	1.9	1.9	2.3	.5-10	2.2	2.2	2.8	.5-10	1.9	1.5	2.1

"When the oil gets dark, we change it," is approximately the wording of the comments grouped in the Color column.

The next two columns are quite clear. The column headed Inspection, however, seems to require explanation. While the inference seems to be the same as that in the Color column, a separate listing was made because so many fleetmen used that term. The same is true of the comments in the Contamination column; although here some of the remarks imply the use of methods to detect dilution by gasoline, presence of water, sludge and acidity.

In the Type of Work column, the comments imply flexible schedules, "It all depends on the type of work that the truck is

Disposition of Drained Oil

Majority, 70%, discard crankease drainings 21% sell and balance reclaim used engine oil

Table 3 VOCATIONAL GROUPS	Number of Fieets Report- ing	Throw Away Per Cent	Sell Per Cent	Reclaim Per Cent
COMMON CARRIER GROUP Local and Over-the-Road	42	59.52	35.72	4.78
Food Products	43	65.12	25.58	9.30
State, County, Municipal, Federal	53	86.79	7.55	5.66
Builders, Quarries, Cravel	5	80.00	20.00	*****
Local and Over-the-RoadPETROLEUM GROUP	1	100.00	****	** **
Producers and DistributorsPUBLIC UTILITY GROUP	8	62.50	25.00	12.50
Gas, Power, Water and Telephone RETAIL DELIVERY GROUP (Other than Food) Dry Cleaning, Laundry, Newspaper, Coal and	30	70.00	13.33	16.67
Ice, Department Stores, Beverage	16	68.75	25.00	6.25
TRUCK RENTAL GROUP	5 7	60.00 57.14	40.00 28.57	14.29
TOTAL AND AVERAGE	210	70.48	21.43	8.09

doing," says one fleet operator. "In local service we work on a mileage schedule, and, in over-the-road service, the same truck would be placed on a weekly schedule."

Time basis mainly refers to weekly and monthly periods. Hours, however, also were mentioned by quite a few, especially those having vehicles on off-the-road work.

Process of Elimination comments probably could be grouped under the Experience column but, inasmuch as an appreciable number of fleetmen used that term, it was considered more accurate reporting to set up a column with this heading.

Due to the fact that some fleetmen mentioned more than one basis for the adoption of their oil change periods, the per cent totals for some of the vocational groups add up to more than 100 per cent.

Oil Change Frequency Schedules

A TABULATION of the oil change frequency schedules reported by the Board of Experts will be found in Table 2. The national average for fleets that work on a mileage basis is 2000 for light trucks, 1900 miles for medium trucks, 2200 miles for heavy trucks and 1900 miles for passenger cars. Because the variation in the mileage schedules is rather large in quite a few cases, an extra column was added in the table to show the extremes. Some public utility fleets, for example, change as frequently as every 500 miles, while others work on 10,000-mile schedules. The extremes in weekly and monthly schedules were too inconsequential to tabulate.

Comparison of Table 2 with Table 1 may seem to show discrepancies that require explanation. The Time Basis column in Table 1, for example, does not show any Common Carrier fleets using that basis. Yet, in Table 2, time intervals are reported. Actually, the fleets in the Common Carrier Group reporting the use of time schedules are distributed under such headings as Experience, Advice of Oil Testing Laboratory, Inspection, and Process of Elimination.

What fleets are doing with their used crankcase oil is shown in Table 3. The trend, based on pre-war practice, is in the direction of reclaiming or selling. Current petroleum products delivery shortages may further cut down the Throw Away percentage.

st T

le ti th



CORRECT Application of Motor Trucks

Eight vital steps in the selection of the right vehicle for specific service requirements and economical operation

STEP 8
(CONCLUSION)

How to Select

Other Equipment

Choosing the Correct Chassis Springs . . . Method of Calculating the Actual Spring Loads . . . Choosing the Correct Service Brakes . . . How to Determine the Size or Capacity of a Generator and a Battery . . . Method of Figuring Total Continuous Electrical Load

(Copyright 1947, The White Motor Co., Cleveland, Ohio)

CORRECT APPLICATION at its best includes nearly every unit of a truck. Not just the major units discussed in the other steps, but small units as well—the generator, brakes, springs, etc. There are a number of such small units which are available in more than one type to meet the needs of various operating problems. The correct selection of these units is part of the application solution since such equipment affects safety and control of the truck, as well as efficiency of operation. These small details then are important. They are the finesse in correct application that rounds out the selection of a truck. The total choice is a truck applied, in every possible unit, to the requirements of the trucking operation.

Choosing the Right Chassis Springs

ON EACH truck model, the chassis standard springs are designed with a capacity for a definite load, and a certain amount of deflection from light to the fully loaded position. The capacity of these standard springs was designed on the basis of the average weight distribution and a normal maximum load for the truck model. Most truck manufacturers' specifications will list the capacities for these standard springs, and optional springs which are available.

A part of correct application should include a check on: (1) The actual spring loads of the truck, against (2) the capacities in the specifications, to determine the springs best suited to the job.

This check is made by finding the spring load, like this: Sub-

L

tract the weight of axles with wheels, tires, and springs from the front and rear gross vehicle weights, which have already been determined in the analysis of the truck weight distribution (Step 3, Page 15). The result is the total weight on the springs.

For example, a truck with a gross weight of 24,000 lb. and a distribution of 27 per cent of the weight on the front axle would figure out as follows:

CALCULATING THE ACTUAL SPRING LOADS

Total gross vehicle weight	Front 6,500 lb. 950 lb.	Rear 17,500 lb. 3,200 lb.
Total weight on springs	5,550 lb. 2,775 lb.	14,300 lb. 7,150 lb.

The figures on the total weight on each spring, front and rear, should be compared with the weights listed in the truck manufacturer's specifications. Of the available standard or optional springs, the ones closest in capacity to these figures should be used.

Also among the spring data in the manufacturer's specifications is information on the rate—rate of deflection in pounds per inch. This rate figure is sometimes necessary to truck application since it affects not only the riding qualities of the truck, but also the height of the chassis frame and the amount of the difference in chassis height between light and fully loaded positions. The

higher the rate, the stiffer the springs. So that springs with a high rate show a smaller difference in chassis height between lightly loaded and fully loaded frames.

This rate also affects the position of the truck body and chassis on the wheels. Sometimes the type of body mounting, or the operation of equipment on the vehicle, requires the chassis frame to be level under certain loaded conditions. Some attention will have to be paid to the spring's rate of deflection in order to achieve this.

Application of tractors used to pull semi-trailers brings up several problems regarding springs. On some tractors the fifth wheel must be an exact height from the ground. And the springs must have a definitely limited amount of deflection. This is necessary so the tractor will be able to correctly pick up and drop the semi-trailer with various types of standard or automatic fifth wheels and jacks. At times, it is necessary to make special modifications of the tractor springs. The engineering branch of the truck manufacturer should be consulted regarding such special spring problems.

Rate of deflection is also of importance in special cases where it is necessary to control the body sway when turning corners and at other times. Springs selected in such applications should be stiffer or, in other words, have a higher rate of deflection than the standard springs.

Choosing the Right Service Brakes

TWO general types of brakes are available on most trucks—air-power-operated brakes and vacuum-power-operated brakes. The air power for operating the brakes is derived from an air compressor driven by the truck engine. The vacuum power for operating the brakes is taken either from the intake system or from a vacuum pump driven by the truck engine. Before the fleet owner completes the application of a truck, he should decide which type of brakes he prefers, and also which optional equipment is necessary to augment that type.

Air brake installations on normal tractor-trailer and straight trucks are complete and satisfactory. The standard air compressor furnishes the amount of air required.

In the case of larger units, such as large truck-train combinations, the standard compressor might be inadequate. There are sometimes as high as 12 or more air diaphragms to be supplied each time the brakes are applied—which is double the number on most truck units. An optional compressor of higher displacement, supplying a greater volume of compressed air, should be required—especially when the route includes hilly country and heavy traffic.

Vacuum-power-operated brake installations on normal tractor-trailers and straight trucks are also complete and satisfactory. The standard installation has the vacuum cylinder connected to the intake manifold which furnishes a high degree of vacuum and permits safe brake operation. Auxiliary vacuum reservoir tanks should always be used. Larger units such as truck-trains and others, may need additional vacuum to operate the brakes. Instead of depending on the intake manifold, vacuum pumps driven by the engine can be used to furnish the additional power.

Which type of brakes should the fleet operator choose when the truck model has both available? Both systems are designed to perform an efficient braking job and conform to standard braking requirements. The choice may be based mainly on interchangeability. Usually the brake system on which the fleet is standardized is the logical preference because of simplified parts problems and maintenance problems. However, in the case of multiple-axle truck-trains operating over long grades, the airoperated brakes are normally recommended instead of the vacuum-operated brakes. With air brakes the truck has a greater safety margin in brake operation under such circumstances.

Selecting the Electrical Equipment

MOST trucks have many items of electrical equipment which are available in several types and sizes for each model. There are several sizes of generators and batteries available. Or special low-cut-in generators. Or a 12-volt electrical system, instead of the more popular 6-volt system. Or other pieces of electrical equipment which vary with the truck model and the truck manufacturer.

The choice most buyers will face in the application of a truck is in the size of generator and battery. This size can be ascertained by first finding the total electrical load for the truck in this manner: The amperes of current required for each of the electrical devices which may be in continuous operation at one time are totaled. The ampere output of the generator should be approximately 10 per cent greater than this total continuous electrical load. For example, a large tractor-semi-trailer which operates at night would have the following electrical load:

DETERMINING THE TOTAL CONTINUOUS ELECTRICAL LOAD

UNIT: Tractor-Semi-Trailer	Amperes Each	Ampees: Total
Headlights (2)	7.50	15.00
Taillights (2)	.56	1.12
Dashboard lights (7)	.25	1.75
Ignition coil (1)		2.00
Heater and ventilator blower (1)		12.00
Cab market lights (5)	.56	2.80
Trailer marker and side lights (8)	.56	4.48
TOTAL MINIMUM CONTINUOUS LOAD		39.15
In the case of a tractor using fog lights in wet weather the above amount would be increased as follows:	,	
Fog lights (2)	3.7	7.4
TOTAL CONTINUOUS LOAD		46.55

Calculating the generator output from the electrical load just found, can be done in this manner:

GENERATOR AMPERE OUTPUT = total continuous load + 10% of total load GENERATOR AMPERE OUTPUT = 48.85 + 4.68 = 51.31


GENERATOR OUTPUT should be about 50 amperes, which will be correct size for this tractor-semi-trailer.

Fog lights, added in the example above, are not used on all tractors. But many tractors have other additional items of electrical equipment such as electrical windshield wipers, radios, or higher candlepower bulbs in the marker lights. This additional equipment should be included in the calculations of the total continuous load necessary for choosing the generator.

A special generator is needed in operations where truck speeds are low and the delivery or loading stops are long. The engine then operates a large part of the time below the speed at which the standard generator starts to charge the battery—about 600 rpm to 700 rpm of the engine. In order to keep the battery charged under these conditions, a generator of the low-cut-in type, which will start to charge at about 400 rpm, should be installed.

Along with the generator in each truck is matched a normally correct-size battery. Optional storage batteries of larger capacity are available. If the trucking operation is in a cold climate where the starting load is very heavy, the larger battery may be necessary.

Electrical systems of 12-volt potential are standard on very heavy-duty model trucks, and optional equipment on other models where the 6-volt is standard. The standard system—whether 6-volt—is usually satisfactory for most normal operations. Other operations where the starting loads are heavy, or there is additional electrical equipment, may exceed the capacity of the 6-volt system and require a 12-volt system. The 12-volt system should also be considered from the viewpoint of interchangeability. A fleet made up mainly of trucks with 12-volt system should standardize their new trucks to this same electrical system in order to simplify parts and maintenance problems.



Typical bearing failures arising from:

1. Insufficient oil clearance
2. Acids in lubricant
3. Failure of oil supply
4. Foreign particles
5. Normal fatigue
6. Abrasives from overhaul
7. Lack of oil

Trouble Shooting

Engine Bearing Failures

A study of common bearing troubles, featuring practical pointers on diagnosing premature failures in a move to prevent recurrence

WHEN engine bearings fail in service, it is the mechanic's responsibility to determine the cause. Troubles supposedly corrected without properly diagnosing the reason will reappear altogether too soon. The life of a replacement depends upon an intelligent diagnosis of the failure. In general, types of failures can be determined from the condition of the bearing, the appearance or the wear.

Dirt is probably one of the greatest enemies of engine bearings, causing as much as 90 per cent of some fleet's bearing troubles. It is often by M. K. SIMKINS

Technical Editor Commercial Car Journal

difficult to tell, however, when an engine is torn down, whether the dirt has entered during overhaul, from carbon deposits, addition of contaminated lubricants or from foreign material brought in through crankcase ventilation. Fortunately, all these avenues can be controlled by careful maintenance and operation,

so that there should never be a second failure from the same cause. Better serviced air filters, more frequent changes of oil filters and more attention to the cleanliness of oil filling equipment, together with proper overhaul methods should eliminate this condition.

Bearings failed as a result of dirt may have a scurvy appearance with foreign particles imbedded in lining, indicating that the engine had not been cleaned after a rebore job or after cylinder reconditioning. Bear-

(TURN TO NEXT PAGE, PLEASE)

ls

o y e, d. ly

ls 6s. is ne my.

Bearing Failures

(Continued from page 53)


ings assembled over a dirty crankshaft or bearings installed without being properly cleaned may show up as pock-marked, with foreign particles imbedded in spots.

Large metal particles will leave definite ridges or paths similar to the track of a snail. There will be definite channels cut into the surface, starting from the oil hole and running in line with the oil flow, eventually leading to the bearing edge. Large scratches of this nature will soon cause complete failure because each crevice permits an oil bleed which will drain off the lubrication from the bearing and reduce its load carrying capacity. If the channels start at no particular source, it may indicate that the dirt or abrasive material was present when the bearing was assembled. If the source of the channels is at the oil hole, dirty lubrication is generally indicated.

Abrasives left in the engine during overhaul may show up in a loading up of the bearing surface with dirt. Oftentimes these particles displace the babbitt, raising it around the particles and reducing the oil clearance. The result is a development of excessive heat which melts the babbitt so that it may look as if overheating were the trouble. This often causes fatigue in localized areas.

Not all dirt may be evidenced on the bearing surface. It can do as much damage if particles lodge behind the shell. This lifts the insert from the seats and impairs the proper dissipation of heat to the block or rod. Melted babbitt may result. Again, such a condition will cause a high spot which will carry the load until it is broken down. The babbitt will eventually be rubbed off at these

Excessive crankshaft thrust



spots, the clearance will probably increase and failure will be sure. Dirt held under the insert reduces the bearing contact, increasing the unit pressure and causes flexing of the bearing. The result is lateral cracks in the babbitt comparable to those arising from fatigue failures.


Partial Load Distribution

A FREQUENT cause of premature failures is partial load distribution, a condition arising from any number of factors all centered around bearing-to-shaft contact. Insert bearings must have perfect contact between the insert and saddle or the con-rod to provide proper heat dissipation and to maintain the cylindrical form of the bearing. Localized pressure at any spot will cause overheating and melting of the babbitt.

A bent con-rod will cause failure for this reason as will a misaligned bearing cap, out-of-round saddle bore, crankcase distortion, out-ofround connecting rods, misaligned crankshaft or cylinders bored out of line. Chiseling of the bearing on the back to reduce bearing clearance, a common shop malpractice, will result in early failure because full shaft contact will not be possible. Out-ofround bearing saddles permit the bearing to take the same form, resulting in partial bearing-to-shaft contact. Even large size con-rods sometimes distort under heavy loads and high speeds.

A distorted crankshaft held in alignment by force imposes heavy loads on main bearings and usually shows up in failure of the center bearings while the end ones remain

Out of round con-rod bore



in apparently good condition. A warped or bowed crankcase will show up in the same type of failure. If the block is found to be misaligned, the best possible remedy is to use semifinished bearings and align bore them to true dimension.

o in b


One of the primary causes of misalignment of either the crankcase or the con-rods is improper bearing cap tightening. Far too many mechanics still rely on "feel" with the result that the adjustment is apt to be too tight or too loose. For satisfactory results the cap must be tightened with a torque indicating wrench with just the right tension to hold the bearing tight enough for the two bearing saddle halves to act as one solid piece. If the nut is pulled too tight, the saddle may be stretched out of round or the threads may be stripped enough to give way under high stress. If the adjustment is too loose, the insert may slip in the saddle, resulting in overheating and early failure.

Con-rods can be misaligned in several ways which will speed failure due to impartial load distribution. The rod may be twisted, putting extra strain on the lower end bearing as well as the edge of the insert. The small end will ride against the piston boss, tilting the crankpin end. The seat may become elongated after long periods of service, a condition which reduces the oil clearance near the parting faces of the rod and cap. A heat zone is created in these areas. and failure follows. Out-of-round crankpins are another reason for impartial load distribution.

Incorrect Fitting

A LOOSE bearing can be identified by shiny or smugged areas on the back of the insert, the parting faces and the locking lug. Loose inserts permit the oil to lodge between

Bearing loose in seat



the shell and the back, hindering proper transfer of heat. Mottled steel on the backs of the bearing will point to a loose insert, caused by lack of bearing crush, oversize bore or deflection of the rod bore. When found on a connecting rod, it may be an indication of overspeeding. A loose bearing will flex and frictional heat will develop, causing scoring and failure. Bearing crush built into the insert dimension by the manufacturer is designed to eliminate this condition by holding the insert clamped solidly in the seat when the bolts are tightened. Insufficient crush will not allow for an adequate film of oil between the shaft and bearing. The babbitt will eventually score from overheating. This condition is usually the result of filing of the parting faces of the shells.

On the other hand, excessive oil clearance, especially of the main bearings, will not permit adequate lubrication of the connecting rods. This condition also allows extra metal to be forced into bulges near the parting faces, creating areas of excessive pressure and resulting in early breakdown of the babbitt.

- Insufficient oil clearance will allow metal-to-metal contact and result in a wiping action on the part of the shaft. Babbitt will be wiped out of the insert in definite grooves, while scoring will be evident. This condition will closely resemble that caused by inadequate lubrication, although scuffing and scarring will appear to be rough and pitted, with scoring quite pronounced.

It is appalling to find that so many bearing failures are purely the result of malfitting practices in the fleet shop. These conditions, however, should and can be controlled quite easily with more attention given to mechanic training. Experience has shown that it is expensive to try to fit bearings by the trial and error methods. Many sets of new inserts have been ruined because the mechanic guessed at rather than measured the bore of the bearing seat and the diameter of the shaft. Many times nicks, burrs and dirt make for improper readings on instruments.

Many fitting failures can be eliminated by simply comparing the new bearing with the old one, with respect to the grooves, position of oil holes, flanges, etc. Inspection may avert a

breakdown.

TROUBLE SHOOTER'S CHECK LIST

Causes of failure

Dirt from-

Careless service methods Contaminated oil Infrequent oil changes Dirty oil filters **Dusty** operation

Improper fitting through -

Distorted con-rods Out-of-round journals Tapered journals Scored bearing surface Warped crankshaft or block Improper clearance Use of inaccurate tools Improper tensions of studs Mixing con-rod caps Installing shells backwards Filing shell to fit Chiseling shell to reduce clearance Excessive crankshaft end play Dirt between brg. and rod bore Mutilated bearing surface

Corrosion from

Crankcase acid vapors Overcooling Overheating Inferior type of oil Incomplete combustion Poor crankcase ventilation Engine blow-by Infrequent oil changes

Improper vehicle operation

Overspeeding Overloading the vehicle Lugging on hills Spark detonation Improper engine break-in Racing a cold engine Use of wrong type, grade oil Improper fuel Insufficient oil Improper timing

Improper Assembly

IMPROPER assembly, another practice directly the responsibility of the mechanic, is frequently the cause of early failures of bearings. Sometimes the bearing caps are thrown out of alignment when they are tightened with an oversize wrench. If the shoulder of the wrench presses against the bearing cap, it may be thrown sidewise, and result in partial load distribution. Mixing of bearing caps or installation of bearing caps backwards is another frequent cause of bearing comebacks. Rods and bearing caps are machined in married parts and must be kept in pairs if precision fitting is possible.

Surprisingly enough the installation of improper size replacement bearings is a common cause of early failures. Several models of engines

· Lubrication failure

Failure of oil pump Clogged oil pump screen Excessive engine sludge Excessive engine temperature Use of too heavy oil in winter Insufficient engine warm up Insufficient quantity of oil Crankcase dilution Inadequate crankcase ventilation

Result of failure

Color

Black deposits on O.D., loose in rod -corrosion-high temperature Coppery color - corrosion - low temperature Steel discolored (blue) overheating Bright spots on I.D.—localized over-Metal to metal contact on I.D. (bright surface). Breaking through oil film

Condition

Broken babbitt-dirt behind shell Scurvey appearance—foreign particles Pitted marks—dirty oil or assembly Melted babbitt—overheating Metal wiped out-too close fit-Lack of lubrication Scored, ridged—contaminated oil Cracks, broken areas—normal fatigue Uneven wear—misalignment Excessive crush—out-of-round bore Rough surface—excessive clearance Worn upper half both halves of main overspeeding
Worn lower half cap half rod bearing overspeeding
Worn upper half of main—lugging overspeeding Worn lower half of main — lugging Worn upper half of con-rod—lugging

deviate from standard dimensions of cylinder bore, main and rod bearings, and these differences must be watched carefully so that proper size inserts are used.

Improper cleaning procedures after a bearing or overhaul job account for a great proportion of failures. The block should be cleaned after valve grinding or cylinder boring. All oil passages should be flushed clean with kerosene or flushing oil. Bearings should be kept in their cartons until they are used. Even the dust and dirt from a normal shop, accumulating on oily parts is sufficient to contribute to early wear. A particle of dirt one half the size of the diameter of a hair placed on a bearing may contribute to failure. Mechanics frequently forget to keep hands clean when assem-

(TURN TO NEXT PAGE, PLEASE)

Bearing Failures

(Continued from page 55)

bling bearings. Manufacturers insist that even metal particles lodged in the pores of the skin are detrimental to bearing life. It is imperative, then, that hands be washed in solvent, not wiped on an oily rag, that work benches be clean, that parts be washed and the shop area free from excessive dust if the longest possible life is to be expected from the bearing job.

Lubrication Failures

I UBRICATION failures might be divided into the following categories, any of which will contribute to early bearing trouble: failure of the oil pressure, insufficient quantity of oil, improper grade and type of oil, contaminated lubricant. Oil pressure failures may be the result of a clogged oil screen, broken oil lines, defective oil pump drive or a broken pressure relief valve spring. A low oil level may allow the pump to pump a mixture of air and oil, a condition which results in insufficient amounts of oil reaching the bearings. It is important that the level be kept at recommended levels especially with high speeds, when the oil does not have sufficient time to return to the pump, thereby lowering the level still fur-

Again a low oil level does not allow proper cooling of the lubricant at the crankcase before it is recirculated. This condition results in overheated oil, and eventual bearing failures due to overheating.

Oil starvation or insufficient quantity of oil reaching the bearings may be the result of worn bearings. In this case the main bearings are flooded while con-rod bearings receive insufficient lubrication. One of the frequent causes of oil starvation is use of either too heavy or too light oil. Bearings failed from this cause may be scuffed and scarred and will eventually lose their babbitt through overheating.

Some types of failure, especially when one bearing gives out, are hard to explain. Such conditions may be the result of pure fatigue, but probably are due to lubrication failure of that particular part, a result of plugging of the lubrication passages. Sometimes adequate lubrication is interrupted when the bearing insert shifts due to insufficient press fit. The shifting of the bearing cap will result in the same condition. Single bearing failures may be the result of fillet ride, resulting from improperly ground journals, a condition which will seal off the oil flow and result in starvation of the bearing.

A great deal of oil starvation difficulties occur during the warm-up period, when the driver fails to allow the engine to normalize before gunning it. A great percentage of wear takes place during the first few revolutions of the crankshaft. Again, bearings are frequently starved following an overhaul, when clearances are close and the engine is allowed to idle too slowly. The condition occurs in new engines if they are not properly broken in.

Bearing failure from oil starvation is usually rapid due to development of excessive heat. The lead content of tin-based babbitt softens around crystalline structure, producing a cracked appearance. The babbitt softens and islands are formed similar to that in a defective asphalt pavement.

Corrosion

HIGH temperatures are conducive to the formation of acids which are harmful to bearings, especially cadmium alloys and copper alloy types. A black varnish on the babbitt, as long as it is a surface deposit, is not harmful, but if the black deposits have cavities, it is an indication that the bearing surface is breaking down due to corrosion. A shiny, oily, black condition can be easily removed and is not a sign of bearing failure. It is sometimes hard to determine whether the particular discoloration is really evidence of failure, and the mechanic may have to resort to a cleaning up of the bearing before making a decision. Bearings with deposits can be immersed in a solution hot dip cleaning, washed with soap and water and rubbed briskly to remove remaining loosened deposits. After this if pit marks, surface corrosion, porous surface is detected, the bearing should be replaced.

Corrosion may be caused by many factors, all well beyond the scope of this article. The mechanic will know that if evidence of corrosion is found, it is caused by either high temperature operation, overcooling, unsatisfactory type of oil, inadequate crankcase ventilation. Frequently the type of operation will need to be studied, the driving habits, as well as the corrosion conditions before remedial measures can be taken.

Normal Fatigue

FATIGUE failures will show up in surface cracks in the babbitt. This is caused by the normal flexing of the bearing under heavy loads and high temperatures. While accelerated by fatigued con-rods, loose inserts, dirt under the bearing, many such failures are normal after extended service. The final stages of this type of failure will show up in a peeling of the babbitt when oil entering the cracks lifts up the metal. When one bearing is found in this condition, all should be replaced.

While fatigue may show up regardless of operation, the following conditions will accelerate it to a great extent; racing the engine in low gear, using the engine as a brake without shifting to proper gear ratio, blow-by which passes hot gases to enter around the pistons and rings. Use of low octane gasoline combined with heavy loads may result in fatigue failures as a result of the higher heat generated.

Engine detonation imposes heavy loads on main and rod bearings, the failure showing up as cracks and broken spots over the entire area of babbitt.

Operational Factors

L UGGING of the engine at low speed is one of the most common causes of premature bearing failures due to operating factors. Failures of this type will show up in wear of the upper connecting rod bearings, while fatigue failures will be evident in the lower half of the crankshaft bearings.

Excessive speeding, either through normal operation or through use of engine as a brake will show up in definite bearing patterns. High speed is indicated if the bearing wear is evident on the lower half of the rod bearings and on the upper half of the mains. The lining will be cracked or broken away from the back. When this condition is noted, it is wise to replace all bearings as all have been subjected to excessive strains and may fail prematurely later.





The truck dispatcher was a patient in the hospital. Awakening from a major operation, he noticed that the blinds of his room were drawn. "Why are those blinds down, doctor?" he said.

"Well," said the physician, "there's a fire burning across the alley and I didn't want you to wake up and think the operation had been a failure."

CCI

The president of Fleety-Fleet Express was interviewing his eldest employee, the building custodian, prior to retiring him on a pension.

"I be eighty-six years old, sir," boasted the old geezer, "and I don't have an enemy in the world."

"What a beautiful thought," murmured the president.

"Yessir!" continued the ancient one.
"I've outlived 'em all!"

001

The coach at Rah Rah College was being entertained at a dinner given in his honor by the local association of motor carriers,

"What's the secret of your success?" asked one of the truckers. "You haven't lost a football game for years."

"Oh, I just get good boys!" replied the

"Good boys!" cried another operator.
"How do you build 'em up? Nobody ever heard of 'em before you get 'em, then nobody forgets 'em, How and where do you find them?"

"Well, it's this way," was the answer. "When I need new players I take a trip around the country and look over the farms. Whenever I see a boy plowing, I ask him the way to the nearest garage. If he points with his finger, I go by. If he points with his plow, I take him."



A motorist driving along with the top of his car down was wearing a bright checkered suit, a baby blue ascot tie, yellow shirt and a red beret. A motorcycle cop hailed him and told him to pull over to the curb.

The fellow in the red beret stopped his car and asked, "What's wrong, officer? I haven't violated any rules of traffic."

And the cop said, "I know you haven't, I just got a hankerin' to hear you talk."

CCI

THE TWO STOOD ON THE DOORSTEP THEIR LIPS TIGHTLY PRESSED. THE FATHER GAVE THE SIGNAL THE BULLDOG DID THE REST.

C C .

Enroute to answer a service call in the wee hours of morn, the road mechanic stopped at a small all-nite beanery for mud and sinkers.

Although the place looked none too sanitary he gave his order and sat back to relax a moment. Minutes later as he swallowed the last drop of coffee and sat the cup down, he noticed a foreign object in the bottom. Calling the waitress, he indignantly demanded, "What does this mean, there is a cockroach in the bottom of my teacup."

"Listen, tall, dark and greasy," snapped the waitress. "If you want your fortune read, go see a gypsy!"

C C 1

The semi-trailer manufacturer and a group of his business associates were vacationing in Florida, where they fished almost daily. One day they noticed a pretty girl fishing off the pier, and as they watched she caught a very large and beautiful fish—but immediately threw it back into the water.

A few minutes later she caught another—even larger than the first. This she threw back also. After half an hour she caught a very small fish. With a sigh of satisfaction she packed up her equipment and prepared to leave.

At this, the trailer tycoon could contain himself no longer. "What kind of fishin' is that," he demanded, "throwin' back the good fish and keepin' that puny one?"

The young lady smiled at him sweetly. "I have a very small frying pan."

Claim Agent: "I understand your wife is a finished singer."

Maintenance Superintendent: "No-not yet-but the neighbors nearly got her last night"

0 0 1

Joe, our janitor on the freight platform, had a habit of going home three or four times a week about three sheets to the wind, so his wife determined to teach him a lesson. With the aid of a sheet and a floor lamp she made a fair imitation of a ghost. She went in and shook her husband.

"Wash thish?" Joe murmured sottily.
"This is the devil," was the answer.
"Shake, ole horsh," said Joe, "I married

0.01

ver sister.

PLUMBER: "I'VE COME TO FIX THE OLD TUB IN THE KITCHEN."

SON: "MA, HERE'S THE DOCTOR TO SEE THE COOK."

C C J

A male nurse in a mental hospital spotted a patient with his ear pressed to the wall listening intently. The patient held up a warning finger, then beckoned the nurse to come over quietly. "You listen here," he whispered.

The nurse put his ear to the wall and listened a few moments. Then he turned to the patient and said, "I can't hear anything."

"No," said the patient knowingly, "and it's been like that all day."


CCJ

Visitor: "Well, and what are you going to be when you grow up, little boy?"

Little Boy: "Well, after I've been president for a while to please mother, and a lawyer a while to please dad, I'm going to be the best darn taster the ice cream company ever had."

Resume Work





Millions of tiny glass spheres applied to plastic sheets or sprayed on special binder reflect outlines, names or trade marks; promote night safety and goodwill

MICROSCOPIC spheres of glass, coated on a plastic backing or applied to a special fluid binder, are adding new brilliance to America's night-time highways and new safety for fleet operations after dark.

The materials provide bright reflective protection for trucks and buses, are applied with adhesive or a spray gun depending on the type, and withstand weathering and washing without losing their brilliance.

Although used for years on high-

way signs and markers, the materials only recently have been made available for a wide variety of fleet applications. Repeat orders from scores of fleets who have already used them indicate the nature of the results.

The two principal products in this field known to COMMERCIAL CAR JOURNAL are "Scotchlite" made by the Minnesota Mining & Mfg. Co., St. Paul, Minn., and the "Prismo Sign Kit" made by Prismo Safety

Corp. of Huntingdon, Pa. If and when other materials of this type become known to COMMERCIAL CAR JOURNAL, they will be described in future issues. Both of these products provide controlled reflection through the use of tiny glass spheres, but

MATERIALS

Signal Safety and Glamorize Trucks at Night



Grayhound Lin



Top. Rear and front views of F. B. Noerr & Son (Lewistown, Pa.) equipment using Prismo reflective material

Above. Greyhound bus illustrates efective use of Scotchlite for outline panels, name and the Greyhound emblem

Left. New Scotchlite reflective fabric applied to pedestrian clothing stands out under headlights from car

Right. Night and day views of Scotchlite application showing how lettering may be dark by day, light by night

their application is quite different.

Although COMMERCIAL CAR JOUR-

Although COMMERCIAL CAR JOUR-NAL cannot presume to weigh the relative merits of these two products the important differences, as claimed by the two manufacturers, can be pointed out. Scotchlite Sheets

"SCOTCHLITE" is supplied in plastic backed sheets with the tiny glass spheres, about 30,000 to the square inch, already applied under careful laboratory control (ac(TURN TO PAGE 98, PLEASE)

GASOLINE



A selected list of the latest literature eatalogs, pamphlets, charts—chosen to help fleetmen improve operation and maintenance

L141. Truck Refinishing

This 30-page, illustrated publication on truck and auto refinishing is the result of practical experience and surveys made by a leading manufacturer in this field. Valuable information is offered for better planning and operation of the paint shop. The manual features such pointers as shop designing, equipping, operation instructions, cost controls, management, etc.

Instructions includes such subjects as removing old finishes, preparing bare metals, masking, priming, puttying, surfacing, sanding, striping and chrome finishing. In addition such procedures are discussed as engine, radiator and tire painting. Special instructions cover the technique of spray gun sign painting, and photographs show proper handling methods for the gun.

Of special interest to fleetmen will be the section on Shop Tips, a full page devoted to practical service instructions designed to produce a better refinishing job.

This manual is published expressly to aid the shop in producing quality work at highest efficiency. It is well worth considerable time and study. Available free for the writing of L 141 on the accompanying postcard.

L142. Freight Handling

This 20-page, pocket-size booklet has been prepared to assist drivers and dockmen in handling freight transported by truck. Handling tips include those practices resulting in the most common errors responsible for expensive freight claims. The helpful hints set forth the general practice of most motor carriers.

The general rules and regulations set forth in this booklet cover appearance, safety, mishandling of funds, courtesy and responsibility. Another section is devoted to regulations with regard to picking up freight from shippers. A section outlines packing requirements which should be set up to afford full protection against damage from ordinary handling while in transit.

Other handling tips cover such subjects as picking up from connecting carriers,

delivering freight to consignees, delivering to connecting carriers. Of special interest will be the section covering handling and loading tips for the driver and dockmen.

This booklet will save the hauler a great deal of time and money. Every employee handling freight should have access to this information. A single copy is available free upon request. Write L 142 on the free postcard.

L143, Truck Decal Folder

Various ways in which decalcomanias can be used on trucks are described and illustrated in a new folder "A Moving Story for Fleet Owners," now available in the truck fleet field. The folder also compares decals with other types of signs for use on trucks and cars.

JOBSERVATIONS by Buster Rothman

People who aren't afraid to roll up their sleeves seldom lose their shirts.

* * *

When you point your finger accusingly at someone else, remember you have three fingers pointing at yourself.

The man who knows how will alway have a job. The man who knows why will be his boss.

* * *

There are two kinds of men who never amount to much, those who cannot do what they are told, and those who can do nothing else.

* * *

The turtle has to stick its neck out or it gets nowhere.

* * *

Take a lesson from the woodpecker: he uses his head when he works.

L144. Tube Data Sheets

A new data sheet covering tips on working various kinds of tubing has been made available to the fleet field. Few instruction sheets have covered the subject so thoroughly as this publication.

Under Tubing Handling the author takes up such subjects as annealing copper tubing, annealing aluminum tubing, uncoiling the tubing, how to straighten it and how to cut it. Special instructions cover the technique of flaring, and illustrations show how the job is done. A special section takes up the correct method of double flaring of steel tubing, while other tips give recommended procedures for handling both plastic and copper tubes.

A few minute's reading of this data sheet will enable the mechanic to do a quality job. It is free and yours for the asking. Just write L 144 on the postcard.

L145. Tire Handbook

Designed to provide a printed means by which truck operators can reduce operating costs and thus increase profits by proper selection and maintenance of tires, a new Truck Operators' Handbook has just been made available to the fleet field.

Featured in the volume is a discussion of the factors which can be controlled to get the most service out of any truck tire, which points out that either too much or too little air pressure decreases tire service. Suggestions for control of proper air pressures are given.

Overloading and improper load distribution, together with an easy formula for analyzing loads is also a prominent part of the publication, as well as a discussion on speeds and their effects on tire life. Matching and spacing of duels and mechanical irregularities which may cause rapid or uneven tread wear are comprehensively outlined.

The volume points out that periodic inspection prevents many tire failures, and illustrates and describes all of the most important causes of failure as well as telling how to prevent and repair many tire injuries. Ninety-three factors which affect truck tire life are listed, and data given on each type of truck tire the company manufactures.

Just write L 145 on the free postcard for a copy.



ries, shop equipment, supplies-illustrated

described in brief for the fleetman

P150. Clutch Plate

The new Accurate Powerflex Clutch plate incorporates several new features. The disc itself is made up of completely separated segments. Each segment is formed with opposing flat-surface crimps which afford support to a substantially greater facing area. Because the contour of the segment has a large area of flat surface, there is much more actual contact between the disc and the facing.



The larger coil springs used on this new plate, combined with patented spring supports, are said to increase the life of the springs, and minimize spring breakage or collapse. Because the safety stops afford rigid support over the entire diameter of each end of each coil spring, the springs compress parallel and do not belly out at the center coils or rub against the retainer plate. The hub splines are chamfered or pointed so that the transmission shaft splines align themselves automatically, with the splines in the clutch hub when it is inserted.

Use Free Postcard for More Details.

P151. Lite-Guard System

The Lite-Guard System developed by International Lite-Guard, Inc., Cleveland, Ohio, is an automatic safety device which provides a system whereby both headlights of a vehicle will function even though any one of the four headlight filaments are burned out. When either filament in one or both of the double filament sealed beam headlights burns out, the Lite-Guard will automatically transfer the power to the remaining filament in said bulb and also automatically signal the operator as to the defective lamp. Due to this action the driver has two lights which will operate until he can find the oppor-

tunity to replace the defective lamp.

The system is composed of the unit, the indicator for dash mounting, the foot switch with complete wiring. Installation is simple, and the cost is low.

Use Free Postcard for More Details.

P152. Nut Setter

A new Speed-o-matic electric impact Nut Setter has been introduced by Illinois Gage & Mfg. Co., Chicago.

This nut setter is torqueless—it will not twist in operator's hands when nut becomes tightened. It operates at high speed, driving nut or bolt 1750 rpm at free speed. At point of resistance, impact unit automatically delivers 3000 impact blows per minute.



The unit is instantly reversible for removing bolts or nuts. Equipped with 25 ft of rubber-covered cord and plug with ground wire, it operates on any 110 volt, 60 cycle, A.C. or D.C. circuit. It has an overall length of 12½ in. and weighs 13½ lb. Its capacity is up to ¾-in bolts and nuts.

Use Free Postcard for More Details.

P153. Piston Setter

The Wilton Tool Mfg. Co., Chicago, Ill., has developed a new type piston setter for removing pistons from any engine. The tool is in effect a hand-operated clamp with a threaded jaw which grips the connecting rod bolt to guide the piston over the crankshaft without damage to the bearing. One man can set pistons with this tool.



Overall length is $14\frac{1}{2}$ in. The tool weighs $2\frac{1}{2}$ lb, is of sturdy construction and is furnished in fine plated finish.

Use Free Postcard for More Details.

P154. Hand Cleaner

Farbach Chemical Co., Cincinnati, Ohio, announces the introduction and addition of FAR Waterless Handy Cleaner.

FAR removes dirt, grease, grime, paint, and other soiling agents without the use of water in cleaning or washing; included in the formulation is refined lanolin for protecting the hands against chapping and chap cuts.

Use Free Postcard for More Details.

P155. Spark Plug

The Electric Auto-Lite Co. has announced the development of a new spark plug with a built-in resistor which suppresses spark plug interference with radio, radio-telephone, radar and television reception. The new resistor spark plug is said to provide smoother operation and improved economy. The plug features a built-in 10,000 ohm resistor which reduces electrode erosion thus allowing for a wider gap setting. Other benefits claimed include smoother idling as the wider gap helps to eliminate occasional missing; reduction of ring and cylinder wear when lubrication is washed away by gasoline not burned as a result of occasional misses; reduction of misfiring due to lean spots in carburetion;

(TURN TO NEXT PAGE, PLEASE)



(Continued from page 61)

assists in the burning of leaner mixtures bringing about improved engine economy at idle and throughout the speed range; increases electrode life up to 200 per cent and more.

Use Free Postcard for More Details.

P156. Extinguisher



Power-Pak Tire Inflator-Fire Extinguisher units developed by Power Pak Products, Inc., Buffalo, N. Y., are now available in a heavyduty size. Big brother to the smaller 10-oz automotive unit, the heavyduty model contains 2½ lb of CO₂. With this increased capacity.


the new Power-Pak will inflate not only the largest commercial tires (9:00 x 10 to 90 lb) but also a dozen average size passenger tires (to approx. 30 lb each).

Use Free Postcard for More Details.

P157. Sunnen Mandrels

Sunnen Products Co., St. Louis, Mo., presents two new series of mandrels.

The new mandrels for fitting pins in connecting rods are made of steel—and provide much greater service life. The short



stone and shoe assure extreme accuracy and a straight round hole—free from bellmouth. Very little truing is required. These mandrels cover the range from .650 in, to 1.024 in.

For fitting king pins Sunnen offers a new line of multiple stone mandrels that maintain a perfect alignment between the bushings. These mandrels come with low cost wear shoes that can be replaced when they become worn. The mandrels handle the popular king pin sizes—from .733 in. to 1.500 in.

Use Free Postcard for More Details.

P158. 5th Wheel

Increased efficiency and driver comfort with 145-lb saving in weight are characteristics of a new torsional rubber mounted 5th wheel just announced by Highway Trailer Co., Chicago.



The new 5th wheel is full 36 in. wide, thus giving the benefit of increased bearing area. With the new-type torsional rubber mounting replacing the former coil springs, "telegraphing" of noise from trailer to cab is eliminated.

Weight of the trailer, levelling the new 5th wheel torsionally, twists the rubber bushing, but as soon as trailer is uncoupled, the tails automatically return to the down position. These rubber bushings need no lubrication.

It is claimed that the new torsional rubber bearing will resist and partially absorb radial dynamic forces up to 220,000 lb without damage, as the rubber flows axially on the loaded side and circumferentially away from the loaded side.

PI

A

petr

tion

Cal

this pro

froi

ina

lin

61

b

ta

Another feature of the new 5th wheel is simplicity of construction. It contains 23 fewer parts than the former model.

Use Free Postcard For More Details.

P159. Bench Grinder

The United States Electrical Tool Co., Cincinnati, has announced a new "Reddy" 6 in. utility Bench Grinder, as now available. It has ball-bearing shaft support,



is sturdily built, well balanced and designed for general purpose grinding within rated capacity. The motor is 1/3 bp capacitor type, ball-bearing, totally enclosed, 3450 rpm load speed.

Reddy is equipped with 1 coarse and 1 fine abrasive wheel, 6 in. x ¾ in. x ½ in.; tool rests adjustable to wheel wear; 7 ft. 3-conductor rubber covered cable. It weighs only 45 lb and can be furnished for 110 or 220 volt, 50 or 60 cycle, 1, 2 or 3 phase AC.

Use Free Postcard For More Details.

P160. Controlled Crankease Ventilator


The problems created by crankcase dilution are successfully overcome by Oildex, according to its manufacturer. This controlled crankcase ventilator, is manufactured and distributed by the Oildex Corp., Cleveland, Ohio.

The unit is designed and engineered for the purpose of removing diluent vapors from the crankcase before they condense into damaging liquid impurities. The ventilator extracts, then filters these vapors and returns them through a volumetric control valve to the cylinders, where they are utilized as additional fuel.

Oildex can be installed on any conventional type gasoline engine, according to the manufacturers. It receives its suction power from the intake manifold; the vacuum sucks out blow-by vapors that would otherwise condense in the crankease and valve assembly compartments.

These vapors are then filtered and cleaned, passed through the control valve to the intake manifold and to the engine, increasing power and gasoline mileage, and preventing crankease dilution.

Use Free Postcard for More Details.



p161. New Carburetor

lb

p

A new Century 3C carburetor for liquid petroleum gas with the controlled combustion principle has just been introduced by Century Gas Equipment Co., Lynwood, Calif.

The controlled combustion principle of this new carburetor meters or varies the proportion of air as well as gas intake from closed to full open position. This controlled combustion principle elim-inates the risk of dilution by liquid gaso-



line and carbon formation in the engine provided the pistons do not pump oil. Overhauls are said to be reduced. Installation of this equipment consists of a tank, converter and the carburetor.

Use Free Postcard for More Details.

P162. Lock Nut

Swallow Airplane Co., Wichita, Kan., has developed a lock nut with replaceable locking unit which may be used with either fiber or metal washers, thus allowing the use of this nut where resistance to heat is essential.

Full holding strength of the lock nut with replaceable locking unit is restored by replacing only the locking unit re-tained in the crown of the nut. Because replacement of the locking unit requires no tools and the cost of the locking unit



itself is only a fraction of the cost of the entire nut, savings are possible over the replacement of the entire lock nut.

Use Free Postcard For More Details.

P163. New Brake Lining

A new wire molded brake material developed by The Raybestos Division of Raybestos-Manhattan, Inc., Bridgeport, Conn., is said to eliminate the warping and curling characteristic of wire molding.

The new wire molded lining as a harder, flat surface claimed to give the material much greater wear resistance, flexibility and stability of friction. It is said to make for less fading, less running drag, fewer adjustments and longer-lived quicker installations.

The new material is boxed in drilled and countersunk sets and will also be available in standard rolls.

Use Free Postcard For More Details.

P164. Crankshaft Grinder

The Waterbury Tool Co., Division of Vickers, Inc., Waterbury, Conn., has recently placed a new portable crankshaft grinder on the market. With this device the crankshaft stays in the block and the unit works from the top of the block, with only the chassis jacked up high enough to remove the oil pan.

This grinder is said to handle full range in-line engines. One electric motor drives the crankshaft while another 34 hp. motor drives the grinder through a flexible shaft arrangement. The grinding wheel is full width of throw, eliminating need of feeding the wheel across the throw. A hand micrometer feed for regulating cut of wheel, graduated in .0005 in., is located at end of yoke. The machine is said to be simple to adjust and operate.

Use Free Postcard for More Details.

P165. Sleeve Press

Announcement of a new type Hydraulic Power Service Tool for removal and insertion of cylinder sleeves has been made by the International Tool Corp. of Chula Vista, Calif.

This power tool inserts and extracts both steel and cast iron sleeves, and will remove and insert all eight sleeves in the average Ford or Mercury engine in 15 to 20 min.



The steady even pressure provided by the power unit is said to eliminate any possibility of distortion or radial cracks to the sleeves, harm to the block or cylinder

Air pressure of 40 to 60 lb provided by any standard type air compressor is all that is needed for its operation. One hundred fifty lb of air pressure generates 17,250 lb of hydraulic power at the ram, which engages the sleeve for its removal or insertion.


Adapters for removing and inserting spring shackle bolts in Fords, Mercurys-Lincoln Zephyr's series and Ford Trucks are also available for use with the same

Use Free Postcard for More Details.

P166. FM Radiophone

Philco Corp., Philadelphia, Pa., has re-cently announced a new FM Radiophone Communication System with a new 30-44 MC "Channel-Saver" circuit.

This development is said to permit higher standards of efficiency in half the channel width. It operates on 20KC channel instead of the 40KC width heretofore required by available equipment. All receivers are double conversation super-



heterodynes using the advanced FM detector and two separate low temperature coefficient crystals to control the heterodyne circuits. All metal parts are plated and Chromac finished as a protection against rust and corrosion.

The new units feature vertical or horizontal mounting, low battery drain, easy installation as well as low upkeep cost. Use Free Postcard For More Details.

P167. Drying Lamp

The Dry - Quick Paint Drying Lamp which has just been introduced by the Dry Clime Lamp Corp. of Greensburg, Ind., has a lava-coated dark burning infra-red generating unit in place of a bulb. It is built to withstand abuse and rough handling without danger.

Because of its light weight the

Dry-Quick Lamp does not require casters. It is not top-heavy. It is easily adjusted to the proper height and angle for the job to be done, and it occupies little space when not in use. It radiates infra-red rays over a wide area and will dry an entire fender at one time.

Use Free Postcard for More Details. (TURN TO PAGE 240, PLEASE)

Ways

to Reduce SLUDGE

Engineer describes corrective measures for low temperature sludging of which improved low-speed carburetion, positive crankcase ventilation at low speeds, and high-set engine thermostats head list

ON THE BASIS of the test evidence, the most obvious remedy for minimizing oil contamination and low temperature sludge deposits would be to eliminate engine idling. Unfortunately, this is impossible to accomplish in urban communities with traffic signals on every main and many secondary street crossings, and in many operations of the stop-andstart type. Additionally, cold starting, engine warm-up, accelerating, coasting to a stop, or using the engine as a brake are all probably in the same category as straight idling, insofar as blow-by contamination is concerned.

Since we cannot ask engine operators to change their driving habits, we must look at the engines for ways and means of improvement. The table on opposite page itemizes engine modifications and corrective measures, which are listed in order of their apparent importance.


Improved Low-Speed Carburetion SINCE the very rich mixtures pro-

duced by present day carburetors at idling and low speeds seem to be the primary cause of excessive oil contamination, improved fuel metering systems capable of maintaining by CARL W. GEORGI*

Tech. Director, Research Laboratories, Quaker State Oil Refining Corp., Oil City, Pa.

more efficient air-fuel ratios over a wide speed range can probably be listed as the number one necessity.

Proper maintenance of fuel, choke and ignition systems to minimize rich mixtures and poor combustion are a helpful measure, but the fundamental problem seems to be one of basic design.



Positive Crankcase Ventilation

THE crankcase ventilating systems of most current engines provide practically zero ventilation at idling and low speeds, and function

* Excerpted from a paper presented at the SAE Annual Meeting, Detroit, Jan. 12-16, 1948. effectively only at high road speeds. Since the worst conditions of contamination blow-by occur at idling and low speeds, present ventilating systems function almost exactly in reverse of the desired.

Lo

Idl

pa

6.

8.

9.

cy st

at

cc

pe

po

a

01

al

C

fr

te

C

f

b

p

W

it

h

f

F

A great need exists for crankcase ventilating systems which will provide positive air flow in good volume independent of engine speed, and especially under idling conditions.

High-Set Thermostats

A LTHOUGH most engines are factory-equipped with thermostats of 140°/150°F. setting, many engines are being used with the thermostats removed or stuck in open position. Many engine owners and operators do not appreciate the importance of thermostats and either do not replace defective units or leave them entirely after one fails.

An educational campaign on the importance of thermostats, as well as development of units having longer operating life seems to be indicated. High set thermostats in the range of 160 to 180°F. will maintain higher over-all engine temperature levels, and are desirable in many engines even though they require the use of non-volatile anti-freeze in winter.

Corrective Measures

for Prevention of Oil Contamination and **Sludge Deposits**

- 1. Improved Carburetion at Idling and Low Speeds
- 2. Positive Crankcase Ventilation at Idling and Low Speeds
- 3. Cooling System Thermostats
- 4. Improved Jacket Temperature Con
 - a. Radiator Covers or Shutters b. Variable Pitch Fans

 - c. Radiator By-pass Plumbing d. Reversed Coolant Flow
- 5. Insulated Crank pans, Valve Compartment Covers, etc.
- 6. Oil Filters
- 7. More Frequent Oil Changes
- 8. Detergent Oils
- 9. Solvent Oils

ıg

se

0-

ne

d

its

n-

en

nd

m-

er

or

he

as

er

ed.

of

er

els,

168

150

er.

Jacket Temperature Control

A LTHOUGH thermostats in good condition will maintain adequate upper engine temperatures, the cylinder jackets of many engines are still overcooled due to excessive radiator capacity at light loads and in cold weather. Improved jacket temperature control is, thus, another important problem requiring further at-

Design improvements to this end which are now receiving considerable attention are radiator covers or shutters, variable pitch fans, radiator by-pass plumbing, and reversed coolant flow wherein the coolant from the bottom of the radiator enters the engine head instead of the cylinder jackets. Reversed coolant flow seems to offer interesting possibilities, since the cooling systems of present day engines put the coldest water in the cylinder jackets where it should be the warmest, and the hottest water in the cylinder head where it could well be the coldest.

Insulation


I NSULATION of crank pans, valve compartment covers, etc., has frequently proved to be helpful in minimizing moisture condensation

and sludge deposition when these surfaces run overly cold in any particular engine due to design or operating conditions. However, insulation is a secondary remedy and does not correct the source of the trouble.

Oil Filters

OIL filters can be of benefit in reducing the contamination solids content of the engine oil, and will minimize sludge forming tendencies by keeping the solids accumulation from exceeding the "holding capacity" of the oil.

However, in engine operations where high rates of oil contamination prevail, filter cartridge changes must often be made at such frequent intervals, to maintain adequate filtering efficiency, as to be entirely uneconomical. Additionally, oil filters are only a secondary remedy for sludge troubles and cannot correct the basic causes.



Frequent Oil Changes

VERY frequent oil changes are sometimes adopted to minimize engine sludging troubles. Oil changes at regular intervals, as predicated by the particular engine operating conditions, are to be recommended as a means of flushing out accumulated blow-by solids and contaminants before they reach dangerous concentrations.

However, under many conditions of service, the change practice would have to be so frequent as to be en-

Low-Temperature Sludge **Most Critical**

There is general agreement among oil marketers that the number one cause of consumer complaints on oil performance is sludge and that these sludge troubles are not the high temperature oil oxidation type, but are the low temperature type resulting from excessive contamination with combustion chamber blow-by products.

tirely too burdensome in time and expense. And, again, frequent oil changes are not a cure or corrective for basic oil contamination.

Detergent Oils

DETERGENT type heavy-duty oils have been widely publicized and utilized, but many disappointments have been experienced when they have been used with the idea of preventing cold engine sludge troubles. It must be emphasized that the very best detergent additives have a limited capacity for holding blow-by insolubles and contaminants in dispersion in motor oil.

When oils become contaminated with several percent and more of blow-by products, detergents become hopelessly overloaded. A detergent can't replace a shovel when blow-by contamination of the oil reaches the proportions prevalent in many lightduty, intermittent operations.

Solvent Oils

C ERTAIN synthetic oils, or petroleum oils containing special additives, which have a solvent action on sludges, varnishes, gums, resins and moisture, have been utilized to a limited extent as a means of preventing cold engine sludge formation. While special oils of this type have shown some indication of helping the sludge problem, their use is, again, a purely secondary remedy which does not reach the real source of the trouble.

The question is also introduced as to whether motor oils are intended to serve as engine lubricants, or whether one of the chief functions should also be to act as "garbage" collectors; the "garbage" in this case being the soots, lead salts, moisture, unburned fuel and fuel resins which work past the pistons into the crankcase. An oil containing several per cent or more of such contaminants cannot be considered as a good engine lubricant, even though the contaminants are held in dispersion or solution.

It appears more general recognition must be given to the fact oil alone canot cure the cold engine sludge problem, and the oil must be given some measure of assistance in the way of engine design improve-





FIG. 1 (left). Effect of king pin offset on load distribution. Top drawing shows load with no offset; center, same load with 14 in. offset; bottom, same load with 14 in. offset and trailer axle moved forward

FIG. 2 (below). Effect of king pin offset on clearance angle. 14 in. is practical maximum

FIG. 3 (bottom). Effect of king pin offset on steering. Side thrust on front axle is greater

FIG. 4 (right). Effect of king pin offset on turning radius and particularly on off-tracking






Figuring

FIFTH WHEEL

KINGPIN OFFSET



DETERMINATION of the proper extent of kingpin offset for tractor-semi-trailers by trial and error methods too often results in costly errors and is fraught with many difficulties. By the term "kingpin offset" is meant the longitudinal distance from the center of the tractor rear axle or bogie trunnion to the kingpin center, zero offset being where the kingpin is centered over the axle or trunnion. The amount of this offset affects a surprising number of characteristics of the combination, including load distribution, steering, braking, tire wear, riding qualities, maneuverability, traction, safety and overall length. The ex-

tent of offset affects some of these considerations favorably and some unfavorably and, consequently, the optimum offset is not easy to find.

Indications point strongly to the desirability of sharply increasing the amount of kingpin offset beyond prevailing practice and to the possibility of higher plate heights compatible with reasonably low height of flat body floors. To accomplish these ends, a certain amount of development work is required in the design of both tractors and trailers.

Regardless of the relative desirability of different amounts of kingpin offset, there are definite geometric limits on how far ahead of the tractor axle the kingpin may be placed. Before exploring these limitations, however, it is well to consider the general effects: ma

un

qu

ax

gr

tra

la

bu

ob

We fer


di

of

Fr

Load Distribution

FIRST among these is that of load distribution. Although the semitrailer has other advantages, maximum load capacity within legislative restrictions is by far the most important reason for its widespread use. Although weight limitations are prescribed in a variety of ways in the various states, axle weight limit is predominant. For the maximum gross weight, obviously each axle must bear as nearly as possible the



Load distribution, traction, braking, steering and maneuverability are all affected by fifth wheel location. Here are the factors involved together with the limitations imposed

> by MERRILL C. HORINE* Mack Manufacturing Corp.

maximum allowable weight. With uniform tires all around, this requires that in the conventional threeaxle combination, 20 per cent of the gross weight shall be borne by the tractor front axle and 40 per cent by each of the other two.

Because of the variation in unladen tractor weight and its distribution between tractor axles, it is obvious that to secure this ideal weight distribution will require different kingpin offsets for various individual combinations. In the case of a particular tractor rated for 40,-

000 lb GTW and having an unladen weight, with fifth wheel lower half of 7750 lb., distributed 54 per cent on the front axle and 46 per cent on the rear, and a wheelbase of 146 in., the kingpin load of 19,250 lb. must be located 361/2 in. ahead of the rear

axle to secure 18,000 lb. on the rear axle and 9000 lb. on the front. **

** All weights in pounds. These values are determined by the formula:

 $\frac{\mathsf{TC_f} - \mathsf{WC_f}}{} \times \mathsf{WBC}$

KO = \frac{1C_f - WC_f}{TC_o - WC_t} \times WBC

Where KO is the kingpin in Inches
TC_f is the tire capacity, front wheels, in processing the tire capacity, tractor chassis, WCr is the tractor chassis weight on front tires, in

pounds
WCc is the tractor chassis weight, total, in pounds
WBC is the tractor chassis wheelbase

In individual cases, with different tractor weights, wheelbases and distribution of unladen weight, this figure will vary somewhat, but in every case the ideal of uniform tire loading throughout will be found impracticable of attainment with present design. Nevertheless, this demonstrates that from the standpoint of load distribution, the maximum practicable kingpin offset is desir-

As will appear later, a considerably more moderate offset-approximately 14 in.—is the maximum which can be tolerated with prevailing tractors and trailers. This falls short of the ideal distribution, as indicated in Fig. 1, but it does offer an appreciable gain in GTW over that which is obtained with the kingpin centered over the tractor axle or offset to any lesser extent. The top drawing in Fig. 1 shows the distribution in pounds with the kingpin centered over the axle. The second shows the result of offsetting the kingpin 14 in., but making no other changes. The third represents the effect of moving the trailer axle back in appropriate amount to agree with the 14-in. offset so as to secure 18,-000 lb. on both the tractor rear axle and the trailer axle. The difference between 5790 lb. on the front axle and the ideal of 9000 lb. represents the unavoidable discrepancy between the optimum and the maximum.†

(TURN TO PAGE 122, PLEASE)

† These values are determined by the formulas:

$$\begin{aligned} & \text{GC}_f = \frac{(\text{GC}_r - \text{WC}_r) \times \text{KO}}{\text{WBC} - \text{KO}} + \text{WC}_f \\ & \text{GTW} = \frac{\text{GT}_r + \text{GC}_r + \text{GC}_r}{\text{WBC} \times (\text{GC}_r - \text{WC}_r)} \\ & \frac{\text{WBC} - \text{KO}}{\text{WBC} - \text{KO}} \\ & \text{KCG} = \frac{\text{BL}}{2} - \text{BO}_k \\ & \text{WBT} = \frac{(\text{GT}_k - \text{WT}_k) \times \text{KCG}}{(\text{GT}_r - \text{WBC})} - \text{KCG} \end{aligned}$$

When the gross weight on the tractor and trailer rear axles is set, with no kingpin offset, and then the kingpin is moved forward, the following applies:

Find GT_k from the above formula, leaving KO=0:

 $(WBC - KO) \times GT_k$ GCr = $\mathbf{GT}_{k} \times \mathbf{KO}$

 $GTW = GC_r + GC_f + GT_r$

 $\begin{aligned} & \text{GTW} = \text{GC}_r + \text{GC}_f + \text{GT}_r \\ & \text{BL} \text{ is the body length in inches} \\ & \text{GC}_k \text{ is the body overhang ahead of kingpin in inches} \\ & \text{GC}_k \text{ is the gross weight of tractor on front tires} \\ & \text{GC}_k \text{ is the gross weight of tractor on rear tires} \\ & \text{GT}_k \text{ is the gross weight of trailer at kingpin} \\ & \text{GT}_k \text{ is the gross weight of trailer on rear tires} \\ & \text{GTW} \text{ is the gross train weight} \\ & \text{KGG} \text{ is the distance from the center of gravity to} \\ & \text{the kingpin, in inches} \\ & \text{KO Is the kingpin offset, in inches} \\ & \text{WBC Is the wheelbase of tractor, in inches} \\ & \text{WBC Is the wheelbase of tractor, in inches} \\ & \text{WC}_k \text{ is the weight of tractor chassis, on front tires} \\ & \text{WC}_r \text{ is the weight of tractor chassis, on rear tires} \\ & \text{WT}_k \text{ is the weight of trailer, at kingpin} \end{aligned}$

ri-

ve

T-

e.

he

is

m

de

he

^{*} Excepted from a paper presented at the SAE Annual Meeting in Detroit, Jan. 12-16.



L. C. Allman, Fruehauf Trailer Co.



P. D. McLean, Highway Users Conf.



Chas. W. Kynoch, Detroit Arsenal



Ed. J. Buhner, President, ATA



E. J. Lucas Kingham Trailer Co.

TRAILER

Makers Discuss:

- 1. Standardization of Connectors
- 2. Brake Operating Devices
- 3. Future of Highway Transport
- 4. Highway Planning and Courtesy



President Harrison Rogers Rogers Brothers Corp.

ELECTRICAL CONNECTORS for trailers and brake systems got the play at the engineering roundtable held in connection with the seventh annual convention of the Truck-Trailer Manufacturers Association at Edgewater Park, Miss., Jan. 12-14. At the general sessions prominent speakers discussed problems of interest to trailers users and manufacturers.

A proposed TTMA standard for truck-trailer and semi-trailer electrical connectors was submitted for adoption by the Specification Standardization Committee. The purpose of the standard is to bring about uniformity of installation and interchangeability of vehicles so as to eliminate the necessity of changing wiring each time a different powered vehicle is coupled to a towed vehicle. It is not the intent to favor the product of one manufacturer over that of another but to create uniformity of dimensions so that any plug will fit any coupler.

After a discussion of the subject it was decided to rewrite the proposed standard and submit it to members for a mail ballot. The specification standards will include approximate lecation of the coupler, diameter of the plug and spacing of its six sockets, diameter of the six-strand rubbercoated cable and its minimum load capacity.

Room for Brake Improvement

IT was generally agreed that there was room for improvement in brake operating devices to get better synchronization of tractor and trailer brakes. James J. Black, vice president in charge of engineering, Trailmobile, thought that truck manufacturers should pay more attention to the brake operating devices they place on truck models which are also used as tractors. Too often, he said, a braking problem is dumped into the lap of the trailer manufacturer that has its ori-

gin in the inadequacy of the power unit's braking system.


Homer T. Seale, of Homer T. Seale, Inc., Los Angeles, revealed some interesting results of a cooperative effort involving air brakes. When his company entered the compressed air brake field it offered its facilities to truck-trailer operators for experimental and research purposes. There have been some interesting developments.

One operator presented a problem in two-way check valves used where lines from hand and foot valves join. This operator had experienced a centering of the mechanism when the valve received air from both hand and foot valves simultaneously, thereby prohibiting air flow to brake-operating valves. To solve this problem a two-way check valve was designed which may receive air from either hand or foot valve or both and which has no position in which the air flow

(TURN TO PAGE 220, PLEASE)



CCJ QUIZ -



There was a young chap from Hoboken Who wrote poems in meter that's broken. His efforts at verse

Went from awful to worse
Till one day he happened to choken.

So, if you don't choke over some of the atrocious rhymes here, you can try your skill at identifying the TRUCK in each jingle. All the correct answers are listed below, plus as many wrong answers just to make things a little tougher. Check page 138 for the answers. A score of six correct is passable. Seven is fair and eight is good. Nine is getting out of this world, and if you get all ten right, you should quit your job and concentrate on "Miss Hush" contests.

1.

A not so young man up in Lansing, At his favorite magazine glancing, Saw his initial success On the cover no less And found it was mighty entrancing.

2.

This truck is a gem— It's very well built. Your score will still count. Even though it shows "Tilt."

ver

ile, in-

ef-

his

air

to

en-

s. em

ere

in.

en-

the

nd

at-

a

ned

ner

ich

OW

AL

3.

Young Henry from way up in Michigan Once said, "Gee, but I wish I can!"

He didn't wish long

For it came like a gong

And old Dobbin he never did hitch ag'in.

4

Queen on the Hit Parade,
To the top every time it will go—
Number one song that they're singing,
"Let it snow; let it snow; let it snow."

5

This outfit was started in days antebellum—

The answer you must guess for it's sure we won't tellum.

It built carriages fine for your lady and mine,

But now it is trucks
That are making the bucks
As they roll down the assembly line.

6.

Take a ride in a steamer with Stanley, so manly,

But he's not the one of our choice.

We'll take the other, though lacking in color,"

And we know we could have done "woise."

7.

Great oaks from "Little" acorns grow; Find the clue and the answer you'll know.

8.

For a truck
That is stuck
In the muck
Or on ice
It is nice
To have twice
As much drive
As you strive
To arrive
Back in place
In the race
And save face.

9.

Said Horace to John,
"A truck, we have made it."
Said John back to Horace,
"For a job then let's rate it."

10.

There was a ferocious bull puppy;
On the front of a truck he stood uppy,
But biting he wasn't
And barking he doesn't
And that ends our Quiz quite abrup'ly,

Now find the answers on this list:

International Autocar Biederman Kenworth Mack Chevrolet Corbitt Peterbilt Diamond T Reo Dodge Sterling Federal Studebaker Ford Walter FWD Ward LaFrance

1948 Quaker Package Delivery Body

GMC



Atlas Body & Equipment Co., Philadelphia, Pa., announces its 1948 models of Quaker Package delivery bodies. These bodies are made to mount on flat face cowl chassis from ½ ton to 5 ton units.

face cowl chassis from ½ ton to 5 ton units.

The bodies are of all steel construction incorporating the latest technique of high tensile steel welding—assuring less dead weight yet giving the strength


of a sturdy steel structure.

New features of the 1948 line are the elimination of separately attached drip moulding, this has now been made an integral part of the roof. Panels and rear quarter panels are riveted so that repairs can be made quickly without costly tie-ups of equipment. Drivers seats are made of newly designed stretcher coil spring covered with attractive leather. Drivers section and body is covered with 12 gage safety tread steel plate.

12 gage safety tread steel plate.

The Quaker package bodies are available with insulation for the frozen food trade, and for the milk industry. Also lined with steel slats or plywood for regular package delivery.

FEBRUARY, 1948



Diesel Smoke Problems Aired at SAE . . . Dodge Prices Up 8 to 12% . . . Ford Up Average of 5.6% Chilly Torque Converters . . . 10% Rate Increase for East Coast . . . First Taft-Hartley Injunction

Diesel Smoke Aired at SAE

Fleet operators who use diesel trucks know that the smoke problem is a rather serious one. At the annual SAE meeting in Detroit the engineers gave the problem a good working over and devoted no less than six papers to the subject. Their discussion was rather technical, and when we couldn't keep up with the confusion of curves and graphs and engineering lingo in general we corralled P. H. Schweitzer, of Pennsylvania State College, chairman of the session, who is considered an authority on the subject.

He pointed out that the problem requires three methods of attack—the technical approach, education, and law enforcement. He said currently police in Los Angeles run around armed with a smoke chart and when they see an offending diesel they hold the chart up to the sky and compare various sections of it with the smoke coming from the stack. If the comparison shows too heavy a density, the driver is hauled before a regulating body which may impose a fine as high as \$200. However, in most cases the operator is given an opportunity to correct the condition.

Contributing factors toward excessive smoking, according to Mr. Schweitzer, are fuel injection and bad driving habits. He added that at the outset the unions would not permit discharging a driver for improper driving or tampering with the fuel adjustment, but that they now will allow the discharge. He said that even the best diesel would smoke when crowded and that drivers paid on the basis of so many hours per run often are offenders in that respect. He also pointed out that smoke from gasoline engines is more toxic and dangerous than diesel fumes, but are not so conspicuous and thus do not attract public attention. It is his opinion that the operators and manufacturers are making progress and the diesel smoke problem eventually will be brought under control.

Dodge Prices Up 8 to 12%

Although only a few prices were available in mid-January, those that could be obtained indicate an increase of between 8 and 12 per cent on the new greatly improved Dodge truck models. Following are prices of a few models which were available. Factory retail price at the factory

by LEN WESTRATE

CCJ Detroit News Editor

without taxes or other charges: ½-ton 6½ ft. box, \$1113; ¾-ton chassis cab 7½ ft. express body, \$1221; 1-ton chassis, cab, 7½ ft. express body, \$1277; 1½-ton chassis, cab, and 9 ft. stake body, single rear tires, \$1491; 2-ton chassis, cab, stake body, dual rear tires, \$1858, and the 4-wheel drive 1-ton power wagon with chassis cab and express body, \$1814.

Ford Up Average of 5.6%

Prices on the new Ford truck line are up an average of 5.6 per cent over the level prevailing for previous models. The list prices of the F-7 21/2-ton and the F-8 3-ton, which are new large sizes, range from \$2485 to \$3430. New prices on the regular models which were made previously range from \$890 for the F-1 6-cylinder 1/2-ton chassis and cowl to \$2135 for the F-6 series cab-over-engine 2-ton 8-cylinder stake truck. The company stresses that while prices are up somewhat, additional value has been built into the units and is not fully reflected in the price increase. (All Ford prices are published in the CCJ Specification Tables beginning on page 77 of this issue.)

Chilly Torque Converters

Truck owners who are looking for adoption of torque converters by truck manufacturers will be interested in the experience of Detroit's street railway which has several hundred buses equipped with the device. It has housing for only 250 of the units and in cold weather it is required to start the buses several times during the night to keep the oil in the system warmed up in order to prevent trouble when trying to start out in the morning. The D.S.R. also has found that it must house all its diesel buses if it wants to be able to start them on cold mornings.

10% Rate Increase in East

With costs soaring, motor freight carriers from the East Coast to the Rockies got a badly needed 10 per cent increase on interstate rates during the early days of this year. However, it is the feeling of many operators in the Detroit area that another increase will be necessary to bring operating ratios up to a satisfactory level. costs mounting, many carriers who had been operating at a reasonable profit now find themselves with 99 per cent or higher ratios. One particular company had a 92 per cent ratio up to the time of the last wage increase in November and within three months had gone up to more than 99 per cent. Current truck rates still are 17% per cent under railroad rates on loads of 5000 pounds or more, which not only affects uniform transportation costs for shippers but also makes too great a disparity.

One fleet operator made an interesting suggestion in the discussion following presentation of a paper on the interval between preventive maintenance procedure at the SAE annual meeting in Detroit. He said that truck and bus manufacturers should provide some means of centralizing lubrication for trucks and buses. Another interesting point brought out was that while P.M. procedures in themselves are valuable, their worth is greatly reduced unless the operating department will release the trucks for inspection.


Taft-Hartley Injunction

The first injunction of its kind under the Taft-Hartley law against featherbedding has been handed down by a U. S. court in Utica, N. Y., against the Albany teamsers' local. The ruling orders the local to refrain from secondary boycotts and demanding pay for work not done. The action grew out of a strike against Montgomery-Ward in which leaders of the union were charged with persuading individual truck operators and drivers to refuse to handle shipments to and from the company's plant at Menands, N. Y.

Fruehauf Move Rumor

Reports persist in Detroit that Fruehauf Trailer Co. is planning to move its head-quarters from Detroit to Cleveland. Some substance was given to the reports recently when Hudson Motor Car Co. purchased approximately 200,000 sq. ft. of factory space from Fruehauf. It also is known that negotiations to lease some of the Detroit Fruehauf office space are under way.

(TURN TO PAGE 144, PLEASE)



Hydrovac is the Answer

FOR EVERY SIZE VEHICLE FROM THE SMALLEST TO THE LARGEST

Hydrovac*—the Bendix-developed hydraulic-vacuum braking system—has proved to be the economical way to finer braking on all types of vehicles. This unique line of units is designed for engineering simplicity, and fits into any hydraulic system with only three connections. Their capacities range from station-wagons all the way to heavy tandem-axle liners. Nearly two

million installations and literally billions of miles have proved Hydrovac's efficiency, economy, and long life. Investigate Hydrovac! It's the answer to almost any power braking problem.

BENDIX PRODUCTS DIVISION of SOUTH BEND 20, INDIANA



HYDROVAC* POWER BRAKING

CENTERMOUNT PARKING BRAKE

HYDRAULIC REMOTE CONTROLS

UNIVERSAL JOINTS

Bendix PRODUCTS DIVISION TRAILER VACUUM POWER BRAKES

B.K. VACUUM POWER RELAY VALVES

HYDRAULIC POWER STEERING

WHEEL BRAKES

PREG. D. S. PAT. OFF.

BUILDER OF THE WORLD'S MOST WIDELY PROVED POWER BRAKING SYSTEMS

FEBRUARY, 1948

r l-S. y e is e t-

e y d

y n

Use postage-paid card inserted at page 61 for free information on advertised products

73



WASHINGTON RUNAROUND

New Federal Vehicle Committee Gets Results First Year . . . Transportation Study Bogged Down . . . ICC Revised Safety Draft Due Soon . . . Two Year Limitation Bill . . . Federal Highway Roundup

Federal Vehicle Committee Gets Results First Year

Slashing through government red tape at a furious pace in an effort "to improve motor equipment management throughout the Federal Government," the Interdepartmental Motor Equipment Committee after its first year of actual operation can point to several concrete accomplishments which, when made available publicly, should prove of inestimable value to commercial fleet operators.

COMMERCIAL CAR JOURNAL, after an interview with W. A. McCutcheon, Budget Bureau staff member and chairman of the interdepartmental group, can report that the work of this group is so intensive that some of the results may become standard practice throughout the trucking industry

when they are released.

In addition to Mr. McCuthcheon, the committee is made up of the following: James Scammahorn, Wm. K. Knauff, Agriculture; Lt. Col. T. R. Hikel, Air Force; Col. W. J. Crowe, Army; Clarence S. Bruce, Commerce; Oscar C. Wiederhold, Federal Works Agency; M. A. Stephens, Federal Security Agency; C. C. Davison, Interior; A. W. Corthell, Justice; Commander N. M. Martinsen, Navy; Albert G. Biedenweg, Post Office; Chas. C. Hudson, TVA; John D. Larson, Treasury; I. J. Henderson, Veterans Administration. However, the work of this small group affects all Federal vehicles, totaling about 73,000 (excluding military), of which approximately 52,000 are trucks.

The two top priority projects now underway should be of considerable interest to fleet owners. The first of these is the promulgation of a replacement standard for vehicles. The committee has already worked out such a standard for passenger automobiles which would permit replacement after six years or 60,000 miles of operation. If this proposal is approved the Committee will limit the number of vehicles that may be replaced during the first four years to 25 per cent of the total. A replacement standard for trucks is being prepared and should be available well before the end of the year. These standards are based on operating experience and other similar data gathered from the hundreds of government vehicle installations throughout the United States as well as industrial users.

The other major project is the preparation of a general standardized preventive maintenance manual. This manual will be by GENE HARDY CCJ Washington News Bureau

drawn up in such a manner so as to assure flexibility of use under various field conditions.

As to the concrete results recorded as a result of this cooperative effort, perhaps the most interesting to fleet owners is the adoption of a standard cost and reporting system. This system has resulted in the compilation of the first annual report covering all Federal vehicles. This report, not yet released, covers all government agencies and includes the following data for each agency as well as cumulative totals on automobiles, buses, and 10 classes of trucks:

Miles operated; hours operated; gallons of fuel used; accumulated hours operated; accumulated miles operated; accumulated maintenance costs; operating costs (less storage and depreciation); maintenance costs; tire and tube renewal costs; total operating and maintenance costs; cost per mile; cost per hour; miles per gallon of fuel; gallons of fuel per hour.

Other concrete accomplishments include: 1—The establishment of a central clearing point for the interchange of technical information on equipment. All such material comes to Mr. McCutcheon, who, with the assistance of the Committee, passes it along to other agencies and goes to work in a trouble-shooting capacity if necessary.

2—Consolidation of government shops, so as to eliminate duplication of maintenance and repair facilities in a particular area. This has been done in several instances with the full cooperation of local advisory groups. This project will continue indefinitely.

3-A standard system of identification for Federal vehicles has also been adopted.

Other projects underway include a vehicle operator's training program and standardization and simplification of forms used in motor equipment management.

Transport Study Bogged

The transportation investigation of the House Interstate and Foreign Commerce Committee is presently in a state of "suspended animation," according to Dr. John H. Frederick, committee analyst. Dr. Frederick told COMMERCIAL CAR JOURNAL that he had hoped the letters mailed by the Committee last September to selected associations would "bring forth specific sug-

gestions for legislative activity," but that there has not yet been "any great rushing in."

He further stated that the Committee intends to re-survey the replies from the first series of questionnaires and cull four or five specific suggestions for legislation looking toward revamping of the nation's transportation policy. He added that it is not likely that the Committee will issue another report in the near future.

Dr. Frederick also said that the Committee has been studying other aspects of transportation problems, including transportation in Alaska, which covers the much-discussed highway, and that a report on this subject will be issued soon.

ICC Revised Draft Soon

The ICC Motor Carrier Section of Safety expects to begin writing the second draft of the revised motor carrier safety regs before March 1. It is this draft which will be used as a basis for public hearings sometime later in the year.

Much of the Section's work has been concerned with reviewing all comments received at the series of informal conferences with carriers and other interested groups last fall. Also included in this review are briefs submitted by organizations which did not appear, as well as revisions of material already submitted.

Further slowing up the work is the fact that organization which had not made any statement on the subject continue to pop up and ask for further time in which to

submit their views.

Two-Year Limitation Bill

The first bill to be given approval by the House of Representatives after the opening of the second session of the 80th Congress was H.R. 2759, which amends the Interstate Commerce Act to provide a two-year limitation within which actions may be brought by or against common carriers by motor vehicles, common carriers by water, and freight forwarders, and other common carriers for the recovery of undercharges and overcharges.

The bill was designed to establish a uniform statute of limitations for such action so as to end the confusion which has resulted from the application of the varying State statutes of limitations. The two-year period is the same time within which similar actions may be brought against com-

mon carriers by rail.

(TURN TO PAGE 146, PLEASE)

Truck Specifications Table

CURRENT PRODUCTION MODELS

DATA SUPPLIED BY MANUFACTURERS AND TABULATED BY

COMMERCIAL CAR JOURNAL

Key to Definitions, References and Abbreviations

DEFINITIONS

h-

ur n

1e

16

MAKE AND MODEL Only Domestic Truck Models are listed.

OPTIONAL UNITS

For the express purpose of best fitting the truck to the individual job most of the models listed can be provided with optional engines, transmissions, axles, etc., and these models when so equipped are considered standard stock models.

CHASSIS LIST PRICE

The chassis list price applies to the minimum standard wheelbase with standard tires and standard equipment. All prices are F.O.B. factory. Chassis list price does not include the price of the Cab unless otherwise noted.

RECOMMENDED GROSS VEHICLE WEIGHT FOR NORMAL SERVICE

The Gross Weights published herewith The Gross Weights published herewith are those supplied by manufacturers as their Recommended Gross Vehicle Weights for Normal Operating Conditions, and are based upon the Maximum Authorised Tire Size listed. In actual practice the manufacturer may either increase or decrease the gross vehicle weight rating when either favorable or unfavorable operating conditions are involved. Since the proper performance of a motor truck depends upon man factors, including grades, road condi-tions, etc., the gross weights that a manufacturer is prepared to recommend will vary with particular conditions, and the manufacturer's own standard of safety factors. Specific recommendations, therefore, should be obtained from the manufacturer's representative.

CHASSIS WEIGHT

The chassis weight listed includes the weight of the minimum standard wheelbase chassis, with cowl, with standard tires, with standard equipment with The chassis weight listed includes the weight of the minimum standard wheelbase chassis, with cowl, with standard tires, with standard equipment, with orankcase and cooling system full, and 5 gallons of fuel in the tank. It does not include the weight of the Cab. This applies to C.O.E. as well as conventional chassis types. Exceptions are noted.

STANDARD TIRE SIZE

The standard tire size listed is that which is included in the Chassis List Price.

MAXIMUM AUTHORIZED TIRE SIZE

The tire size listed in this column is the The tire size listed in this column is to maximum size recommended by the manufacturer of the chassis for the Grovenice Weight for Normal Operatin Conditions. It is furnished at extra coeff it differs from the standard size. Durears are understood; exceptions noted

MINIMUM STANDARD WHEELBASE

The minimum standard wheelbase is the so-called standard wheelbase on which the Chassis List Price is based.

MAXIMUM STANDARD WHEELBASE

The maximum standard wheelbase is the extreme end of the standard range of wheelbases offered by the chassis maker.

MAXIMUM BRAKE HP.

Maximum Brake Horsepower at Given R.P.M. is actual dynamometer reading without accessories.

GEAR RATIO RANGE

Gear Ratio Range in High—Ratios within the range given are available at no extra cost. Exceptions are noted.

TRACTORS

Unless given the designation (N)—meaning not available as a tractor—all standard models may be assumed to be available as tractors. Exclusively Tractor models are designated (T).

KEY TO REFERENCES

c.f.-Cab Forward design. c.o.c.—Cab-Over-Engine design. (D)-Diesel-engine equipped.

(T)—Designed for tractor use only.

(C)—Converted Ford or Chevrolet Model.

(2) International Harvester—Specifications shown represent only the basic standard chassis units and standard chassis ratings in keeping with definitions established by Commercial Car Journal. Optional units not shown such Journal. Optional units not shown such as engines, clutches, transmissions, axles or axle ratios, brakes, wheels and tires, frames or frame reinforcements, optional wheelbases or any other units which make up part of the truck chassis and which International will furnish and approve from the factory as optional equipment can or will change either the ratings, chassis weight shown or performance of the truck as indicated by this list.

Also the company reserves the privileges of assigning special gross vehicle ratings for any chassis providing in the opinion of its engineering department, the type of service justifies the new rating with-out decreasing the safety factor de-signed into the truck.

(a)—Available with Two-Speed Axle designated KBS Models.

__KEY TO ABBREVIATIONS __

MAKES-ALL

MAKES—ALL

B—Bendix
BL—Brown-Lipe.
Bu or Bud—Buda.
BW—Bendix-Westinghouse
C—Chevrolet.
Cl or Cla—Clark.
Con—Continental.
Cum—Cummins-Diesel.
Eat—Eaton.
F—Ford.
Fu—Fuller.
H—Hotchkiss.
Her—Hercules.
L—Lockheed.
LH—Lockheed.
Tork" rear.
M—Midland.
N.P.—New Process.
O or Ow—Own.
Op or Opt—Optional.
Shu—Shuler.
Spi—Spicer
T or Tim—Timken.
Tw—Timken-Westinghouse
Tw—Westinghouse

WHEELS DRIVEN

2F—Forward unit of Rear Axle Group.
2R—Rear Unit of Rear Axle Group.
4R—Forward and rear units of Rear Axle Group.
6—All wheels.

BRAKES-SERVICE

Location

4-Four Wheels, front and rear.
4r-Four Wheels, rear only.

Type

I-Internal.

Operation

A—Air. H—Hydraulic. V—Vacuum. D or Dp—Dual Primary

BRAKES-HAND

Location

C—Center of double propeller shaft,
2—Rear wheels,
4—Sur wheels,
5—Six wheels,
5—Six wheels,
3—Jackshaft,
7—Transmission,
7—Driveshaft,

Type

D—Tru-Stop disk.

i—Internal.

M—Mechanical.

X—External.

PD—Two drums on rear of power divider.

BRAKE DRUMS

Material

A—Cast alloy Iron.
A—American Car Foundry.
e—Cast Iron.
Ce—Composite Front, Cast Iron in rear.
Cl—Copper Iron.
Co—Composite.

D—Dayton,
E—Ermalite,
O—Gunite,
N—Nickel iron,
S—Steel.

(Where a combination of any of the above is used, the first reference mark applies to the front and the second to the rear drums.)

FRAME

Type

C—Channel.
T—Channel tapered front and rear.
L—Channel reinforced with liner.
B—Channel reinforced with both liner and fishplate.
P—Channel reinforced with plate.
Ti—Channel tapered front and rear reinforced with liner.
D—Drop Center
Tf—Tapered front.
A—Straight section sidemembers, lined with oak inserts.
Z—Reinforced (X) member frame, box type sections.

REAR AXLE

Final Drive and Type

B—Bevel. CD—Chain Drive F—Full-floating.
H or Hy—Hypoid.
d—Dual range axle.
2—Double Reductk
S—Spiral bevel.
W—Worm. 4—Three Quarters Floating.
5—Semi-Floating
T—Torque Tube

GEAR RATIOS

(**) Only one ratio.

Drive and Torque

H—Hotehkiss (springs). R—Radius Rods. L—Parallel Torque Rods T—Torque Arm.

COVERNOR STANDARD

O-WO-VO-SRO	d on the front were cab models a
OPS OR ORSO	7.50/20 can be use 7.00/168 Sleep 2.6870; Front Cen 50/20D.
Modele OVS_OWS_OP.	Rear 6.50 2.08; — * 7.50 2.00 cm; be used on the front w ** Front only: Rear 7.00/168; Bleeper cab models as * Pront only: Front 2.0870; Front Center, 2.7180; Rea ** Front only: Rear 7.50/2005
	80, please)
	80

e to

S t F

	Type	Editor Control of Control			
FRAME			00000000000000000000000000000000000000	*** *** ****	
FR	Side Rail Dimensions	000 000 000 000 000 000 000 000 000 00	######################################	4 0 00 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	######################################
(C-A Dimensions (Min. Std. W. B.	######################################	84559 5858558558 7 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	00 00 00 1- 1-00 00 00 00 00 00 00 00 00 00 00 00	444200000000000000000000000000000000000
	Type Tocation	KKKKKKKKBB		2444444	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
	Drum			FFFFFFMAARFMAAAA	
KES	Area Mi	5833 5833 5833 5833 5833 5833 744 744 744 744	00004444444444444444444444444444444444		60000000000000000000000000000000000000
BRAKES	Spenato Spenato Singa Sina Singa Singa Singa Singa Singa Singa Singa Singa Singa Singa Sin	251 - 1723 - 172 -	11148888888888888888888888888888888888		45333333333333333333333333333333333333
	Make Location Type Operat'n			B41HV B41HV B41HA W441AA W441AA W441AA W641AA W641AA W641AA W641AA W641AA W641AA W641AA W641AA W641AA	
FRONT	bna esaM leboM	22502H 22502H 32502H 35000H 35000H 224550H 27452TW 27452TW 27452TW 35000HX		32502H 35000TW 32505TW 32505TW 32505TW 32500TW 33100TW 33100TW 35100TW 35100TW 35100TW 35100TW 35100TW 35100TW 35100TW 35100TW 35100TW 35100TW	77-148 77
			10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		E E E E E E E E E E E E E E E E E E E
	Gear Racio Range in High	0444440000 0H	44400000000000000	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	
2		6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6. 6	:::	& & & & & & & & & & & & & & & & & & &	
AXLE	Gear and Type Drive & Torque	THERMANAPARE			
REAR		200 400 200 200 200 200 200 200 200 200		HH Seetlelle # e	нининанонононовносносносный
	Forward Sp'da	4Tim 53440H 5Tim 54411H 5Tim 54411H 5Tim 56410H 5Tim 66410H 5Tim 56300H 5Tim 8200PA 8 Tim 8200PA 8 Tim 8200PA 8 Tim 7000PH		5TTM H1001PH 5TTM L1001PH 5TTM L100P## 5TTM Q100P## 5TTM Q100P## TIM Q100P## TIM Q300P TIM Q300P TIM Q300P TIM Q300P TIM A300P TIM A300P TIM A300P TIM B300P#	T1448 T1448 T1448 T1488 T1488 T1488 T1488 T1588 T1
S. NO	71.37.34.04			3	•
TRANS-	Covernor Stands Make and	N WG T9 N WBu 54330 N Wbu 54330 N Wbu 554330 N Wbu 55430 N Wbu 55430 N Wbu 55430 N Wbu 57841 N Wbu 54330 N Wbu 54330	N	Cla 2050 The 5043 The 5043 The 5043 The 5043 The 5054 The 5054	NNNNNN PROPERTY OF THE PROPERT
	тепась 6	00 04000000000000000000000000000000000		*** *** : : ***** : : : ****** : : : :	888000000000000000000000000000000000000
	Number, 6 Z Diameter	0000000000004 000 	*************	HANNAHAHA - MANA -	* 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
S	Max. Brake H.P. at R.P.M. Given	78-2800 7 95-280	20000000000000000000000000000000000000	000-00-00-00-00-00-00-00-00-00-00-00-00	25. 26.00 26. 26.00
DETAILS	Torque lb. ft.	27 25 25 25 25 25 25 25 25 25 25 25 25 25	44444460000000000000	84888884848884848884888848888848888848888	10000000000000000000000000000000000000
	Comp. Ratio	80004447cs co 80004444cs co 8000000000000000000000000000000000000	######################################	000000000000000000000000000000000000000	
NGINE	Stroke	2 2224 22224 22224 244 255 255 255 255 255		## ###################################	GOWNIE ZE
EN	No. of Cylinders, Bore and	0000000000 00 0111144100 11 711477777 14 774741100 77		00000000000000000000000000000000000000	
	Make and Make	Wau 6BM Wau 6BZ Wau 6BZ Wau 6BZ Wau 6BZ Wau 6MZA Wau 145 CK	O-Thrift Mea. O-Thrift Mea. O-Thrift Mea. O-Thrift Meas. O-Thrift Meas. O-Thrift Meas. O-Thrift Meas. O-Load Mea.	Con M6330 Con B6371 Con B6371 Con B6427 Con M6330 Con B6427 Con B6427 Con B6427 Con R6613 Con R6613 Con R6613 Con R6610 Con R6613 Con R6602	
SIZES	Meximum Authorized 5 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	7.50/20 8.25/20 10.00/20 10.00/20 11.00/20 11.00/24 11.00/24 11.00/24 11.00/24	158 17700/178 17700/178 17700/178 1750/20 1750	10.00/20 11.00/22 10.00/20 10.00/20 10.00/22 11.00/24 11.00/22 11.00/24 11.00/24	8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9
TIRE	bas anoriginate to the control of th	7.00/20D 7.50/20D 8.25/20D 8.25/20D 8.25/20D 8.00/20D 11.00/20D 11	6.00/168 158 100/178 1.00/208 1.00/208 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D 1.50/20D	0.000000000000000000000000000000000000	
	Chassis Weight (See definition)	6070 6070	048998888888888888888888888888888888888		
eigh	Gross Vehicle W for Normal Servi	115000 12220000 12220000 12220000 12220000 1220000 12000 12000 12000	454 455000 4550000 45500000 455000000000	20000000000000000000000000000000000000	48850 100000000000000000000000000000000000
SE	Maximum	2000 E E E E E E E E E E E E E E E E E E			0000-111555-111555-11111111111111111111
BASE	Minimum Standard	130 000 1100 000 1100 1100 1100 1100 11	1256 1256 1257 1258 1258 1258 1258 1258 1258 1258 1258	8000004444444444666 00000444880448888886	00004448884448884888888888888888888888
	Chassis List Pric		780 885 885 9865 11050 11195 11195 11195 11755 1		
	MAKE AND MODEL	Available C8200-8P C-250-8P C-250-8P C8-50-8P C8-50-8P C8-50-8P C8-50-8P C8-50-8P C8-50-8P C9-600-8P C9-60	Chevrolet (Sencol bus) (Second bus) (Second bus) (Second bus) (Second bus) (Second bus) (Second bus)	Oobite 1880	Dooge B-1-B B-1-FC B-1-FC B-1-FA B-1-A B
	Line Number		#440F800H8440F80	822222222233	



Good-looking Studebaker trucks do a fine job of saving money for many a business!

EVERYWHERE you go these days, you find attractive-looking places of business. A trend toward clean-lined modernizing is sweeping the country.

Many firms now make looks a major consideration, even when they invest in a new motor truck. They take effective steps to reduce their hauling costs at the same time, when they buy Studebaker trucks.

Studebaker trucks have eye appeal

Superior operating economy is only one reason for the steadily growing popularity of today's rugged, powerful Studebakers.

Many a truck operator can tell you that you will find it good publicity for your business, when a handsome new Studebaker truck represents you on the streets

Pages could be filled with letters to this effect that Studebaker receives from enthusiastic owners. They're constantly being complimented by their customers on the attractive appearance of their trucks.

A "plus" that costs nothing extra

You don't pay a penny of premium for the distinction that comes with a gleaming new half-ton, one-ton or larger capacity Studebaker truck.

What's more, you get a vehicle solid and sound with the world's finest truck craftsmanship—brilliantly engineered—with every detail of its construction and performance exhaustively pre-tested on Studebaker's famed 800-acre, million-dollar proving ground.

A new Studebaker truck is certain to reward you with top-quality transportation. See your nearby Studebaker dealer now and plan with him on the model best suited to your requirements.


STUDEBAKER

Builder of trucks you can trust

The Studebaker Corporation, South Bend 27, Indiana, U.S.A.

-						, 60mm	38 38	42	44	2444	9022254 012224	55755	622	2000
	MAKE AND AND MODEL	Dodge Cont'd 2 B-1-TA B-1-VA	Behool Buses 5 Delge B-1-FS-152 6 B-1-FS-170 7 B-1-JS-212 8 B-1-RS-229	Duplex TH-404 Duplex TH-404 Duplex TH-404 Duplex TH-404 DH-558	Foderal 15 M 18 M	Ford F-1		F-3 Cowl				M P	4 1	Cab. SRWH-81
-	Chassis List Price	4>4	NONNO	HZMAØAH	MA		4 995 4 1015			4444	11487 11487 11517 11527	1240 1260 1455 1475	1530 1550 1560 1580	1875 1895 1905
WHEEL	Minimum Standard	130	22120	0.000 000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.	44444444444444444444444444444444444444	155 143 163 163	122	9 122	134	134 158 158	1134 1138 158 158	158	134 158 158	134
-	Maximum Standard	1900	22122	200000 200000 200000 200000	00000000000000000000000000000000000000	201133	1122 5	122 6		134 134 158 14 158 14 158	1100 1134 1134 1158 1144 1158 1144 1158 1144 1158	158 12 158 12 194 15 154 15	134 134 158 158 158 158	1100 160 160 160 160 160 160 160 160 160
3428	Gross Vehicle We	23000 23000 23000	150000 170000 170000	322000 322000 322000 322000 322000 322000 322000 322000	11111111111111111111111111111111111111	-	5700 5700 5700 5700			14000 14000 14000 14000	4444444 4444444	12000 15000 15000 1444	15500 15500 15500 4 15500 4	16000 16000 16000 16000 16000
	Chassis Weight (See definition)	10.0	877766 255555	6600 8.25 6900 8.25 8820 9.00 9800 11.0 11.00 11.0	4460 7 50 4 4 4 6 0 7 5 0 6 8 2 5 0 6 0 6 2 5 0 6 8 2 5 0 6 0 6 2 5 0 6 8 2 5 0 6 0 6 2 5 0 6 8 2 5 0 6 0 6 2 5 0 6 0 6 2 5 0 6 0 6 2 5 0 6 0 6 2 5 0 6 0 6 2 5 0 6 0 6 0 6 2 6 0 6 0 6 0 6 0 6 0 6 0 6	9600 11.0 9370 11.0 9995 11.0 0225 11.0	27656.50/16-6 27656.50/16-6	30157.00	Late	3935 6.50 3935 6.50 4095 6.50 4095 6.50	4615 4615 615 615 65 65 65 65 65 65 65 65 65 65 65 65 65	4143 6.50/ 4143 6.50/ 4450 7.50/ 4450 7.50/	42337.50/ 42337.50/ 43277.50/ 43277.50/	47717.50/ 49317.50/ 49317.50/
TIRE S	Standard Sta	8.25/204 10.00/20† 10.00/20	50/20D 50/20D 50/20D 50/20D 50/20D 50/20D 50/20D 50/20D 50/20D		F-W-W-W-W-W-W-W-W-W-W-W-W-W-W-W-W-W-W-W	0000				1-1-1-	6.50/20-6 6.50/20-6 6.50/20-6 6.50/20-6 7.55 7.55 7.55 7.55 7.55 7.55 7.55 7.5	3.50/20-6 5.50/20-6 7.50/20-8 8.2 7.50/20-8	50/20-8 50/20-8 50/20-8 822 50/20-8	8888
SIZES	mumizahi a a bazironizah a siza ari a a a a a a a a a a a a a a a a a a a	0.00/20 1.00/20 1.00/20	00/20 25/20 00/20 00/20	.00/20 0.00/20 1.00/20 1.00/20 1.00/20	22/2/20 22/2/20 22/2/20 20/2/2	00/24	50/16-68 50/16-68 00/16-68	7.50/17-88	18-8	50/20-8 50/20-8 50/20-8 50/20-8	50/20-8 50/20-8 50/20-8 50/20-8 50/20-8	25/20-10 25/20-10	25/20-10 25/20-10 25/20-10 25/20-10	25/20-10 25/20-10 25/20-10 25/20-10
	Make and Model	Own T-158 Own T-158 Own T-158	Own T-148 Own T-148 Own T-150 Own T-150	Her WXLC3 Her WXLC-3 Her WXLC-3 Her RXB Her RXLD Her RXLD			Own 7HY	DWD	Own	Own 7HT Own 8RT Own 7HT	Own 7HW Own 8RW Own 7HW Own 8RW Own 7HW	Own 7HT Own 8RT Own 7HT Own 8RT	Own 7HT Own SRT Own 7HT Own SRT	Own 7HW Own 8RW Own 7HW Own 8RW
ENC	No. of Cylinders, Bore and	6-3%x5 6-3%x5 6-3%x5	Na4444	1111111 1444444 1444444	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	1111	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	3x4	3.3x4 3.4x3	6-3 3x4 6-3 3x x3 8 -3 3x x3 8 x x x x x x x x x x x x x x x x x x x		THE COLUMN CO.		6-3 3x4 6-3 3x4 8x4 8x4 8x4
GINE D	Displacement	3316 3316 3316	27777 800000 800000 800000	444444	74444 014401014888888888844444 488888888888888888888	00000	232 239 66 239 66 66 66	4 226	4 226 6. 34 239 6.	4 % 4 % 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	24.24.2 24.24.22 26.25.22 20.00.00 0.00.00	4%4% 22222 23222 6000 6000	4.44.7 22236 222396 232666	22396 22396 22396 22396
DETAILS	Comp. Ratio	5270	61192 61192 6204 6204 6225	2000 2000 2000 2000 2000 2000 2000 200			88 88 80 88 80 88	8180	8180	88888 88888 10088	00000000000000000000000000000000000000	88888 88888	8888	88180 180 180 180 180 180 180 180 180 18
rs	Mar. Brake H.P. at R.P.M. Given	128-3000 128-3000 128-3000	109-3600 109-3600 109-3600 114-3600 115-3200	113-3000 139-2600 121-2200 154-2400 154-2400		48-240 00-260 00	95-3300 96-3800 96-3800	95-3300	95-3300	95-3300 95-3300 95-3300 96-3300	95-3300 95-3300 95-3300 95-3300 95-3300	95-3300 100-3800 95-3300 100-3800	95-3300 100-3800 95-3300 100-3800	95-3300 00-3800 40-3300 40-3300 40-3300
	Number, Diameter an and snd and snd Leagth	7-3x11. 7-3x11. 7-3x11.	44447 99999999	00000000000000000000000000000000000000		alama e	3-2-49x4 3-2-49x4	200	200	2-2-87x 3-2-49x 4-2-87x 4-2-87x 4-2-87x	2-2-40 4-2-8-40 4-2-8-40 4-2-8-40 4-40 4-40 4-40 4-40 4-40 4-40 4-40	3-2.87x4 3-2.87x4 3-2.87x4 49x4	4-2.87x4 3-2.49x4 3-2.49x4	3-2.49x4 4-2.87x4 2-2.87x4
Di	Covernor Standa	NNN KKK	200054 200054 NNNN	**************************************	日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日	S KKKK	XX XX	ZZ	800 2Z	ZZZZ	XXXXXX	ZZZZ	ZZZZ	ZZZZ
TRANS-	Make and Model	NP-38110 NP-38110 NP-38110	NP-39670 NP-39670 NP-38910 NP-38100	Fu 5B330 FU-5A430 Fu 5A63 Fu 5A620 Fu 5A650 Fu 5650	00000000000000000000000000000000000000	u 5A65\$ u 5A650 u 5A650 u 5A65\$	Own 51Y Own 51Y	Own 51Y Own 51Y	Own 41T Own 41T	Own 41T Own 41T Own 41T	Own 41T Own 41T Own 41T Own 41T Own 41T	Own 41T Own 41T Own 41T	Own 41T Own 41T Own 41T	Own 41T Own 41T
_	Forward Sp'da	25 25 25 25 25 25 25 25 25 25 25 25 25 2	44044 40044 50044 51044	######################################	######################################		3 0 4 4 0 0 4 0 0 Wn		4 Own	4444 0000 H H H H H	444444 00000 HHHHHHH	0000 HWWW HWW	00444 00004 naw	0004 0000 0000 0000
REAR	Make and Model	C-1000 C-1000 C-300	Own T-148 Own T-148 Own T-150 Own T-150	H100 Q300 Q300 G-300 U-200 U-200	3347DPH E300DPH H300DPH	3200P 3300P 3200P	SERD SRD	SRY	11	7RT 7RT 7RT	7RT 7RT 7RT 7RT 7RT	7RT 7RT 7RT	TRTM 7RTM 7RTM	7RTM 7RTM 7RTM
R AXLE	Gear and Type	HYF H	HYF H HYF H HYF H HYF H	PER PRESENTA	A LA	HANN H	22 22 23 24 24 24 25 24 25 26 26 26 26 26 26 26 26 26 26 26 26 26			2000 2000	28 28 28 28 28 28 28 28 28 28 28 28 28 2	20000	SF HH	HHHH THHHH
CE CE	Gear Ratio	66.8-9	600000 000000 000000		20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	6.53-8	3.73	**	5.0	2000	0000000 000000	25555 4444 6665	2000000 2000000 2000000	20000000000000000000000000000000000000
104	witner on a fi	.1. Tim	88 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	20 15 15 15 11 53 11 83 11 88 11 8 11 8 11 8 11 8 11 8 11 8 11 8 11 8 11 8 11 8 11 8 11 8 11 8	2201718883771888837718888377188883771888837778888377788883777888837778888377788888377788888377888888	08 53 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	68 OWB 68 OWB	.68 Own .68 Own	83 Own 83 Own	67 Own 67 Own 67 Own 67 Own	67 Own 67 Own 67 Own 67 Own 67 Own 67 Own	67 OWB 67 OWB 67 OWB	1110 MINIOWIN	OWN OWN OWN
FRONT	Make and Model	32516A1 35020-NX9 35020-NX9	T-148 T-148 T-150 T-156	32502 32502 32502 28450 26450 26450 26450	30000HX 30003H 30003H 3100H 32100H 32514H 32	36021TW 36021TW 36000TW 36000TW	SRC SRD SRD	SRY	22	7RT 7RT 7RT	7RW 7RW 7RW 7RW 7RW	7RT 7RTH 7RTH	TRTH O	7RW 00
-	Make Location Type Operat'a	041HV 041HV 041HV	04IHV 04IHV 04IHV	LAHLY Weally Weally Weally	141HV 174HHV 174HHV	W41A W41A V841A V841A		041H 041H	04IH 04IH	00000 00000 000000	AEHHHH HHHHHH	9000 HHHH	04HTV 04HHV 04HHV	04IHV 04IHV
BRAKES	Operation Area Area Area Area Area Area	428 428 4353	888888 888888 888888	992220	2227 2428 2428 2428 2428 2428 2428 2428	7 2222	167			8888	8888888	8888	2222	3002
SS	Area Drum Material	988 770 770 770 770 770	479 479 609 609 609 609	83311664A 331116AAA	48820 8820 8820 8820 8820 8820 8820 8820	000000	264 Co 264 Co 264 Co			0000 00000 00000	888888	0000 00000 000000	0000 0000 00000 00000	00000
-	Hand Location Type	XXX	XXXXX	XXXXXXX	KKKKKKKEKKEE		M2 48 M2 48 M2 48	M2 48 M2 48		XXXX 8888	TX 60.0 TX 84.0 TX 108.0	XXXX	XXXX 8822	77. 77. 77. 77. 77. 77. 77. 77. 77. 77.
	C-A Dimension (Min. Std. W. B.)	000 000 7777 XXX	27.7.4.2 22.2.2.3	20 20 20 20 20 20 20 20 20 20 20 20 20 2	2000 2000 2000 2000 2000 2000 2000 200		88 88 88 89	06 6x2 06 6x2	067x2 067x2		06723/x.21 06723/x.21 067.08x2.8x 067.08x2.8x 8.17.08x2.8x	28+ 7x2%x.21 28+ 7x2%x.21 64+ 7.08x2.8x	8888	9000
FRAME	Side Rail Dimensions	x3x10 x3x10 x3x10	SCHOOL STANKER	THE HAME	HUNDHANNING COME	O MARO	92 22 XX	747	XX HH	XXXX	********	**************************************	.08x2.8x .08x2.8x .08x2.8x	7x2%x.2 7x2%x.2 7.08x2.8x

FEB



EXIDE BATTERIES... for extra power, peak performance and low cost per mile of operation

You gain in many ways when your trucks are equipped with Exide Batteries. Operation and maintenance costs are reduced to a minimum. Replacements are less frequent. And you can count on added months of dependable service. For into each Exide Battery goes 60 years of battery building experience.

Thousands of fleet owners... with both Diesel and gasoline engine powered trucks... have learned that they can count on

their Exide Batteries for dependable performance, long life and low, over-all battery costs.

IMPORTANT NEW FEATURES

Heavy, oversize

Greater capacity

Self-cleaning, non-spitting vent plugs.

Double insulation

"Bull's Eye" electrolyteleveling device.

Larger, heavier inter-cell connectors.

Hard rubber container.

Positive cover seals.

THE ELECTRIC STORAGE BATTERY COMPANY, Philadelphia 32

Exide Batteries of Canada, Limited, Toronto

grans. Spicer 6231B. three forward 31x.125, Inside Siderall from Front

wheel bases—10x3 1/5 x 1/4.

82.

Page

(Turn to

-	Lype	-		• ••••••••	:	::::		
FRAME	Side Rail Dimensions	1000	5000	######################################	Mark Mark Mark			4444444444
		9233	0000	2	9 % x3	None None None	HANN HANN HANN HANN HANN HANN HANN HANN	A WANTER HANDER
	Type C-A Dimensions (Min. Std. W. B.)	855.	855.	g 8 32 888822824	72 72 70		- 00 20 00 00 00 00 00 00 00 00 00 00 00	79577777777777777777777777777777777777
	Material	XXX		S XXXXXXXXXXXXXX		FXXX	: XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
KES	Mum Area Drum	2222	729 729 729 729 729	080474000000000000000000000000000000000	020	4788 47788 7448 7448	4822 Var. 4822 Var. 4822 Var. 5584 Var. 5584 Var. 5584 Var. 5584 Var. 5584 Var. 5584 Var. 5584 Var. 6484 V	~~~~~~~~~
BRAKES	Operation	350 350 350	4855	11 4 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5			20000000000000000000000000000000000000	2524 6424 6540 77224 6540 7722 7728 7728 7728 7728 7728 7728 772
	Location	HAA	04IHV 04IHV 04IHV	B41H [141H [141H [141H [141H [141H [144HV [144HV WW41A WW41A BW41A BW41A	MIA S4IA		### ##################################	
	Make	222	000	141H 141H 141H 141H 141H 141H 164H	22	HH124 H166 H166 HHHH	1141 1141 1141 1141 1141 1141 1141 114	LURRERLURRER
PRONT	Make and Model	11EQ	750	F50 F150 F150 F150 F150 F750 F750 F750 F750 F750 F750 F750 F7	36000T	F30B281 F30B281 F30B281	20000000000000000000000000000000000000	35011H 36000TW 36000TW 36000TW 35011H 35011H 5600TW 6600TW 77554W 77554W
		Own	Own		題	SESS C		
	Geer Ratio Range in High		00000	20 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	.84	0000	000000000000000000000000000000000000000	200000000000000000
VXLE	Drive & Torque	600	HH 6.5 H 6.5	######################################		NNN NNN NNN		7. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2.
REAR A	Gest and Type	222	00 00 00 00 FFFF 7	222222222222		ZZZZ	PARTHARAMANA NO DOCUMENTAL SALES	EE C C C MMMMMMM
2	Meke and Model	900	100H	R1050 R1050 R1050 R1150 R1150 R1560 R1560 R100 R100 R100 R100 R100	U200P 58415P	800 8000 1000 8001	15.5447—28.00 17.5347—28.00	Q100DPH1 R100DPH1 29200P 29200P 29721W 977H 1377
		6000	50wn 7 50wn 7 50wn 7	20000000000000000000000000000000000000	Tim U	Own 60 Own 60 Own 60	25.55.47 25.55.47 25.55.47 25.55.47 25.55.47 25.50 2	IN O 100 100 100 100 100 100 100 100 100 1
NO.	Forward Sp'da			######################################	410	***	. <u></u>	######################################
TRANS-	Make and IsboM	7EQ	л 750н п 750н п 750н	M. HD8-B M-HD8-B H	7841 5A620	2222	T197 T197 T197 T197 T197 T197 T197 T197	440008444868888888888888888888888888888
	Covernor Standa	- 444	Y Own Y Own Y Own	000000000000000000000000000000000000000	BL Fu	SZZZ A	62566666666666666666666666666666666666	Fu 55A
- 1	Diameter 25 and		87x5.0 87x5.0	4444		7777 10000 1		KKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKK
	Number, 98	2000	0000	00000000000000000000000000000000000000	7-4×x16 7-3x11×	7799		CONSTRUCTOR HINES
eņ.	Max. Brake H.P. at R.P.M. Given	45-3600 45-3600 45-3600	145-3600 145-3600 145-3600		50-1800	77-3200 77-3200 91-3200 91-3200	8 888888888888888888888888888888888888	
DETAILS	Torque lb. ft.	515151 515151	4255142551425514255142551425514	000000000000000000000000000000000000000	000	184	44-4833333323232322222222222222222222222	2200130 2200130 2200130 2200122 2200122 2200122 2200122 220130 220122 200122 200122 200122 200122 200122 200122 200122 200122 200122 200122 200122 200122 200122 200122 200122 200122 200122 20012 200
	Displacement Comp. Ratio	3337	3376. 3376. 3376.	77556666666666666666666666666666666666	5255.5	2245 2456.5 2456.5	44444444444444444444444444444444444444	00000000000000000000000000000000000000
ENGINE	Cylinders, Bore and Stroke	22.22 24.24 24.24 2.2.22	33,5x4% 33,5x4% 33,5x4%	THE RESERVE TO THE TENES OF THE	10 1	lacalata A	Jahalalalalalalalala	4400000440000000
-	No. 01		8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8		947	00000 4 000000 0 000000 0 000000 0 000000 0 000000	pppppppppppppppppppppppppppppppppppppp	11141444444
	Make and Model	888 888 888 888	8EQ 8EQ 178	Own GRD214 Own GRD214 Own GRD214 Own GRD214 Own GRD214 Own BLD260 Own BLD260 O-RED 361 O-RED 361 O-RED 450 O-RED 460	B6 255	TYPESSES AND A STATE OF THE STA	22222333277777777777777777777777777777	6MZA 6MZA 6SBKR 6SBKR 6SBKR HB600 6MZA 6MZA 6MZA 6MZA 1450K 1450K
		OWN	DWD DWD	Own G Own G Own G Own G Own G Own H Own H Own H Own H	Cum HBC Bu LO522	Her OXC3 Her JXE3 Her JXE3	Own GC 245 Own GC 245 Own GC 245 Own GC 245 Own GC 225	Wau 6M Wau 685 Wau 685 Cum Hi Cum Hi Wau 6M Wau 6M Wau 145 Wau 145 Cum He
ES	Muchorized 6 # 9 6 # 9 6 # 9 9 9 9 9 9 9 9 9 9	25/20-10 9.00/20-10 25/10-20 9.00-20-10 25/20-10 9.00-20-10	10.0/20-12 10.0/20-12 10.0/20-12 6.50/16-6	5-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	/22 /22 /22 E			00444400444444
E SIZES	Maximum	00.00 00.00 00.00 00.00	001000	7.00/16-6 7.00/16-6 7.50/16-8 8.25/20 8.25/20 8.25/20 9.00/20 11.00/24 11.00/24 11.00/24 11.00/24	11.00/	0.00.00.00 00	80000000000000000000000000000000000000	888888888888888888888888888888888888888
TIRE	Standard Front and Rear	25/20 25/20 25/20	9.00/20-10 9.00/20-10 9.00/20-10	6.00/164 6.00/164 7.00/164 7.00/164 7.00/164 7.00/20D 10.00/20D 10.00/20D 11.00/20 1	00/20	50/208 50/20D 50/20D	1,000,000,000,000,000,000,000,000,000,0	00/200 00
-	(See definition)	56644 5914488	63939 65439 66939 	22506. 215506. 325556. 325556. 325557. 45557. 565557. 565557. 565557. 565557. 10175111. 12530110.	12200 10 10130 10.	62007.50/ 77007.50/ 79007.50/ 7.50/	2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.	9550100020 9550100020 10550100020 115501100020 115501100020 9550110020 1250100020 11550100020 11550100024 11550100024 11550100024
90[4	Gross Vehicle V		21500 21500 21500 21500	446 652000 65200 6		12700 12700 12900 7		
	Meximum Standard		135 159 195 21 128	11125 122111111111111111111111111111111	215 35	118	1125 1125 1125 1125 1125 1125 1125 1125	175 24000 175 24000 175 24000 175 24000 185 32000 185 32000 185 32000 175 24000 175 28000 175 36000 175 36000 175 36000 175 36000
BASE	Minimum Standard	135	135 159 195 128	10111111111111111111111111111111111111		205 205 109 109	22000000000000000000000000000000000000	44440444440F06
93	Chassis List Pri	2485 25155 25655	3165 3195 3245	815 1005 1005 1005 1145 11625 11625 1005 1005 1005 1005 1005 1005 1005 10				
		8E90-84 8E50-84	H-84 H-84 H-84	KB-1 KB-3 KB-3 KB-3 KB-6 KB-6 KB-1 KB-1 KB-1 KB-11 KB-11 KB-11 KB-11 KB-11 KB-14 KB-16 KB-	585	ZŽŽŽ	184	000 000 000 000 000 000 000 000 000 00
	MAKE	4	8E90H-84 8E90H-84 8E50H-84 (%T. Pkp)	3	th(D).	e. D	458044804480314848488888888888888888888888	HD05 HD06 HD015 HD015 HD015 HD015 HC05 HC05 HC05 HC015 HC015 HC015 HC015 HC015 HC015
	4 2	Ford Control	Cowl. Cowl. Cowl.	333333 3	Kenworth(D)		9	96 99 99 99 99 99 99 99 99 99 99 99 99 9
	Line Number		400 t-	800-146450F880C13	M 3	28 28 29 Mar	01000000000000000000000000000000000000	80000000000000000000000000000000000000
	1							

FEBI



SPARK PLUG DIVISION, CORPORATION GENERAL

		PAGE		COLLE	:::::::::::::::::::::::::::::::::::::::	TED		DL	0	E.F. Patroner		1441444	TL			Q	
PRAME		Dimensions	400 HHH 233	244	********			10	700	######################################	FHHHXHH			100	ZZZZZ DMMMMO	44	
FF		Side Rail	XXX KKH	XXXX 83333 83333 83333	**************************************	5x2 1/4 x 5 1/5 x2 x		9x3x)4	A KZ fr	9x3x 14 9x3x 14 7 4 x3x 14 10 4 x3x 11 10 6 x3x 11 10 15 x3x 11 10 15 x3x 11	9 H 23 x M 10 t x 3 x t 7 x 2 % x t 7 x 2 % x t 5 H x 2 % x t 6 x 2 x x A	8.4 x 3 x 3 x 3 x 3 x 3 x 3 x 3 x 3 x 3 x	10%x34x	9x3 14x 14 9 14 x3 16x 1	4444344 444444 4444444	2 × 2	10%x3%x4 10%x3xx4 10%x3xx4 10%x3xx4 100x3xx4 100x3xx4
(B. W.	C-A Dimensi (Min. Std. W	2000	65% 70 70 70 90 70	2222222 22222222 2222222222 2222222222	-00			100	250888888 7774 9918	· 中央 (-4)		2			28 5 15	
		Type Hand Locati	XXX	KKKK	ZEFETETE	42:		TD 7	4	4444444	2228 : 64	888888888888888888888888888888888888888	08	X 76	444648	42	000 1008 1008 1008
	1	Drum Material	ය ට්ට්		000000000	- et et			3		10日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本	200000000	FD	A TX	000000	B P	CTT ST
CES	31	Drum	227	9999	928 1003 1003 1003 1003 1003 1003 1003 100	220		868	911	807 807 867 867 976 976 1030	563 563 563	867 975 975 975 975 975	12508	984	888893	198 276	15698 18888 16248 1680
BRAKES	SERVICE	Lining	280 280 280	38900	6773 6773 6773 6773 6773 6773 6773 6773	133			210	391 391 512 578 614	2003 3003 1622 18622 18622	9830000 445500000 7455500000	800	644	470 585 585 585 585	118	1082 1092 1092 1080
	SE	Make Location Type Operat'n	LH4IH LH4IH LH4IH	LEHEV LEHEV	W84A W84A W84A W84B W84B W84B	B4IH B4IH		LAIHV	CALL	MANUAL PROPERTY OF THE PROPERT	WARFFF AMERICA	1.411 1.41H 1.41H 1.41H 1.41H 1.741W8 1.741A 1.741A	WS4IA	W84IA W84IA	**************************************	XIII	Wa6IA Wa6IA Wa6IA Wa6IA Wa6IA
t.					WTTI WTTI WTTI WTTI										000000	Inches .	>
AXLE		Make and Model	676461 664452 664452	Ford Ford Chevrolet Chevrolet	23501 23501 2501 27454	F-154		F2090H	1-10	F409	F2090W F3100W M5 M5 O	W312 1700 W700 W700 2200 2200	36000W	F3110W F409CW	THEOLEN	255	36000TV 27452W 27452W F409 F400
			30wn 600wn 00wn	3 Ford	FFFFFFF	Cla F-1			O N	WW IS WELL	000000	00000000	Tim	HILL	000000	Spi	16 Tim 6 Tim 15 Tim 6 Wie 1
	ų8	Gear Ratio Range in Hi	66-6.66 13-8.10	7-6.83		88-5.38 38-6.17		-8.43	2	77.338	\$2000444 \$1000113	20000000000000000000000000000000000000	-6.42	-8.6	000000	55.38	8.15
3	anh		HHH 65.00	20000 00000	********	H 5.38		# h	*	2000 2000 2000 2000 2000 2000 2000 200	*******	********	:	7.33	000000	::	*** **
A AKLE		Gear and Ty	SF SF HyF	8F 8F 8F	SSS BSSS BB	Hy		2F I		25 F F F F F F F F F F F F F F F F F F F	HHHHHHHH	22222222222222222222222222222222222222	2F R	2F R		H 1/4	WYF R BR B
REAR					4								64		***************************************	(X38)	
		Make and Model	665174 665171 676055	R1250 R1250 R1250 R1250	58415P 	Spi 23-1 Tim51540NX3		R2090H	CT-1	H H U 1758 1758	R3100W	W312 W1700 W700 W2200 W2200 W2200	P	1357W 1758W	PACCE BE COME	41-2 51540NX3	T SW3012P Tim SW456P Tim SD462P Wis SD462
			000 W B B B	2000	888888888 888888888	3 Spl 2		Tim	OWIT	THE STATE OF THE S	Ford Ford Ford Ford Ford		U-200P	10 Tim	000000	Spl 4 Tm 5	ME E E E
SO.	•p	Forward Sp'	400	2222						8000000	1010 क क क क क	EEEE5000000	12	100	000000	\$\$ \$\$	222 00
TRANS- MISSION		Make and	673674 674989 674989	& BL & BL & BL	5A430 5A430 5A620 5A650 5A650 5A650 5A650	T96 T90E		Fu 5A43	0000	KKKCHHH	A430 A620	5A43 5A620 5A620 5A620 4A86 4A86 4A86	7741	5A62† 4B86;	PAGGER	190C	5A65* 7741* 7741* n M
		10712100	000	Ford	2222222	WGW					Fu 5A430 Fu 5A620 Ford Ford Ford Ford	EEEEEEEE	Spi 7	Fu 5/	00000	WG T90C	Spi 7
-		Length Governor St	ZZ>	ZZZZ	の466664446 グルグラングルグググ メントントントン	84. NX		3 1/2 Y		HAMAMAM	* EEEEE	尤其五五五五五五五五	X 541	7 7 7	**************************************	2 × ×	HER KER
	Main	Number, Diameter and	60 60 60 4 7 7 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	SIGISION STATES	HAHHHHHHH	2.33xo		76 X	2	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	KENNYK KO	COCOCOCACO COCOCOCACO COCOCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCACO COCOCOCO	41%x16	3x1376	XXHHXX HHMMHH XXHHXX	3315 3315	7-33 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
		CIACH	444		000 000 000 000 000 000 000 000 000 00	-		00 7-2	2	00000000000000000000000000000000000000	8000 8000 8000 8000 8000 8000 8000 800	A SA	-	Po Po	22222 200000 222222	3-20	000 000
S,	'M'	Mer. Brake H.P. at R.P.	80-4000 94-3600 94-3600	00-3800 00-3800 93-3100 93-3100	244684800 -8-648080	63-4000		100-2600	70-10	129-2800 129-2800 129-2800 129-2800 129-2800 130-1800 180-1800	00000000000000000000000000000000000000	39-2500 31-2200 31-2200 50-2200 50-1800 88-2100 80-1800	50-1800	25-2250 50-1800	125-2600 125-2600 125-2200 125-2200 125-2200 135-2000	0001-09	464 200-2600 464 200-2600 464 200-2600 585 186-2000
DETAILS	.3	Torque lb. fe	134 176 176	9222	8888448444 88884484460 84886460	105		280	100	00000000000000000000000000000000000000	293 180 180 180 180 180 180 180 180	255000000000000000000000000000000000000	500 15	368 12	229012 28012 36512 58012 58012	105	464 464 200- 464 200- 585 186- 605 186-
	-	Displacemen Comp, Ratio	1706.5 2266.5 2266.5	2396.4 2356.7 2356.6	5227 5225 5225 5225 5525 6025 6025 6025 6025	346.5		3716.0	0	000000 · ·	4044444	@10101010 · · · ·	17.	75.5	220000	44 6.0 0.0	5 6 6 6
GINE	_	930336	22	エキンズ	XXXXXXXXX	1/2/20		2 3	2	2442888 2442 22 84427 44	40000000000000000000000000000000000000	4883886584 4888886584	8 672	651	232255 232255	134	25,5 25,5 25,5 25,5 25,5 25,5 25,5 25,5
K		Cylinders, Bore and	6-3r4 6-3r4 6-3r4r6	88899 4444 88888	**************************************	4-31/8x4 4-31/8x4		43/4	0-072 X	######################################	**************************************	444444000 22222222 4856666666	476x6	6-4%x5 6-4%x6	111113	4-3 %x4	22/2 22 24/4 20 27/2 23 24/4 24/4
				න නකුතු			-	0 0					\$			44	Transfer Tra
		Make and Model	3M 3M	olet	B6427 22R B6427 1140GK 1140GZ 22R R6572 R6672 R6602	463 2WD		6371	1-13/	Wau BZ Wau MZA Wau MZA Wau BKKR Wau 145GK Bu DC844 Bu DC844	WXLCS	Her WXLO3 Her RXC Her RXCO Her RXCO Her RXLD Cum H8600 Bu MO779 Bu MO893 Bu GDC844	HB600	6SRKR HB600	MZA MZA BRKR 9RKR 145GK	CJ-2A 4WD	00/22 Con R6602 00/20 Con R6602 00/20 Con R6602 00/24 Wau 145GK
			OWB 2	Ford Ford Chevrolet Chevrolet	Con Red 1	Own 4 Own 2		Con B6371	Own 1	A DOCUMENT	Her W Her RO Ford Ford Ford	au Monda	Cum H	Wau 68	Wau M Wau M Wau 89 Wau 14	Own 4	Con RC Con RC Con RC Wau 1
50		(Duals un-		8888		*			-			000000004 800000004 HEHHHCREE			0022222 0024444 000266		000 \$4
SIZES	rear o rea	Maximum Authorized Tire Size	7.00/20 8.25/20 8.25/20	00000	98988888888888888888888888888888888888	7.00/168		10.00/20	8-01/00.8	00000000000000000000000000000000000000	10.00/20 11.00/20 7.50/20 15. 7.50/17	1122.00/20 122.00/20 122.00/20 144.00/20 145.0	11.00/22	11.00/24	10.00/2081 11.00/2081 11.00/2481 12.00/2481 12.00/2481	.00/15	10.00/22 12.00/20 12.00/20 11.00/24
TIRE	D-dual r	Front and Rear	_	2000	88888888			8	0-0	8.25/20D 1 9.00/20 1 11.00/20D 1 12.00/20D 1 12.00/20D 1 11.00/24D 1	00000	0 000			982229		000 44
+	À.	Standard	7.50/178 7.00/20D 7.00/20D		888888888	6.50/158		0.00/20	97/10-2	000000000000000000000000000000000000000	9.00/20D 10.00/20D 7.50/20D 15.0/20D 15.0/20D 15.0/20D	10.00/20 11.00/20 11.00/20 12.00/20 13.00/20 13.00/20 13.00/20 13.00/20 13.00/20 13.00/20 13.00/20 13.00/20 13.00/20 13.00/20 13.00/20	10.00/20D	10.00/20	9.00/20D 10.00/20D 11.00/24D 11.00/24D 11.00/24D 12.00/24D	00/16	10.00/20 11.00/22 11.00/22 11.00/24 10.00/24 10.00/24
	(we	Chassis Welg (See definition	30607. 36307. 39557.	5385 5615 5530 5700	20000000000000000000000000000000000000	*2752 *2788		:		\$8000 \$8050 \$5500 \$700 \$400	48477 49737 2719	22222222	125001	115001	7500 9 10500 11 12000 11 13000 12	*2169 6. *2920 7.	145001 158501 109501 214001
93		Gross Vehicl	13500	18500 18500 18500 19500	000000000000000000000000000000000000000			22000	2,000	17000 20000 20000 20000 20000 38600 415500 41000 41000 41000 164000	24000 49300 9.0 280000 10200 10 13500 48477.1 13500 49737.1 4700 4271915 6800 445007.8	4444	27000 13	36000 13	20000 320000 320000 420000 11 20000 12 20000 13 20000 10 10 10 10 10 10 10 10 10 10 10 10	3500	40000 1450010.00/2 55000 1555011.00/2 58000 1-95011.00/2 58000 2140011.00/2
	- S	DIBDRESS	128 195 195 15 15	194 166 195 180 180 19	\$2555555555555555555555555555555555555	118			00	1156 1156 1156 1156 1156 1156 1156 1156	22 24 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				\$25555 \$2555		2000 45 2000 2000 2000 2000
WHEEL- BASE		Minimum Standard mumizaM	128	1208011	445445444 4444444444444444444444444444			159 Opt		50000 500000 50000	22 158 158 174 158 158 158 158 158 158 158 158 158 158	149 150 205 150 205 150 204 150 204 158 150 160 181 160 181	165 Opt	160 178 167 185	228615	80 80 118 118	189 225 189 225 189 225 Opt Opt
	Prio	Chassis List			65340 65000 65000 72500 72500 72500 72500 72500 72500 72500 72500 72500 72500 72500 72500 72500	11894	_	:	*		HAHAHAH					*1146 *1495	### 00
	-		9000	9000			rive	-		delin no		0.000000	:	100	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		200
		a . el	Cont. 15A-2 M1	1958 1958 1958 1958 1958	D-38 D-38 D-38 D-38	2WL	el-D	22FG	M J-T-	HRG HGG M70 M10D	COMPAND OF STATE OF S	W-312 W-700 W-703 W-703 W-2200 W2201	70DD	DD115	FCK	CJ-2A	Wheele wh
		MAKE AND MODEL	M. Mis	Estell(C) F18-5 F19-5-0 C18-5-0	4	Sd.D	Whe		9		XX -		t(D)2		000000	Jp.	Wh Wh Wh Wh
	,	- 7	Studebaker Cont'd M15A-28 M16(2-Sp)	2000	Ward L	Willys (Sd.Del.) 463 Willys2WD	Four-Wheel-Drive	Corbitt	Douge.	EWD.	200000 2000000	Oshkosh (D)	Peterbilt/D)270DD	Sterling.	Walter	Unv.	Six-Wheelers Sederal Gestal
-	31	Line Numbe	-0000 -0000	4001	800-08450 8	17 W 18 W	F	19 Co	00	18888888 100	3333338 3333338	8888884444 0	44 Pe	45 3te	78488 8550 8500 8	653	55 57 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
													-				

STAINLESS STEEL:

"AMERICA'S BEST TRAILER BUY" SAY EXPERIENCED OPERATORS

... and <u>ONLY FRUEHAUF</u> Builds STAINLESS STEEL TRAILERS!

STAINLESS STEEL Needs No Painting


STAINLESS STEEL More Than Twice as Resilient as High-Tensile Steel

STAINLESS STEEL Stronger Construction Throughout

STAINLESS STEEL Lighter Weight — Bigger Payloads

STAINLESS STEEL Rust-Proof and Non-Corrosive

STAINLESS STEEL Longer Earning Life -



RECENT PURCHASERS OF FRUEHAUF STAINLESS STEEL TRAILERS

* Aluminum & Magnesium, Inc. *
Standard Oil Co. * Midwest Transfer Co. * Haynes Milling Co. * Merchants Freight System * Security Cartage Co. * O K Trucking Co. * Zero Packing Co. * Dittlinger Roller Mills * Twin City Warehouse Grocery * Bos Truck Lines * Red Top Brewing Co. * Producers Produce Co. * Savage Truck Lines * McLean Trucking Co. * Johnson Motor Lines * C-D Motor Delivery * Suburban Motor Freight * Liberty Trucking Co. * National Cooperative, Inc. * Graff Trucking Co. * Adkins Transfer Co. * Columbia Box & Board Co. * Beaunit Mills, Inc.

World's Largest Builders of Truck-Trailers

FRUEHAUF TRAILER CO. . DETROIT 32



Send for Free Booklet "STAINLESS STEEL"



ete vehicle.

Tillige Axle.

Page 86.

9

"ENGINEERED TRANSPORTATION" Fruehauf Tra

	Labe		: cee			دددد	AA 34 33	الله الله الله الله الله الله الله الله
ME		- KEF011		DOFF		#### ####	## 4444444	<u> </u>
FRAME	Dimensions	88 98 98 10 10 10 10 10 10 10 10 10 10 10 10 10	KHHHHHHH	79x3x3x 79x3x3x 19x3x3x 10xx3x3x 10xx3x3x	A Charles to the land	HHHH	ME ME Suppose he was led and led before, and led hel net.	4444444 44664444
in .	flag obig	HHHOOS SOUTH	REPERENCE XXXXXXXX	HHH	de de la contraction de la con	0000	100 100 100 100 100 100 100 100 100 100	**************************************
	1	861110	00000000	*X	222222222	2222	20 00000000000000000000000000000000000	PPP-PP-PP-PP-PP-PP-PP-PP-PP-PP-PP-PP-PP
-	C-A Dimension (Min. Std. W. B.	F##8880 80	2238825	25,88	984784424	9999	000000000000000000000000000000000000000	\$
	Type Location	XXXXXX	5555555		XXXXXXXXX	5555	66 EXXXXXXXXXXXXX	\$3555555555555555555555555555555555555
	Dansterle!			440 :	00000000		** 444444444444	000000000000000000
9	Drum Area	869 111056 11796	-21-21-1 -40400 · ·	808	6086254368 608624368 555554368	734 626 626 626	44 14444444444444444444444444444444444	88200888888888888888888888888888888888
BRAKES	S sork	495 6441 7381 020	92411 92411 92411 92411 92411	503 503 092 10	888 : 888	212 450 100 000 101 101 101 101 101 101 101 1	20000000000000000000000000000000000000	
BE	M animado		19898109	2200	200 20000	2232	20 000000000000000000000000000000000000	20000000000000000000000000000000000000
	Tabe		4222222	44	444444		44 >4444444444	*******
	Make	H41 H61 W6 W4	22222222		L61H L761A L761A L761A L761A L761A L761A L761A	961A 861A 861A 861A	W841A W841A T61HV W861A W861A W861A W861A W861A W861A W861A W861A W861A	######################################
		STEMBE	8888888	MARK	AHAHAHAH	8888	***************************************	**************************************
ni)		999	2222222	M5 M5 F2090W F3200W		>>>>	99 188 8 8 2 2 2 2 2 2	
AXLE	Make and Model	F470 F550 F760 82F 83F	86000000000000000000000000000000000000	720 730 730 730 730 730 730 730 730 730 73	5555555	36000W 27454W 27454W	im 35000 im 36000 a 35011TW a 35011TW a 35001TW a 35001TW a 35001TW a 35000TW a 35000T	Ford Ford Ford Ford Ford Chevrolet C
-		000000	8888888	1100 1100 1100 1100 1100 1100 1100 110		2768	### ##################################	PPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPP
-		000000	2444444	1557 1500 1500 1500	248284884 00000000	PHHH		
	Range in High	16-6 50-7 71-6 15-11	10 00 00 00 00 00 00 00 00 00 00 00 00 0	တုတ်တု	99979999	888	Pop mooooppromprom	000000000000000000000000000000000000000
	Genr Ratio	58. 185			*******	888	8 82421242144	86600044 46604444
VALE	Drive & Torque	₩ ₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩₩	HEREE H			4444	です エナナルエア政権政権政権政権	
	Geer and Type	SF SF WF WF	DAMARE.	2222	######################################	WF	COCCOCCAMANTA SECOCCOCCAMANTA SECOCCOCCAMANTA SECOCCOCCAMANTA SECOCCAMANTA SECOCCAMATA SECOCCAMANTA SECOCCAMANTA SECOCCAMANTA SECOCCAMANTA SECOCCAMATA SECOCCAMANTA SECOCCAMANTA SECOCCAMANTA SECOCCAMANTA SECOCCAMAT	77.44.44.44.44.44.44.44.44.44.44.44.44.4
MEAN			4Thm U200P&** 4Th BW3012PA W 4Th SW4012PA W 4Th SD462 II 4Th SD462 II 4Th SD462 W 4Th SD468 W 4Th SD468 W		<u> </u>	B>>>		
2		RF1450 RF1560 RF1670 SW3012 SW456 SD466	00P 452 122 122 122 123 123 124 125 125 125 125 125 125 125 125 125 125	215	4225222222	SW456W SW456W SW456W SD462W	8D3010 8D454 8D45454 D1555DP 73010PA 73010PA 73012PA 7456P 7456P 7456P 7456P 7456P 7456P 7456P 7456P 7456P 730W 330W 330W 330W 330W 330W 330W 330W	99 4 9944
	Make and Model	RE RE BRE BRE BRE BRE BRE BRE BRE BRE BR	020 W3 W3 W45 W45 W45	SD3	80462 80462 80462 80462 80462 80462	WAS WAS	301 301 301 301 301 301 301 301 301 301	350 350 350 350 350 350
		THE PARTY	B B B B B B B B	Timken Timken Tim SFD154 Tim SD3000		8688	5TIM 8D3010 5TIM 8D454 5T-88015556PH 5T-88W3010PA 4T-8W456P 4T-8W456P 5C-8W1 356W 5C-8W1 356W 5C-8W1 356W 5C-8W1 350W	Ford Cla R1250 Cla R1250 Cla R1250 Cla R1250 Cla R1250 Ford Cla R1250 Cla R1
	Forward Sp'ds	000444 000444	44404440	4400	222222222	2222	## ###################################	40000000004000000000000000000000000000
MISSION							26 66	7
SSI	Model	Own F51 Own F52 Own F54 Spi 7741 Spi 7741	BL 7841 BL 7841 BL 7841 Fu 6A620 BL 7841 BL 7841 BL 7841 FW5A620	Ford Ford Fu 5A430 Fu 5A620	5A650 4B186 4B186 4B186 4B186 4B186 4B186 4B186	5555	Cla 270V&* Spi 6252&* Spi 6252&* Fu 5A43 Fu 5A63 Fu 4B86	Ford BL Ford and BL Ford and BL Ford and BL Ford Chevrolet Chevrol
M	Make and	888777	2000 A 400 0 400 A	PPOO		774	25 4448484888888888888888888888888888888	PPOPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPPP
DIE	Covernor Standa	2XXXX	YAKKY KA		22222222	8888	Transfer & School	22-22-22-25-000000000000000000000000000
			WANT WAY	ZZXX	**************************************	****	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	ZZZZZZZZZZZZZZZ
	bas Leagth	**************************************	ZZZZZZZ EZZZZZZZZZZZZZZZZZZZZZZZZZZZZZ	4418	80000000000000000000000000000000000000	HHHH 6666	84 227200007779999	* * * * * * * * * * * * * * * * * * *
	Number, 9 Z	24444	44464446 2222222	51010100	XXXXXXXXXX	7777	The same relative relative to the	To Ta
	-	00000000	20000000	8822	000000000	00000	00 00000000000000000000000000000000000	00000000000000000000000000000000000000
	Mar. Brake H.P. at R.P.M. Given	1800 1800 1800 1800	50-1800 50-1800 50-2200 50-2200 50-1800 50-2200 50-1800 50-2200	00000	25000000000000000000000000000000000000	18000	200-2800 200	829200000000000000000000000000000000000
	Mer. Besto	924333		9985	*********	500-1	25 88488344888 2 448	මුවල් මුවල් මුවු සු සු සු සු සු සු සු
	Torque lb. ft.	0200000 0200000	80000000000000000000000000000000000000	180 180 390	828286888 838286888888888888888888888888	88888	84 444 6666 666 666 666 666 666 666 666	000000000000000000000000000000000000000
-	Comp. Ratio			@@!\@ 4448		2444	00 0000 -0000 000	4444444400000000
	Displacement	2516.3 3616.3 4516.3 67217.	6722 6722 6722 7722 6722 7722 7722 7722	239	69698888888888888888888888888888888888	6000	00000 100000 0000000000000000000000000	
CINE	Stroke	###### %%	2 %	XXXX	****		72 727 7	<i>%%%%%%%%</i>
	Cylinders, Bore and	HHHHHH	ZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZ	447X	ZZZZZZZZZ	2222	43 4488488888888888	#:-:-#:-:-#:-#:-#:####################
	No. of	100000 144444 477777	IIIIIIII	8800	199991111	IIII	II IIIIIIIIIIIII	and
		BLD250 RED361 RED450 HB600 HB600 HB600		65		0000	10427 R0602 6MZA 6MZA 6MZA 145GK	
	Make and Model	BECO BECO BECO BECO BECO BECO BECO BECO	HB6 HB6 HB6 HB6 HB6 HB6 HB6 LO525	WXLC3	BEEEE 24425	HB600 HB600 HB600 HB600	10427 66622 66622 66824 68824 145GF	22222222
		E E E E E E		22 ES	80000000000000000000000000000000000000		25 C C C C C C C C C C C C C C C C C C C	200000000000000000000000000000000000000
_		OCCOO OCCO OCCOO OCCOO OCCOO OCOO OCCOO OCCOO OCCOO OCCOO OCCOO OCCOO OCCOO OCCOO OCCOO OCCOO OC		Ford Ford Her Her	Her RXLD Bu 6DC844 Bu 6DC844 Bu 6DC844 Bu MO893 Cum 6HBI Cum 6HBI Cum 6HBI	BBBB	COOD IN MAN OUT OF THE COOD IN THE COORD IN	Ford Ford Ford Ford Ford Ford Chevrolet
.	(Dunie un-		222224422	0000			10.00/20 10.	
-	Maximum Authorised Size	8.25/20 9.00/20 10.00/20 11.00/22 11.00/22	2222222	7.50/20 7.50/20 10.00/20 11.00/20	888888888	11.00/22 11.00/22 11.00/22	88 888888888888	68868888888888888888888888888888888888
	a mumixal	1201112			2022422222	=====	00 00	
TIME	Standard WD Front and Fron	255555 255555 255555 25555 2555 2555 2	22224222	2000	044444444	2000	50 00000000000000000000000000000000000	000000000000000000000000000000000000000
	Standard on	00000	88888888	7.50/20D 7.50/20D 9.00/20 11.00/20	888888888	8888	10.00/20 10.00/	00000000000000000000000000000000000000
_ '	(See definition)	035000		2000	804004444	3838 5555	44 000000000000000000000000000000000000	Pro
	Chassis Weight	70107.50/20D 86708.25/20D 1675010.00/22 1655010.00/22 1989511.00/24	12900 14600 15100 17000 14900 14650	\$673 \$6710 \$10600 \$14900	25000000000000000000000000000000000000	16250 17300 17450 17900	131004 115500 11	44444444444444444444444444444444444444
93	for Normal Servi	222000 37000 45000 65000	#4747274 20000000000000000000000000000000	225500 225500 225000 225000	888888888	43000 54000 56000 56000		8888888888888888
ble	Gross Vehicle W			9999 9	47000 2227501 60000 2227501 60000 243004 60000 227501 60000 237001 60000 237004 60000 240004 60000 243004		\$4,000 \$4,000 \$4,200 \$5,200 \$5,200 \$6,000 \$6	######################################
NA.	Maximum Standard	194 223 302 302 302 302 302 302 302 302 302	44464646 61141614	::::	000000000	0000	04	000000101000000101 000000100100000010010
BASE	Minimum Standard	151 161 161 188 203 188 206	18635386337 1935386337	1822	044444444 4467446666	88888	00 4440000000400004	00004040404040404040404040404040404040
					OMMANAMA			
	Chassis Liet Price	3150 4700 7125 12425 13200 15700						
_			Signatura	9900	C A principle of the control	Sec-Est.	E0 0000H1001	P. C.
		£44.400 444.400	225 244 244 255 2825 2825	250 250 250 250 250 250 250 250 250 250	SECOND SE	345DT 345DT 354DT 355DT	C-266 HB8130 HB8130 HB8130 HW8160 HW8235HW8235HW8235HHW8235HHC8160 HC8265HC826	F2X26 2F F2X24 2F F2X34 2F F2X34 2F FXX34 2F FXX34 4R FXX30-0 FXX30-0 C2X36 2F C2X34 2F C3X30-0 C4X30-
	No.	B-6 B-8 B-8 W4 W4 656	5528 5528 5528 5528	FOOTE	2000 2000 2000 2000 2000 2000 2000 200	4448	HHBBS HHDBS HBB HBBS HBBS HBBS HBBS HBBS	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
	MAKE	W.W.	2 000 00	M	W W W	(C)		= 1 1 2 00 00 0
	~ 7	International (2) KB-6F 4R KB-8F 4R KB-1F 4R W4064L W4564OH W6564OH	(D)	(C) CM5-6 (C) CM6-6 (C) CM6-6 (MH440-6 MH-555-6	Oshkosh W703-6X6 (D) W 600BD (D) W 600BDH (D) W 600BDH (D) W 600CDH	Peterbilt (b)	9999	\$0000000000000000000000000000000000000
		The contract of the contract o	B:::::8:	4	0 55	2000	9: E:::88::::8888	E
	Man Number	~66466	P&00-04	2000	202222420V	33008	000 0000000000000000000000000000000000	600000000000000000000000000000000000000

De cal rar is get eas ope the is accelef miner oil

Li op le

tio ha att mi sp

ga co po

Chevrolet Announces Additional Mechanical Refinements for 1948

CHEVROLET has announced major mechanical improvements in its Advance-Design line of trucks for 1948. Most radical change in the medium and heavy-duty ranks is in the 4-speed transmission which is provided with synchro-mesh and helical gears in 2nd, 3rd and 4th speeds to assure easier and quicker shifting and quieter operation. In addition, it is claimed that the necessity for frequent double clutching is eliminated. Shifting into reverse is now accomplished by moving the lever to the left of the low gear position. The transmission is huskier, and the case has been newly designed to reduce the possibility of oil leaks.

Light model trucks have a footoperated hand brake with a hand release located on dash. Provides clear floor space

All standard and regular production option 4000, 5000 and 6000 series rear axles have a newly designed hub-to-axle shaft attachment. Driving torque is now transmitted from shaft to hub through mating splines, external on the shaft and internal on the hub. A bolt-attached cover and



A stronger, better sealed axle attachment. Driving torque is transmitted from shaft to hub through mating splines

gasket are separate from the axle. The cover and gasket are not strained by the power flow from the axle shaft to hub,

with the result that the oil seal is more effective. The new splined axle is easily removed for seervicing.

All heavy-duty series as well as series 3800 now feature a simplified propeller shaft bearing support. The rubber-mounted bearing is a single row type permanently sealed and lubricated. Several changes in the baffle improve sealing against water and dirt. To further prevent the entrance

of foreign materials, traps at each end of the bearing are packed with waterproof grease.

A new 11-leaf rear spring assembly of greater capacity now replaces the former 10-leaf assembly in the 4000, 5000 and 6000 series (4502 and 6702 uses 11-leaf 2-stage spring). Used in combination with the 6-leaf auxiliary spring, a total spring rating of 15,600 lb. for the rear axle is now available.

A new heavier 8-leaf front spring assembly is now standard equipment on all 3100 series trucks. This replaces the former 7-leaf, increases capacity and minimizes bottoming on rough roads.

(TURN TO PAGE 143, PLEASE)



PREPARED TO TAKE PUNISHMENT

To stand the punishment of high-speed, heavy-duty, rough-road trucking, your springs will have to be *mighty* tough. That's why perfected Maremont springs so consistently fill your most exacting bill.

Many, many years of research and experimentation stand behind the spring that bears the Maremont name. The design . . . the select alloy steel . . . the fool-proof heat-treating . . . the rigorous pre-testing . . . these are but a FEW of the features which make the Maremont spring so resilient . . . so durable . . . and so perfectly prepared to take the punishment of fast, modern truck operation!

See Your Nearest Maremont Jobber or Spring Service Station for Springs, Helper Springs, Axle U-Bolts, etc. Ask for Latest Spring Catalog 9720T.

ALSO MANUFACTURERS OF MAREMONT MUFFLERS AND PIPES



1947 New Truck Registrations by Makes by States*

STATE		Auto- car	Brock- way	Chev- rolet	Dia- mond T	Divco.	Dodge	Fed- eral	Ford	FWD	GMC	Inter- na- tional	Mack.	Osh- kosh	Reo	Ster- ling	Stude- baker.	Ward La France	White	Willys	All Others	To
labama	Nov. 11. Mos.	4		910 4929	19 93	8 28	348 2304	15 76	556 3883		149 952	257 2025	10 91		41 264		72 493		19	174	1	2
rizona	Nov.			174	2	2	53	2	88		36	56	1		4		33		169	1080	69	18
rkansas	11. Mos. Nov.	4		1140 368	25 10	12	569 120	18	1051	4	279 54	406 80	12		94	4	293		47	311 72	39	4.
alifornia	11.Mos. Nov.	25	2	4425 1990	83 59	52	1630 716	40 11	3778 951	28	763 464	1423 564	27 38		99	8	483 339	2	59 61	955 246	26	13
olorado	11. Mos.	340	48	13539 192	446	310	8121	162	11766	179	3917	6022	344		497	107	3455	9	565	2084	77 890	52
	Nov. 11. Mos.	27	*****	2112	113	52	76 1076	42	123 2224	74	43 505	90 1341	3 47	2 2	11 106		33 364	9	7	58 676	63	8
nnecticut	Nov.	12 182	132	238 1795	14	17 90	108	20 163	132 1286	10 36	63 457	81 1250	37 262		120	1 6	58 443		7 152	43 400	6 82	
elaware	Nov. 11. Mos.	16	21	51 601	3 20	4 24	49		23		13	28	2		5		6		3	12		0
at. of Col	Nov.	1		80	4	3	465 31	5	613 43	4	154 30	360 25	17		24	2	110	2	28	94	17	2
orida	Nov.	15	19	672 506	42 18	100	474 173	31	704 259		271 66	368 120	29 20		51 19	2	129		. 47	50 105	18 17	3
eorgia	11. Mos. Nov.	37	1	5075 675	174 18	34	2251 225	71	4105 215	35	814 73	1746 141	224 14		214 15		771	4	164	879 74	174	16
tho	11. Mos.	7	2	5856	185	11	2741	63	5180	1	938	2077	162		239	1	711		16 220	934	69	19
	Nov. 11. Mos.	9		153 1414	65	17	56 649	7 55	94 1241	8 14	29 310	82 761	17	1	73	2	373	11777	20	39 418	59	5
inois	Nov.	236	54	1043	65 1038	16 366	381 6025	28 261	411 9200	5 18	143 2232	489 6281	25 380	***	48 745	17	149	3 6	66 658	174 1338	15	3
diana	Nov.	5	8	732	41	10	268	8	210	6	108	323	14		29		148		50	135	371 24	42
wa	Nov.	38	119	5647 596	369	147	3511 193	144	4913 136	37	1333	3848	112	****	414 28	1	1857 62		429 11	1236 135	239	24
insas	Nov.	5	2	4739 433	288 14	59 2	2368 148	61 21	4070 144	18	765 76	3137 199	157	4994	284 17		960 53	2	142	1338 78	77	18
ntucky	11. Mos.	10	1	5020	239	24	1717	155	3831	1	779	2222	48	****	197	1414	868	*****	153	582	68	15
	Nov. 11. Mos.	16	******	543 4431	28 171	19	188 2122	25 127	164 3443	1	78 825	114 2014	9 96	11:11	28 236	****	58 611	*****	10 131	153 1532	99	15
wisiana	Nov.	15		223 3297	33 184	3 19	127 1637	5 48	137 2965	1 2	39 560	83 1542	11 112		13 144		38 621		18 158	144 776	3 26	12
aine	Nov.	2 24	1 32	197	19	5	71	4	91		42	96	9		12	1	27	2	6	49	4	
aryland	Nov.	7	8	1733 318	8	26 3	1005 163	72 10	1832 105	7	414	1003 92	113 12	12	134 16	13	361 46	5	80	333 44	54	7
assachusetts	Nov.	95 12	99	3038 462	76 21	138 31	1885 260	118	2388	****	587 98	1420 170	170 29		232 18	7	529 58	22	145 25	445 28	72 6	11
ichigan	11. Mos.	262 5	239	3488	246	325	2649	100	3765	5	1011	2232	408	2	262	120	784	32	348	516	142	16
	Nov. 11. Mos.	.75	6 56	1035 7193	33 332	28 385	338 5270	57 484	471 7369	3	164 1669	169 2839	18 145	1111	70 771	1	130 1326	17	42 303	230 1755	281	30
innesota	Nov. 11. Mos.	54	2	304 3871	15 192	75	191 2342	15 201	218 4087	32	65 771	203 2509	12 131	7	11		65	17	26 296	118 699	6	1
ississippi	Nov.			773	26		267	5	430		118	185	19		142		855 72		14	96	94	16
iseouri	Nov.	2		4506 776	110 25	3	1763 249	33	3640 289	1	778 131	1418 247	95	1111	120 12		516 87	*****	99 19	858 130	25 15	13
ontana	Nov.	22	9	7349 189	288	100	3239 56	126	6013 95	3 2	1359 32	3347 104	123	1.1.	226 11		1017	4	295	1433	121	25
ebraska	11. Mos.	5		1907	80	3	1031	40	1478	20	342	1025	9	1	82	2	42.	****	61	930	50	1 7
	Nov. 11. Mos.	6	1	316 2638	16 228	17	153 1423	73	112 2358	28	57 541	257 1926	16 145	3	12 135	****	605		211	858	34	11
evada	Nov.	8		43 285	21	1 3	22 221	2	33 295	7	14 84	17 189	1 3		15	2	6 25		10	11 71	25	1
sw.Hampshire	Nov.	22	1 10	68	2	6	35	1	23		12	31	10		3		4		5	10	2	1
ew.Jersey	Nov.	25	62	806 762	28 54	18 34	552 347	17 28	718 368	1	168 215	453 417	125 91		77 32	16	146 115	1	52 50	204 139	38 24	2
ew.Mexico	Nov.	312	495	4639 175	288 12	332	2774 72	184	3801 81	13	1392 36	2645 55	709	2	235	17	874 20	40	400	877 64	213	20
ow.York	11. Mos.		107	1427	68		678	31	916	5	326	528	38		41		221	2	60	216	14	4
	Nov. 11. Mos.	909	107 1422	1101 10479	94 975	61 487	810 8993	29 466	506 9515	16	322 3259	483 6549	185 2050	6 56	88 1026	8 71	204 2141	11 169	67 1275	199 2128	36 542	52
orth.Carolina	Nov. 11. Mos.	5 39	1 15	913 6970	7 128	34	230 2928	15 158	271 5207	11	62	105 1910	23		30		97	1 4	34	137	14	1
orth. Dakota	Nov.			79	10	1	38	6	105	1	636 22	131	346	****	386		1022		305	1449	124	21
hlo	Nov.	27	3	1100	76 35	7 27	735 437	36 36	1455	10	251 225	987 401	37 55	3	40 66		380 154		25 88	415 451	11	1 3
klahoma	11.Mos. Nov.	292	67	9883 433	436	366	6589	394	8716	29	2399	5581	648	1	763	1	1838	19	1195	2761	383	42
	11. Mos.	3		4379	68	39	222 2423	5 54	313 3940	7	98 769	302 2564	9 85	1000	22 188		69 723	4	173	105 915	47	11
regon	Nov.	3 44	1	288 2812	7 218	40	97 1779	11	148 2115	27	87 701	108 1331	11		137	13	718	****	156	55 829	13 153	11
ennsylvania	Nov. 11. Mos.	38 556	83 883	981 9848	46 680	11 152	698	31	533		277	483	116	11	57	3	200	5	112	222	29	3
hode Island	Nov.	16		99	2	7	8038 45	378	9314 50	44	2701 99	6789 41	1054	88	870	76	2388 15	64	1152	2188	380	47
outh Carolina	Nov.	101	7	854 490	44	88	460 167	10	644 212	2 2	199 60	404 60	45 29		34 24	8	147	3	61 15	107 72	30	1
outh Dakota	11. Mos. Nov.	6 2		3121	47 10	3	1565	32	2700	26	436	812	131		203		413		126	645	84	10
ennessee.	11. Mos.	10		97 876	106	3	54 811	43	1020	10	32 245	138 878	31		9 81		32 251	****	40	40 588	11	8
	Nov. 11. Mos.	12	17	713 6753	139	28	253 3122	20 207	152 4677	24	95 1482	158 2721	207		22 296	3	68 836	2	16 281	91	148	22
ixas	Nov.	1	20	1649 14002	24	6	728	15	837		284	688	28		52	1,,,,	198	1	78	312	16	1 4
lah	Nov.			96	333	120	7575 49	156	12115 59	6	2544 32	6512 47	356	1	563	153	2210	6	757 5	3022	194	50
rmont	11. Mos. Nov.	*****	3	1076	45	27	518 48	50	987 41	16	285 13	629 39	31 8	1	19	1	260 11	3	43	2 0	43	1
rginia	11. Mos.	9	32	723	29	11	535	28	801	6	212	494	80	6	118	7	137	13	33	400	34	3
•	11. Mos.	101	62	810 5744	191	13 92	297 2881	20 147	362 5802	3 15	122 908	237 2208	17		31 271	1	93 834	1	33 271	124 1089	174	2
ashington	Nov. 11. Mos.	23	1	350 2993	24 192	7	134 1810	23	180 3176	1 18	80 767	170 1676	10		17	16	60 806		14	50 619	15 173	1:
est. Virginia	Nov. 11. Mos.	23 2 29		181	5	2	83	6	86	14	43	46	18		13		28		10			
(leconsin	Nov.	3	63	1891 539	78 24	35 12	1400 248	102 20	1893 265	65 7	466 83	922 276	87 16	3	137 36	3	378 73	10	101	739 104	68	1
yoming	Nov.	48	*****	4948 64	295	175	2372 36	118	3838 45	116	972 12	2879 43	121	35	340	37	753 11	2	365	856 30	113	1
otalNovn	11. Mos.	1 205	210	705	59	4	391	10	703	4	112	449	17		18		139	5	51	453	17	-
otalNoven	nber. 1947 nber. 1946	285 438	319 344	24518 19649	915 509	404 370	10221 8258	552 420	10945 14375	118 79	4525 3507	9028 7051	981 61	23	1026 1125	47 41	3458 2406	33	1074 1186	4936 3815	429 524	6
ital 11. Mor	-16- 4649	4036	3930	207870	9769	4522	118481	5537	181527	1116	44640	104650		222	11952	545	38393	474	12084	45324	6261	81

^{*} Data.f:om.R.L.Pofk.&.Co.

REVOLUTIONARY ADVANCEMENT*

in

WARNER ELECTRIC BRAKES





16½"x5", 16½"x6"**, 16½"x7" Sizes

Two-Shoe Construction

For More Effective Stopping Power!

These big, new, powerful Warner Electric Brakes — with their two-shoe hinge construction, incorporate the most modern and advanced brake engineering — and provide an entirely new concept of effective stopping power.

INSTANTANEOUS, POSITIVE ACTION As with all Warner Electric Brakes, positive-acting braking power is developed within the brake itself. Because the braking mechanism is *electrically controlled*, there is no time lag. Regardless of distances from cab to rear trailer wheels, any amount of stopping power is *instantly available*. Even with this remarkably fast action, the larger, wider, two-shoe brake operates with velvety smoothness never before achieved in brakes of any other type.

UNMATCHED ECONOMY The new Warner Electric Brakes are inexpensive to install. Use only as much current as a tail light. Require minimum servicing thus preventing costly delays and tie-ups of equipment.

CONTROLLED BRAKING POWER Driver can pre-set "Vari-Load" dial on dash to meet load and road conditions.

SYNCHRONIZED OPERATION WITH EITHER AIR OR HYDRAULIC SYSTEMS Warner Controller synchronizes hydraulic, vacuum or air brakes on tractor with Electric Brakes on trailer. Regular tractor foot pedal then



SINCE 1927

ASSURED DEPENDABILITY The new two-shoe Warner Electric Brakes assure years of dependable operation. Warner Electric Brakes have been performance-proved by leading tractor-trailer operators during many years of efficient, trouble-free service.

GREATER SAFETY When both the tractor and trailer are equipped with Warner Electric Brakes their instantaneous "stopping power" under absolute control assures greater safety. All brakes "come in" at the same instant, but with varying amounts of power. Therefore, rear trailer wheels get the effect of coming in first — and the tendency to skid or jackknife is prevented, thus giving greater protection to the driver and load — and avoiding costly repairs or tie-up of equipment.

For maximum performance and satisfaction, standardize on Warner Electric Brakes. Write for illustrated literature explaining all their many advantages.

WARNER ELECTRIC BRAKE MFG. CO. BELOIT, WISCONSIN

Specialists in the manufacture of Electric Brakes since 1927

*REVOLUTIONARY ADVANCEMENT

More rugged construction, rigid shoes, longer lining life, smoother control and dependable performance under severe conditions.

No other brakes equal the new Warner Electric Brakes for simplicity of design and construction. Full clearance under tractor and trailer — nothing to get knocked off, leak, chatter or freeze. No exposed braking equipment — no rods to rattle — no tubes to split — no troublesome boosters and hose connections. One rugged all-purpose Electrical Cable Connection provides contacts for brakes, running lights, parking lights, stop and turn signals — ALL electrical contacts. As easy to plug in as a radio.

** Available September 1



SAE TRANSPORTATION MEETING TO PRESENT TIMELY SUBJECTS

The National Transportation Meeting of the Society of Automotive Engineers, to be held at the Bellevue-Stratford Hotel, Philadelphia, Mar. 30 to Apr. 1, will include functions of both the Transportation & Maintenance and the Truck & Bus activities of the SAE. Gavin W. Laurie, Manager of Automotive Transportation, Atlantic Refining Co., will be the general chairman.

Principal papers to be presented and the speakers are:

Tuesday morning, Mar. 30: "Progress in Insulating of Busses," by K. L. Raymond, GMS Truck & Coach Division.

Tuesday afternoon: "Operating Experience with Weight-Reducing Materials in Vehicle Design," by J. L. S. Snead, Jr., Consolidated Freightways.

Wednesday morning, Mar. 31: "Improvement in Design & Maintenance of Electrical Equipment," by J. A. Bolles, Delco-Remy Division.

Wednesday afternoon, "Comparative Performance of Fuel Injection vs. Carbureted Gasoline Engines," by George M. Lang, Ex-Cell-O-Corp.

Thursday morning, Apr. 1: "Modern Sealed Cooling Systems," by S. M. Young, Young Radiator Co.

Thursday afternoon: "Experience with Apprentice Training," by A. W. Newman, The Willet Co.

'47 NEW TRUCK REGISTRATIONS ESTIMATED CLOSE TO 900,000

New truck registrations for November totaled 73,737 units, and for the first 11 months of 1947, 811,442. With estimates for December running slightly ahead of the November figure, it is expected that total new truck registrations for the year will approximate 900,000. Production for domestic use estimates place the 1947 truck total at slightly under 1,000,000 vehicles. For breakdown of new registrations by state and by make, see page 90.

HARVESTER BUYS METRO

Purchase of the principal stock ownership of the Metropolitan Body Co., Bridgeport, Conn., by the International Harvester Co. was announced Jan. 10 in a joint statement by W. C. Schumacher, general manager of Harvester's motor truck division, and Philip and William Carlson, president and vice-president, respectively, of the body company.

DATES & DOINGS

MAR. 30—APR. 1—National Transportation Meeting, Society of Automotive Engineers, Bellevue-Stratford Hotel, Philadelphia, Pa.

APRIL 1-3—Louisiana Motor Transport Assn. convention, Heidelberg Hotel, Baton Rouge, La.

APRIL 13-16-18th Annual Safety Convention of the Greater New York Safety Council, in the Hotel Pennsylvania, New York City.

APRIL 24—Illinois Motor Truck Operator's Assn. annual banquet, Palmer House, Chicago, Ill.

MAY 6-8-Washington Motor Transport Assn. convention, Davenport Hotel, Spokane, Wash.

MAY 21-22—Associated Motor Carriers of South Dakota convention, Alonzo Ward Hotel, Aberdeen, S. D.

JUNE 11-12 Pennsylvania Motor Truck Assn. annual meeting, Penn Harris Hotel, Harrisburg, Pa.

JULY 16-24—Road Show, American Road Builders' Assn., Soldier Field, Chicago, Ill.

OCT. 8-13—American Trucking Assns, annual convention, Hotels Statler and Mayflower, Washington, D. C.

PIGOTT NAMED SAE HEAD



R. J. S. Pigott

Reginald James Seymour Pigott, who since 1929 has been chief engineer of Gulf Research & Development Co., Pittsburgh, Pa., was introduced as 1948 president of the Society of Automotive Engineers at the annual meeting in De-

troit on Jan. 14. He has been an SAE member since 1918 and was a councilor in 1945 and 1946. He is also director of Automotive Engine Projects for the Coordinating Research Council and chairman of the CRC Engine Section.

The 1948 treasurer is B. B. Bachman, vice-president in charge of engineering, Autocar Co. SAE vice-president for Transportation & Maintenance is Warren A. Tausig, Burlington Truck Lines, Inc., while Dale Roeder of Ford Motor Co. heads the Truck & Bus activity.

GAUSSOIN REAPPOINTED

Julius Gaussoin, of the Silver Eagle Co., Portland, Ore., has been reappointed chairman of the Equipment and Maintenance Committee of the American Trucking Associations, Inc., by Ed J. Buhner, president of ATA. Mr. Gaussoin is also active in the work of the Society of Automotive Engineers and is chairman of the Maintenance and Equipment Committee of the Oregon Motor Transport Association.

ICC TO INVESTIGATE LEASING, SETS APRIL 19 FOR HEARING

Division 5 of the Interstate Commerce Commission has ordered a thorough investigation of the truck leasing practices of all motor carriers coming under its jurisdiction and has scheduled a public hearing for 9.30 a.m., April 19, at the ICC offices in Washington, D. C., before Examiner C. Evans Brooks.

The investigation will cover these categories of truck leases or rentals: (1) those made between for-hire carriers for the purposes of augmenting equipment, (2) those entered into for the interchange of equipment by for-hire carriers, and (3) those calling for the rental of motor vehicles and equipment to private carriers or shippers.

The rules adopted by the Commission in this proceeding will be applicable to all agreements, contracts or leases entered into between common or contract motor carriers subject to the general provisions of Part 2 of the Motor Carrier Act, and between such carriers and private motor carriers or shippers. However, they will have no valid application to any leasing arrangement between one private carrier and another.

The Commission's tentative proposals covering vehicle rentals to private carriers and shippers would impose the following restrictions, among others, upon for-hire carrier lessors: (1) Prohibit rental of equipment with drivers; (2) Prohibit leasing of equipment without drivers unless (a) period of lease is for 180 days or more, (b) lessee has exclusive use of the equipment during the entire leasing period, (c) lessor removes all marks of identification from the vehicle, (d) the terms and conditions of the lease agreement are reduced to writing setting forth the charges to be made, the method used in computing such charges, the definite period within which the lease is effective, and a complete statement of all other terms affecting the rental service.

INDUSTRIAL NOTES

Auto-Lite Battery Corp. has completed plans for a new manufacturing plant at Clearwater, Cal.

Highway Trailer Co. has announced plans for locating its factory service department in Chicago, rather than at the plant in Edgerton, Wis. It is expected that the new location will speed up delivery of parts throughout the country.

The Linde Air Products Co. is building (TURN TO PAGE 94, PLEASE)

See MIDLAND for





Air Brake Kits



Slack Adjusters



Vacuum Brake Kits

THE MIDLAND STEEL PRODUCTS COMPANY

6660 MT. ELLIOTT AVENUE . . DETROIT 11, MICH.

CCJ Newscast

(CONTINUED FROM PAGE 92)

a new oxygen filling station, acetylene producing plant and warehouse at Little Rock. Camcar Products Co. (screw products)

has completed a new plant at 600 18th Ave., Rockford, Ill.

The Ohio Crankshaft Co. has purchased the Induction Heating Division of the Budd Co., located in Detroit, for use by its Tocco Division.

Socony-Vacuum Oil Co., Inc., is rehabilitating its refinery in East St. Louis, Ill., as part of a \$45,000,000 expansion and improvement program.

LEE HEADS ICC FOR '48

Commissioner William E. Lee has been elected chairman of the Interstate Commerce Commission for the 1948 year, succeeding Commissioner Clyde B. Aitchison. A former chief justice of the Idaho Supreme Court, he was first appointed to the ICC in 1934.

SAFETY NOT BUILT-IN

Latest statistics comparing death rates on the Pennsylvania Turnpike with similar rates on other highways confirm the view that safety cannot be "built-in." While death rates for the last six months of 1946 compared with the first three months of

1940 for the nation's highways as a whole declined from 11.5 to 10 per 100 million vehicle miles, and from 10.5 to 8 on Pennsylvania highways, the Turnpike rate went up from 9.5 to 13.8. Furthermore, since pedestrians are not allowed, it is assumed that the Turnpike figures include foot traffee while all the other figures do. It is estimated that such inclusion would make the Turnpike totals about 25 per cent worse.

1947 Truck Trailer Production*

	November	11 Mos.
Vans:		
Insulated and refrigerated		1,771
Furniture		973
All other closed top	1,226	17,440
Open top	36	1,537
Total Vans	1,406	21,721
Platforms:		
With cattle and stake racks		3,150
With grain bodies	83	1,196
All other	482	7,445
Total Platform	765	11,791
Tanks:		
Petroleum	275	2,063
All other	30	832
Total Tanks	305	2,895
Pole and Logging:		
Single axle		3,946
Tandem axle	62	1,442
Total	208	5,388
Low-bed heavy haulers	142	2,298
Off-highway	35	794
Dump trailers	16	602
All other trailers	124	1,363
Total Trailers	3,001	46,852
Chassis for trailers	265	3,147
Total Trailers and Chassis	3,286	49,999

* Data from Industry Division Bureau of the Census

TEAMSTERS-OPERATORS CONFERENCE ON SAFETY

A forward step in encouraging highway safety was taken in Los Angeles in January when 50 leading Teamsters Union officials and motor carrier operators sat down for a day-long discussion on how to improve truck safety through labor-management cooperation.

The conference, the first of several contemplated, was sponsored by the Western Highway Institute, coordinating agency for the for-hire trucking industry, in cooperation with the Motor Truck Association of Southern California and the Truck Owners Association of California.

Chairman of the day was R. H. Cutler. Portland, who heads the Institute. Frank W. Brewster, Seattle, acting for Dave Beck, Director of the Western Conference of Teamsters, headed the Teamsters' delegation. In a statement issued at the close of the meeting Mr. Cutler said, "The discussions between labor and management at Los Angeles have been so cordial and mutually satisfactory that we are determined to have at least two regional-level meetings between the groups each year. The possibilities for improving safety through joint action are practically unlimited."

(TURN TO PAGE 216, PLEASE)





AMERICA'S PATTERN of better living is cut from steel. Literally, from countless kinds of steel. For everything... from plowshares to skyscrapers... pipelines to hypodermic needles... calls for special steels... and

special steels ... and in vast quantity.

Truck transportation adds new flexibility to steel delivery -from mill and warehouse direct to the job. And, as in the steel industry itself, a great deal of versatility is required to perform each specialized transportation service efficiently. It is another vitally important field in

White

which White Super Power is the choice of the leaders because Whites assure distribution efficiency in any truck-using business for many more years of service at lowest cost. Your White Representative will gladly explain the cost-reducing Correct Application method of fitting trucks to your work requirements and acquaint you with the many advantages of White Super Power.

THE WHITE MOTOR COMPANY

Cleveland, Ohio, U. S. A.

THE WHITE MOTOR COMPANY OF CANADA LIMITED

FOR MORE THAN 45 YEARS THE GREATEST NAME IN TRUCKS



... DEAN B. COPELAND as president of the American Bantam Car Co., succeeding Francis H. Fenn who died Nov. 29. Jerome P. Bowes, Jr., is the new chairman of the board, and STANLEY WINKLER is vice-president.

... F. W. SOMMER as treasurer and T. V.

Homan as secretary of Mack Trucks, Inc., succeeding C. W. Haseltine, retired.

...E. G. Lyons as manager of Highway Trailer Co.'s Buffalo branch and J. W. DIBBLE as manager of the St. Paul branch.

...John J. Peterson as Buffalo branch manager for the Trailmobile Co.

...H. C. PANNEBAKKER, JR., as temporary Detroit sales manager for the Strick Co., succeeding Elsworth J. Tackaberry, deceased.

...W. F. HUNT of Hot Springs, Ark., as district manager in Arkansas, Eastern Oklahoma, and Northern Louisiana for Van Norman Co. He will assist RAY RAY. MOND, who has been promoted to Mid. South Division manager.

...G. E. TENNEY as service manager of The Lincoln Electric Co.

... GEORGE MYERS as Hagerstown Plant Manager for the Perfect Circle Corp. succeeding GEORGE KEAGY, retired.

... ALLAN RAE as Toronto Branch Manager of A. Schrader's Son Division, Scovill Mfg. Co., succeeding S. A. Howell, retired.

... C. W. GRANGE as director of public relations for Stewart-Warner Corp.

... W. EARL GIVENS. JR., former chief of the Personnel Safety Section, Department of Safety, American Trucking Associations. Inc., as director of Safety and Personnel for the Geo. F. Alger Co., Detroit.

... WALTER HOLLAND, assistant manager of the Field Service Department of the American Trucking Associations, Inc., as executive secretary of the District of Columbia Trucking Association, succeeding W. EARL GIVENS, JR., resigned.



as general sales manager of the Dodge Division, Chrysler Corp. He was former Detroit sales manager.

KELLY, JR., as first vice-president of the American Brake Shoe Co. He is also president of Kellogg and Engineered Castings Divisions.







... HARVEY E. SCHACH (left) as sales manager of Power Brake Division, Midland Steel Products Co. A. R. LEUKHARDT (right) is new asst. sales manager.

(TURN TO PAGE 226, PLEASE)



Profits Come From Economies

When you lick underinflation, you've made a real saving on your tire costs. To make certain there's no air-loss through tire valves, see that a Schrader Cap is screwed down fingertight on every valve. Its powerful sealing unit guarantees an air-tight valve mouth up to 250 lbs. pressure.

Don't wait until your valve cores are worn out. Replace them. Also make it a habit to check tires regularly with your own reliable Schrader Gauge. Correct pressures at all times increase tire economy and reduce the number of costly roadside flats.

Schrader Caps, Cores and Gauges give your tires extra miles—boost your profits. See your regular supplier today for your needs. To get the best—always specify Schrader.

SCHRADER CAPS, CORES AND GAUGES MAKE TIRES LAST LONGER!



A. SCHRADER'S SON, Division of Scovill Manufacturing Company, Incorporated, BROOKLYN 17, N. Y.
World's Largest Manufacturer of Tire Valves, Gauges and Accessories

6 Years . . . Over 260,000 miles with no interruption in service ... for Unit equipped with

Y.

mi

re


re

nt ie!

ia

MI.

vit



The WAGNER Rotary Air Compressor

Check these features that are so desirable in Automotive Air Brake Systems: Rotary motion of all moving parts ... In running balance at all times... Longer belt life due to more uniform torque loading...Low friction losses -therefore high operating efficiency ... A predetermined air pressure range automatically maintained ... Operating parts are lightly stressed, thereby insuring long life and low maintenance cost... Extremely quiet in operation... Self-contained oiling system—uncontaminated by engine waste products...Compact—requires minimum installation space...Low operating temperature prevents carbon formation in the compressor and delivery lines...
Adaptable to all types of automotive systems

Wasner Electric Corporation

PUGET SOUND POWER & LIGHT COMPANY


Wagner Electric Corp. 1918 1st Ave. South Seattle, 4, Wash. Gentlemen:

Att: Mr A. P. Nelsen

It occurred to me you would be interested in the performance of an AF1001 Wagner Rotary compressor used since April 15, 1941 on a KS8 1941 International Harvester tractor. This tractor pulls a 24 foot semitrailer over all types of roads here in Western Washington, hauling all kinds of line material, heavy transformers and other apparatus to jobs located in many off-the-highway places. Needless to say, thoroughly dependable air brakes such as Wagner builds are

It is a pleasure to report that, as of April 1st 1947, the Wagner compressor has operated for over 260,000 miles with no interruption in service. We replaced the inexpensive control valve diaphragm twice during all that mileage and then did not lay the compressor up. Such performance you may be assured, is a real relief and satisfaction to both driver and superintendent.

Very truly yours





The enthusiastic praise in this unsolicited letter is typical of what users say about Wagner Air Brakes — The only Air Brakes that have the famous Rotary Air Compressor.

These outstanding air brakes can help you, too, in lowering your brake maintenance costs. Get complete information today. Write for Bulletin KU-50B.

Electric Corporation

COMMEED HYDRAULIC BRAKE PARTS and FUULD - NORAL COMMA BRAKE LINING - AIR BRAKES - TACHOGRAPH ELECTRIC MOTORS - TRANSFORMERS - INDUSTRIAL BRAKE



K48-3

Reflective Materials

(CONTINUED FROM PAGE 59)

curate to one 10,000ths of an inch) at the factory and because of this factory application it is claimed that the uniformity is virtually perfect. The sheets are available either with the adhesive already applied or with a separate adhesive, the latter being recommended for application on porous surfaces. The plastic base is

supplied in a wide variety of colors which show up in color in daylight and reflect the same brilliant color at night. It also comes in neutral shades that reflect a brilliant silver at night. It is available in both regular and wide angle types, the latter particularly suited for curved surfaces. To achieve either lettering or special designs the sheets are cut to proper size and shape and affixed to any smooth background. The reflective material may also be painted over with opaque paint to produce reverse

color effects. Both treatments may be noted in the accompanying photographs.

Another inherent advantage of "Scotchlite" is the fact that it can and is now being produced on thin flexible fabric strips which may be sewed onto clothing fabrics. A panel of the material thus applied as decorative trim to a driver's uniform can offer life-saving protection when he dismounts at night, and it is already being widely used as a protection to traffic police and others on the highway at night.

Prismo Kit

THE Prismo Kit, on the other hand. contains the binder and spheres in separate containers together with a special applicator which may be either air or hand-powered. The binder is applied by brush or spray gun using stencil or silk screen to achieve the desired effect. Then while the binder is tacky, the spheres are sprayed on to the saturation point. It is claimed that the process is economical, requires no special skill and is as permanently attached as any good paint job. Control over the amount of spheres applied is said to be foolproof, due to the fact that up to the saturation point the spheres will adhere evenly and that beyond it they fall off harmlessly. Color effects visible both by day and at night can be achieved by introducing any desired tint into the binder before it is sprayed on.

In using the Prismo Kit for the reflectorization of highway signs State and County Highway Departments report from five to seven years' reflective durability. They also report a material cost of about seven cents per square foot for this application. The application work with the Kit involves very little more than an ordinary enamel coating operation with no additional equipment required.

Millions of Spheres

UNDER headlights at night, these materials reflect light brilliantly, directionally and in full color. Brilliance and directional control are achieved by the millions of tiny glass spheres. Serving as lenses, the spheres concentrate the reflected light, preventing diffusion. In addition, the lenses focus the light directly back toward the source of illu-

(TURN TO PAGE 100, PLEASE)



Added to lube oil, gas and all gear greases, MARVEL MYSTERY OIL gives battery-saving summer action to winter starts, and eases sub-zero shifting and steering. It adds motor-protecting toughness to thinner cold weather lubricants, and puts an oily armor on top cylinder parts that operate HOT all winter long. MARVEL cleans, too . . . prevents gum and varnish from building up and stealing power. Remember MARVEL when you think of oil, gas and gear greases, and let its sensational total action be YOUR answer to total winter lubrication needs. Emerol Manufacturing Co., Inc., 242 W. 69th St., New York 23, N. Y.



BARRETT

hin be

Co

al-

the

nd, in

be he

to en

al

ed

An Opportunity To Become A Brake Specialist

BRAKE SCHOOL







THE BARBETT BRAKE SCHOOL began operation in March with a specially selected group of experienced instructors of the highest calibre, and the finest of modern equipment. It is devoted to the training of men who service brakes.

Applications for this specialized brake service training should be made to your nearest Barrett Jobber, or direct to the Barrett Brake School. No tuition is charged while pilot classes are in operation.

BARRETT BRAKE SCHOOL

DIVISION OF BARRETT EQUIPMENT COMPANY . 21ST & CASS . ST. LOUIS 6, MO.

Reflective **Materials**


(CONTINUED FROM PAGE 98)


mination, the headlight beams of approaching traffic.


Applied to trucks and buses, the materials can be used to outline the size of the vehicle, to display the company name, to provide a reflective barricade on the tailgate or on rear doors, and to provide brightly legible warnings such as "DANGER, EXPLOSIVES," or "CAUTION-SCHOOL BUS."

Although they derive this "lightedup" appearance from approaching headlight beams, they are visible far beyond the apparent length of the beams. For example, a square foot of silver "Scotchlite" reflective material can be seen on a normally clear night more than 1500 ft. away. Larger applications, such as on tailgate barricades, outdoor advertising signs and traffic signs, can be seen at even greater distances.

Whatever the material, it is im. perative that the reflective particles of glass be perfect spheres. A glance at the accompanying diagrams will show the reason. A perfectly flat sur.







face will reflect light back at an angle equal to the directed ray. Thus as soon as the light of an on-coming car becomes even a small number of degrees away from a direct right angle to the flat surface, its reflected rays would be entirely diverted. If, on the other hand, the reflective surface is irregular there is no control of the reflection at all—there being two reflections, one specular, the other reflex—and both wild. But with the true sphere, light is reflected back from point "A" directly toward the point of origin. The returning ray carries the color of the pigment "B."

Werner Experience

SPEAKING for "Scotchlite," Morris P. Greenberg, maintenance superintendent for Werner Transportation Co. of Minneapolis, which

moves over 26,000,000 lb. of freight monthly, has this to say:

"At night when you see tail lights ahead, they look a long way off. But before you know it, you're on top of them. 'Scotchlite' on a truck ahead of you gives you a pretty good idea of its size and makes it easier to estimate how far ahead he is. Then you can slow up and approach him gradually-and in slippery weather, especially, that pays dividends in safety."

(TURN TO PAGE 102, PLEASE)



BEARING

Eberhard

HINGES LATCHES DOOR IRONS DOOR CONTROLS DOOR HOLDERS **SEAT IRONS** LOCK HANDLES SEAT PEDESTALS

LOCKS

REFRIGERATOR PANEL DOOR VAN BODY SLIDING DOOR ROPE HOOKS LADDER HOLDERS

FOR SOLID OR FOLDING DOORS

Smooth in action and quiet in operation.

Over-center locking action with no set screws required. The rod is adjustable 1/2 inch in length.

The handle has two pivot holes permitting a 1 inch variation in throw. Can be adjusted to either 4 inch or

3 inch center of hinge bolt to center of bolt rod.

Finishes are plain or chromium.

Side Door Controls, like every EberHARD-WARE item, are "purpose-tested" and built for long life under the most severe conditions of usage.

A copy of the new Eberhard Catalog will be mailed to you upon **Fixed Escutcheon** Lock Handle No. 5653

Attractively designed to blend with present day streamlined bodies. Escutcheon permanently attached to handle. Can be mounted vertically or hori-

BERHARD MANUFACTURING CO. 2734 TENNYSON ROAD, CLEVELAND, OHIO



PISTON RING HANDBOOK

will sur.

gle as

of

ght

If, irrol

he lut ed

> New 40-page handbook to help you turn out better work, easier and faster. Write for free copy or ask your jobber salesman.



HASTINGS

STEEL-VENT PISTON RINGS

Generous Wall Lubrication Always Under Control

Reflective Materials

(CONTINUED FROM PAGE 100)

Asked what his drivers think of it, Greenberg commented, "They like it. And a lot of people who know us and who have seen our trucks on the road, write letters to us, asking about it."

The Werner Co. operates about 225 units of equipment, including 110 semi-trailers on the Minneapolis-

to-Chicago run. First application of "Scotchlite" was in May, and since then a total of 25 semi-trailers and tractors have been reflectorized, with the remaining semis scheduled for the treatment, Greenberg said.

On the tractors, the application consists of strips of silver on the bumper guard, and panels of the same material on the back of the rear-view mirrors.

On the semis the application includes silver panels 6 in. wide, applied on the curved front corners.

with the name "WERNER" and the truck number painted on the reflec. tive sheets with No. 71/2 blue. The side of the semi carries an arrow nearly the full length of the body. with the edges of the arrow reflector. ized with 1-in.-wide strips of blue. Framed inside the arrow is the name "WERNER" made of cut-out "Scotchlite" silver letters. The rear of the semi is outlined with 2-in. wide strips of silver around the sides and top. with a "WERNER" panel extending across the back and a smaller panel, immediately below, carrying the truck number.

Throughout the application, the Werner Co. used wide-angle "Scotchlite." Although both wide-angle and regular "Scotchlite" reflect directly back to the source of light, the wide-angle material has the additional value of reflecting brightly from all parts of a curved surface. It will reflect traffic headlights from any angle of approach up to about 80 deg. to either side of head-on. The "regular" reflects to a motorist approaching only from an angle of zero to 15 deg. from head-on.

The wide-angle material, available in the "Scotchlite" factory-coated sheeting, was preferred because of the curved surfaces that were to be covered, and because of the desire to achieve maximum reflective protection for the truck at all times, whether moving on a straight-away, or turning, parking or backing.

Two types of applications were tested—use of a sheeting pre-coated with a pressure sensitive adhesive, and use of a sheeting applied with a separate "Scotchlite" adhesive. (The pre-coated variety is available only for the wide-angle product.) The Werner Co. settled on the pressure-sensitive sheeting, on the ground that it is easier to apply.

However, 3M laboratory men pointed out, where large areas are to (TURN TO PAGE 104, PLEASE)





"DULUX" Gives Protection Plus!



You find fewer candidates for the paint shop when your fleet is protected with tough, durable "DULUX" Enamel! For years the No. 1 choice of fleet operators, "DULUX" proves itself on the road—by keeping its handsome gloss and color longer, despite severe weather and rough handling.

It's this extra wear that spaces your repaint jobs at wider intervals. You can measure it in miles or years—or in good, hard dollars! Either way, you'll find it good business to place your order for "DULUX" today.

E. I. du Pont de Nemours & Co. (Inc.), Refinish Sales, Wilmington 98, Delaware.



AUTOMOTIVE ENAMEL

BETTER THINGS FOR BETTER LIVING
... THROUGH CHEMISTRY

FEBRUARY, 1948

d the

The arrow body, ector-blue, name t-out rear

2-in.sides anel

d a low.

the

tch.

ngle

dithe ddihtly

ont

The ap-

of

ble

of be

to eces, iy,

Use postage-paid card inserted at page 61 for free information on advertised products

103

Reflective Materials

(CONTINUED FROM PAGE 102)

be covered, as in the case of a barricade-type application on the rear end, the uncoated product may be preferred. The pre-coated "Scotchlite" involves an immediate, tight bond, the moment it is applied, requiring careful application. With widths of 6 in. or less, this involves no difficulty. But with larger widths,

use of a separate adhesive is recommended to insure satisfactory results. (The adhesive is provided without charge.)

Application with a separate adhesive is accomplished by spraying or by flowing the adhesive from a brush on to either the "Scotchlite" or the surface to be coated. It should dry for 15 to 25 min., until the adhesive remains tacky to the touch but does not stick to the fingers. Then apply the material lightly. If it is incorrectly positioned, it can be removed by a

sharp jerk, prior to rolling it down.

Once applied, "Scotchlite" is permanent, can be removed only by use of a commercial stripper. Recommended for the purpose is Kleen Strip, made by William Barr Co. of Memphis.

ar

ro

181

m

80

di

of

th

pa

ez W

A

m is w

to n b

Noerr Experience

COMMENTING on his use of the Prismo process, Floyd B. Noerr of F. B. Noerr & Son, a common carrier firm, Lewistown, Pa., had this to say:


"Prismo reflective material was first applied to one of our trailer units on an experimental basis just one year ago. Increased visibility of the unit at night was at once apparent and the added safety factor is obvious. After a year of use, including both summer and winter operation wherein the unit was subjected to all elements and regular periodic washing, we are entirely satisfied. Wear on the reflective surface is negligible and we expect shortly to equip many of our over-the-road vehicles with the product.

"As will be noted in the accompanying photographs the application on our trailer includes diagonal striping on the tail gate, a broken line around the lower edge, front corner marking and name plates.

"Even when walking in a dimlylighted parking lot where this trailer is parked alongside others not coated with the reflective material, the effect is at once notable, as the trailer stands out in sharp relief. We believe the product is very worthwhile from the safety standpoint."

END
(Please resume your reading on P. 60)





Toll Roads

(CONTINUED FROM PAGE 48)

are part of their business expenses.

In the third place, because free roads paralleling turnpikes must someday be improved to handle regular traffic demands, despite the abovementioned state unwillingness to do so, the turnpikes ultimately face financial trouble. A toll road can only draw traffic when it offers the vehicle operator conditions much better than those on free roads. When the paralleling free road, in time, comes to rival the turnpike's advantages, the turnpike faces financial disaster.

What will happen when toll roads go broke, as most of them can be expected to do, soonor or later? Why then, the states in all probability will have to take over their debts. An unfortunate aspect of this is that most toll roads are built with bonds issued at a higher interest rate than would be available if they were a direct state obligation. If the state takes over the toll road, it takes over not only these high-interest bonds, but it also takes over a stretch of road that may not be practically engineered for free-road use, and that may require new expenditures to make it generally useful.

If this is the ultimate fate of some of the toll roads being considered today, thoughtful men may well wonder why states don't avoid the whole process and build the needed roads with their own credit, if that is the alternative.

(There is, of course, great question whether that is the only alterna-

n

)

Guerra.

"I'm sure he's in there somewhere— I heard a voice!"

tive to toll roads. Highway users are more than paying their way in this country today. In the past, the taxes they pay have proved adequate to buy adequate roads. Many believe they are sufficient today, if the funds do not fall victim to diversion and dispersion.)

Toll roads pose another immediate and major problem. They may interfere with completion of the great proposed Interstate System of free highways.

This system, which is to be built

GATKE

Custom-Bilt

BRAKE BLOCKS

and LINERS

for

Cars • Buses • Trucks

Tractors • Trailers and

all other equipment

with Federal and state funds, would make toll roads unnecessary, because it meets all the problems of traffic and congestion and road improvement that toll roads are supposed to meet. But in at least two states, existing or proposed toll roads would lose traffic to such competition. As a result, vital links in the Interstate System may not be built.

If this happens, everybody loses—including those two states.

END

(Please resume your reading on P. 49)



long hauls or heavy traffic GATKE CUSTOM-BILT Brake Blocks help maintain schedules and reduce maintenance cost.

The smooth, non-grabbing action adds countless miles to tire life with reduced strain on drivers and equipment.

Dependable holding power at all service temperatures—no letdown in heavy traffic or long grades.

The Extra Wear Life keeps brakes safe for the road with fewer adjustments and reduced maintenance.

Make this simple TEST. Use GATKE CUSTOM-BILT Brake Blocks for your next five relines and compare results.

Ask your GATKE Jobber or write.



Centralized Equipment Control

(CONTINUED FROM PAGE 39)

to service floor, between service line or floor and the dock are made except as directed by the Equipment Coordinator.

The Coordinator normally reports for work at 3 a. m. daily. He immediately lists all equipment presently within the area on his equipment register, noting thereon the load and whether LTL, frozen, full load or empty.

The "Big Board"

THIS "equipment register" is really in three parts. First there is the "big board" which forms the heart of the system. As will be noted in the accompanying illustration (Fig. 1) it is arranged to correspond with the actual lay out of our Portland property. A numbered tag is provided for each vehicle and sufficient pegs are provided in each area

so that tags may be placed to correspond with the vehicle's actual location at all times.

The term "H. H." in the upper left hand corner stand for Heavy Hauling Equipment (e.g., flatbeds, lowbeds and equipment needed for crane-loading, etc.). The blocked out area below merely signifies execu. tive office space. The blocks labeled "City Pick-up on Line Rigs" and "City Deliveries on Line Rigs" reg. isters the over-the-road equipment being used for pick-up and delivery of large shipments. Local pick-up and delivery units are excluded from the Coordinator's control. A separately colored tag is used to indicate equipment licensed in each of our five zones. When a piece of equipment is under way its tag is removed from the main board and placed on one of the five zone panels, two of which may be seen at the extreme left of Fig. 1.

The other two parts of the registering operation consist of appropriate entries on Forms 665 and 676 (Figs. 2 and 3) one indicating arrivals and departures at the shop, the other at the dock. As will be noted in the actual entries shown, the two forms must correspond, line for line.

Methods of Tabbing Equip.

GETTING back to the functions of the Coordinator, to arrive at the equipment within the area when he goes on duty; the Coordinator registers all equipment, as reported in on the daily schedule and loading report that arrives after the last outbound schedule departs. As a check on this figure, he compares this with the list of inbound equipment prepared informally by the night hostler which shows unit number and type of load.

After 4 a. m. and until he goes off shift, the unloading foreman checks each inbound unit at the scale house and reports unit numbers and type of load to the Coordinator. After the unloading foreman goes off shift, the floor foreman checks arrivals and reports as above.

Beginning at 4 a. m. when the service line goes into operation, the Coordinator routes across the service line enough units to fill the pits, choosing these with the thought in mind of clearing as many to the dock for unloading as possible, be-


(TURN TO PAGE 110, PLEASE)

V-8 VALVE JOBS MADE EASY!

WITH Johnson
ADJUSTABLE
TAPPETS

Do the job right! Install Johnson Adjustable Tappets in Ford and Mercury V-8's (85-100 HP engines). No expensive shop equipment is needed. Installations are made in half the ordinary time and without the task of fitting valves. Special spanners are included with each set of tappets, leaving both hands free for quicker and more





accurate adjustments. Each tappet maintains its setting and gives many thousands of miles of superior engine performance.

The millions of Johnson Tappets in use today are giving dependable service and providing smooth, quiet engine performance.

You'll find that you will make larger profits and gain more satisfied customers when you install Johnson Adjustable Tappets.


AVAILABLE AT N.A.P.A. WAREHOUSES AND JOBBERS







CASE 1018—PROLONGING BEARING LIFE IN HEAVY-DUTY ENGINES.



ut

u-

nt

ip

te

ur

h

n

of

te

er

In toughest operating conditions, specially compounded RPM Heavy Duty Motor Oil maintains lubricating film on bearings. For both gasoline and Diesel engines. Comes in five grades: SAE 10 to SAE 50.

- A. Contains anti-corrosion compound. Won't pit or honeycomb copper-lead, cadmium-silver or any other bearing metals.
- B. Detergent keeps all oil passages and parts clean. Assures adequate supply of oil to all bearings, prevents ring-sticking and slow action of parts.
- C. Adherence to metal surfaces, whether hot or cold, minimizes both running and starting wear. Film stays on idle parts and protects against rusting.

Other compounds in RPM Heavy Duty Motor Oil and natural qualities of selected base oils resist oxidation, formation of sludge and prevent foaming.

CASE 1027—LUBRICATING GEARS WHERE MANUFACTURER REQUIRES STRAIGHT MINERAL OIL.



Highly stable RPM Gear 0il did not form objectionable deposits in cases in toughest operating conditions. Recommended for both marine and automotive power-transmission gears requiring uncompounded lubricant. Comes in three viscosity grades: SAE 90, 140 and 250.

Made from the finest paraffinic lubricating stocks. Resists high pressures and temperatures and rapidly carries away and dissipates heat.

Inhibitor breaks up air bubbles - prevents foaming and helps resist oxidation.

A. RPM Gear Oil sticks tight on gears, and bearings in gear sets and extends their lives - oil film cushions shocks, prevents metal-to-metal contact and reduces wear.

The several grades of RPM Gear Oil provide lubricant for different seasons and climatic conditions.

For additional information and the name of your nearest Distributor, write

STANDARD OIL COMPANY OF CALIFORNIA

225 Bush Street, San Francisco 20, California

The California Oil Company 30 Rockefeller Plaza, New York 20, N. Y.

The California Company
17th and Stout Streets, Denver 1, Colo.

Standard Oil Company of Texas





rademarks Reg. U. S. Pat. Office

Centralized Equipment Control

(CONTINUED FROM PAGE 108)

fore 6 a. m. Units with LTL and rush deliveries are routed across first. The empties are kept in reserve on the service-ready line to fill in whenever a slack period manifests itself.

Arrivals later than 6 a. m. are immediately classified as to type of cargo. Light loads and rush ship-

ments should be routed to the dock and immediately stripped for release to the shop. Empties should be placed on the service-ready line.

A careful watch on the flow of units through the shop must be kept by the Coordinator in order to keep the flow steady. More units than can be handled quickly should not be released to the dock prior to service. This holds true of the shop.

The hostlers move equipment only upon orders from the Coordinator. The only exception is on moves from the service line to the service floor which may be ordered by the service floor foreman, and from one stall to another at the dock which may be ordered by the dock foreman or one of his assistants. The Coordinator designates areas in the South lot for the parking of full loads, rush loads, empties and out of service equipment.

Each morning the Coordinator confers with the service floor foreman to determine the time necessary for service and/or repairs on each unit for that day. He then confers with the equipment foreman on the dock to determine the time required for unloading or delivery. He then notes, under the appropriate column, the priority of dispatch on form number 450 (Fig. 4) which should be the approximate time the unit will be serviced and unloaded and ready for final release for loading.

As a general rule, 1 hr. and 15 min. should be allowed for service of a unit. If the mechanical repairs necessary to release the unit ready for the road can be made in not over 1 hr. and 30 min., including mechanical work, the unit may be moved from the service line to the floor without direction from the Coordinator. This move must be effected immediately after service work is completed. If a longer time is required, the additional time must be approved by the Coordinator. This, oftentimes, necessitates the return of a unit for mechanical work after service work has been performed and after unloading at the dock.

YOU BY STANDARDIZING on Airco Nos. 87, 90 and 230 Electrodes (A.W.S. Class. E6011-12-13)

Here are three A.C.-D.C. electrodes that meet approximately 61% of all general-purpose, mild steel welding requirements of garages and repair shops.

Airco No. 87, 90 and 230 produce weld metals of high mechanical properties. Their excellent slag coverage results in an unusually smooth deposit, with easy slag removal. Airco No. 230, for example, has a specially formulated coating that produces a spraying type of arc. This is of great assistance in the performance of vertical and overhead welding, permitting high welding speeds with excellent deposits.

All three electrodes are recommended for normal or high speed welding in the flat, vertical or overhead position and are known for their:

...Low Spatter Loss

... Light, Easily Removed Slag

... Unusual Smooth Weld Deposits

... Excellent Operating Characteristics

But learn all about these generalpurpose electrodes for yourself. Ask for Airco Electrode Catalog No. 120A. Just fill in and mail the coupon for your copy. Address: Air Reduction, General Offices, 60 East 42nd Street, New York 17, N. Y. In Texas: Magnolia Airco Gas Products Co., General Offices, Houston 1, Texas. Represented Internationally by Airco Export Corp.



AIR REDUCTION

Offices in All Principal Cities




Headquarters for Oxygen, Acotylene and other Gases . . . Carbide . . . Gas Welding and Cutting Apparatus and Supplies . . . Arc Welders, Electrodes and

Reporting Movements

AFTER the Equipment Coordinator has the available equipment tabulated on his register and the flow is started through the plant, each movement must be reported to him in the following manner through the intercommunication system.

The service floor foreman must report the time each unit is received on the service pits. He then reports the time each unit leaves the grease pits. If the remaining work can be performed within the time limit prescribed above, he does not report the move from the pits to the service floor. He does, however, report the time each unit clears the floor. His report should indicate whether the unit is finally cleared or whether it

(TURN TO PAGE 112, PLEASE)



More "Frigid Freight" rolls in these Lightweight Brown Trailers

• "We consider Brown Aluminum Trailers the very finest equipment available today for hauling perishable food products," reports the National Tea Company. And to prove that they mean it they have just added 10 new Brown Aluminum Trailers to their fleet.

Durability, general performance and weight saving are the reasons for their choice. A Brown is the lightest, high-quality trailer you can buy. Lightweight aluminum alloy plus frameless, airplane-type monocoque construction makes a Brown as much as 20% lighter than most conventional lightweight trailers. Take a minute to figure for your-

self what this extra weight in the payload will mean in profits for you. For complete details on Brown Aluminum Trailers see the Brown representative in your area or write us.

Brown Trailers are insulated with 3" of fire resistant cotton that is 2 to 10 times lighter than most standard insulation. The natural reflective qualities of aluminum create additional insulating efficiency.





the Tale...Lightweight means more Freight



Sales and Service in: Seattle, Spokane, Los Angeles, San Francisco, Denver, Minneapolis, Kansas City, Chicago, Salt Lake City, St. Louis, Ft. Worth, Jacksonville, Great Falls, Akron

m

of

ly

of

ts

Centralized Equipment Control

(CONTINUED FROM PAGE 110)

must return and the approximate length of additional time required.

When the shop releases a unit to the dock, the dock in turn reports the time received and to which operation assigned (e.g., unload at dock or city delivery), also approximate time involved. The Coordinator advises whether the unit must return to the shop and for how long. The dock must promptly report to the Coordinator all units that are emptied. The elimination of delay in reporting empties as soon as unloaded is extremely important.

A unit dispatched on a city delivery must be reported and the time dispatched. Upon its return the equipment dispatcher reports it in to the Coordinator. The same holds true on city pickups.

The Equipment Coordinator records all times on his register. If a unit is longer than the estimated time as given by either the service floor foreman or the equipment dispatcher, the Coordinator will check on its movement through the intercommunication system.

The success of this system depends on current, accurate time reports being given on all movements by the shop and dock. No equipment must be allowed to remain on side streets or alleys around the terminal, or at the dock or the shop without reporting, immediately. City drivers must be properly instructed and impressed with the need of reporting delays and arrivals. Hostlers must keep very much in evidence and be used for no unauthorized moves.

The Portland Transport Dispatcher should line his equipment up for the day's dispatch only after conferring with the dock foreman and the Equipment Coordinator. In this connection, special attention must be paid to the column headed "Dispatch Priority" on form 450. Wherever possible, equipment, upon which a great deal of work is necessary, should be sent on a short run (e.g., Kennewick on Montana equipment). This brings it back early the second morning and allows two full days for the shop. After units are once allocated to schedules, no change will be made by either the dock or dispatcher, without approval from the

In the assigning of equipment on runs, the dispatcher will be governed strictly by the latest equipment list showing the zones in which the equipment is licensed for operation.

Equipment Coordinator.

Priority Runs

PRIORITY must be given the long schedules, particularly those operating to Montana which transport all freight for Minneapolis, Chicago and beyond. If delays are necessary, the shorter schedules such as Oregon local or Seattle (6½ hr.) must suffer.

We are constantly experimenting with new ideas to increase the efficieny of the Control Room, and at the same time aid the shop and dock in the problems that continually confront them. Changes are being made in work schedules both in the shop and dock to fit the ever-increasing demands for better service to the customer.

END

(Please resume your reading on P. 40)



Another Moog Triumph!

FULL DRESS for FULL POWER

To fully emphasize the Extra Quality and Outstanding Performance of Moog X-Plus Full Power Piston Rings, a smart, colorful new metal foil package packs the Full Power set-up. Truly, tomorrow's rings today in tomorrow's package today!

See the best looking package for piston rings...Try the best performing piston ring...Give your customers a Full Power overhaul backed by 10,000-mile or one-year guarantee. Order from your jobber.



MOOG PISTON RING COMPANY Division: MOOG INDUSTRIES, INC. ST. LOUIS 14, MO.

COPYRIGHT 1947 M. I.I.

or

ck

da

st ta at t.

ed

ad ry

p n-

d

h T a ٧,

d T

d

t

Prompt CONNECTING ROD Accurate EXCHANGE SERVICE

Rebabbitted . Reconditioned



This convenient Federal-Mogul service provides you with both rebabbitted and reconditioned rods that are restored to original specifications. I Rebabbitted rods have new piston pin bushings. Pure new babbitt is securely bonded in place, accurately machined, with oilways carefully regrooved. Reconditioned rod forgings have bores that are truly round, refinished accurately and smoothly for new precision insert bearings. I You can buy these rebabbitted and reconditioned rods outright or on an exchange basis for popular numbers. It pays to use flawless rods. Ask your Federal-Mogul Jobber!

FEDERAL-MOGUL SERVICE DIVISION FEDERAL-MOGUL CORPORATION

COLDWATER, MICHIGAN



The complete line-over 7000 numbers:

Engine Bearings • Bushings • Connecting Rod Exchange Service • Reconditioned Connecting Rods • Rebabbitted Connecting Rods • Connecting Rod Bolts and Nuts • Bearing Metals • Laminated Shims • Solders.

Splash Guards

(CONTINUED FROM PAGE 35)

The conventional guard used is one designed by Kenworth. It extends back 6 ft over the set of four wheels, angles down 45 deg for 24 in. over the rear wheels, and then drops 14 in. to the required 16 in. from the ground. Rear wheels of the truck and the trailer are equipped alike.

Still another type of guard is that used on dump trucks. Of the ten

dump truck fleet operators queried, three used canvas for their guards, two used leather, one belting, and four used the rubberized war surplus material described above.

The size of the guards and method of installation was pretty much standardized: Guard, 23 in. wide; 26 in. long (length differing with the make and size of truck). In most cases the guard is bolted to a steel cross member, using a metal strap 1 in. wide and from ½ to 3/16 in. thickness—four bolts to each guard.

What Operators Think of Their Splash Guards

Few of the fleetmen questioned were very enthusiastic about their splash guards. Some of them, particularly the dump truck users, felt that the guards materially hampered their operation. On the other hand, one very large over-the-road freight operator had been using guards long before they were required by law.

When asked directly whether they felt the guards were an added safety factor, however, all said "no." Commented one: "If you are close enough to a truck in the rear to have spray thrown on your windshield, you are too close for safety!" Said another: "With splash guards it is impossible to pass a truck in wet weather without having your windshield splattered with the side angle flush forced out by the guard."

Another was more explicit: "I have come to the conclusion that we must do something more than installing fenders or flaps . . . reduced speed in wet weather is the answer . . . This is

difficult but we have a bonus system that gets our drivers to give us some cooperation . . . I have little faith in flaps or fenders but I do believe they have a public relations value. I personally recommended passage of the bill before the committee at the Ore-

gon Legislature for this reason only."

No dump truck fleet operator reported the guards a success. They blocked view in backing, caused side splash, and were of no value in preventing rocks from flying back on gravel roads.

Same Story In Oregon

THE law became effective on Sept. 1, 1947. Notification was not by letter but through the press. The regulation covers all trucks except: "A motor truck chassis not equipped for hauling a load, or a truck equipped with bunks (a logging truck)."

It requires that the splash guard come down to within 10 in. of the surface of the highway when the vehicle is empty for all motor trucks not equipped with a body. The law (regulation) goes on to require:

(regulation) goes on to require:
The words "Logging Trucks" were
not included in the exemption and it
(TURN TO PAGE 116, PLEASE)




This well-illustrated, 16-page booklet, written in non-technical language, has been designed and produced to tell the TANDEM story simply and pictorially.

A request, and the booklet is yours without obligation.



"Now I understand Why the country's top fleets depend on Daytons for real service!"



Over 50% of the fleets winning maintenance awards in 1947 specified Dayton Truck Belts!



For that extra margin of service on all accessory truck drives—Daytons are Champion Milers! Raytex-Fortified with specially-processed Dayton rayon cord—Daytons outperform all others, even on the toughest hauls. For instance: The Capital Transit Company of Washington, D. C., winner of the Bus Transportation Maintenance Award for 1947, reported that Daytons averaged approximately 35,000 miles per belt on its fleet of 1015 buses. A bonus of 14,900 miles over the life of the average public utility bus belt, as shown by a recent survey!

Take advantage of this Dayton bonus of mileage and service. Get the facts from your jobber, or write direct to Dayton Rubber, Dayton, Ohio.

TRUCK BELTS by

Dayton, Rubber

For Service That's Traditional with Truckers

Splash Guards

(CONTINUED FROM PAGE 114)

required a ruling of the state's attorney general to exempt these, which was given in the following paragraph:

"It is my opinion, therefore, that logging trucks equipped with bunks are excluded from the operation of chapter 550, Oregon Laws 1947...

(signed) . . . George Neuner, Attor-

ney General."

According to the State Highway Department of Oregon, splash guards were installed on 90 per cent of all vehicles covered by the law before the law became effective.

Six oil transport fleet operators in Oregon were interviewed as to kind of material used and method of installation and also as to the value of the guards.

Four of the six used light weight (3/64th in.) aluminum sheet for the splash guard frame above the guard, fastened on to an angle iron frame

with ½sth in. heating hose, split and riveted through the angle iron frame and the aluminum. The splash guard itself was made from composition shoe sole material manufactured for the Russian Army during the war. This composition leather comes in sheets 24 by 24 in. square and it requires 3 sheets to make two guards. These guard flaps can be made from this material for approximately 75 cents each. However the complete installation, including labor runs around \$25 per set of two guards.

Six motor freight operators were queried. Of these, three used the composition shoe leather material. One used the surplus airplane rubber, dressed up for appearance, stability and reflective value, with stainless steel strips. Another used canvas, and one operator had purchased a supply of war surplus belting.

All those queried used the same method of installation. The splash guard was bolted to cross member of the frame on the truck or trailer.


The Ross Island Sand and Gravel Co. of Portland was the only premix concrete fleet operator queried in Oregon. For their mixer trucks, a metal frame 10 in. high and 26 in. wide was made for both sides from 3/16th in. sheet metal. A reflector of 31/2 in. diameter was mounted in the outside corner of each frame. A metal strip 3/16 in. thick, 11/2 in. wide and 24 in. long is used with four bolts to fasten the splash guard, which is made of second-hand belting. All metal used was scrap. The splash guard hangs down to within 16 in. from the ground. Labor charge ran \$5.16 per pair; material brought the total to an average estimate of \$10 per pair.

The Ross Island Co. has had some trouble with the splash guard being torn off in backing and have had to issue special instructions to drivers on this.

So there you have it. Make up your mind as to how you stand on splash guards and if your legislature decides to introduce a splash guard law you will at least know what some of the leading fleet operators in the two Northwestern states think about them.

END

(Please resume your reading on P. 36)



Anger, fatigue, grief, or joy—any one of these can temporarily transform a reasonably good truck driver into a serious traffic menace. This very thing has happened too often to ignore the danger of these human reactions.

The Handy Vari-Speed Governor, however, is not human, is never emotionally involved, but always comes to the assistance of the human driver who is. When your truck fleet is equipped with the Handy Governor, you have good reason to expect fewer accidents, and you will also save on tires, engine repairs, lubrication and brake maintenance.

The Handy Governor costs but a small fraction of what it will save you in its first year of operation.



HELPS KEEP the Emotional Driver OUT OF TROUBLE



ANTS IN ANN ARBOR . GRAND RAPIDS . YPSILANTI.



MORE and more, fleet operators are turning to SUPERCARGO for trailers of Advanced Design, Engineered Construction and Production-line Economy.

Only on SUPERCARGO will you find flexible torque arms combined with free-floating, quadri-point spring suspension. SUPERCARGO is engineered from the ground up! It's a quality trailer from top to tires!

AMERICAN BANTAM CAR COMPANY, BUTLER, PA.
MANUFACTURERS OF

SUPERCARGO TRAILERS

Scattered Dairy Maintenance

(CONTINUED FROM PAGE 43)

four hours. Labor charge here runs \$7.50 per unit per tune-up, or \$22.50 per year.

Tuneup follows a rigid seven point schedule:

- 1. Check compression.
- 2. Put vacuum gage on carburetor and overhaul or replace when needed.
- 3. Check distributor with dwell

tester and electric tachometer and overhaul or replace if needed.

- 4. Check timing with electric tester and make necessary correction.
- 5. Check exhaust with exhaust analyzer.
- Test battery and electric system with tester.
- 7. Inspect job and make a written report on all troubles and corrections.

With the "right" equipment we find that by following the above schedule, we can put our finger on the trouble in the least time. By

following the above schedule on all units serviced at our central head. quarters, we have been able to extend the time between major overhauls by at least one third. This however would not be possible if we did not have all the equipment necessary in making a correct and complete tune-up check.

Lube Man Is Mechanic

THE man who handles lubrication is a competent mechanic. We believe this to be one of the most important factors to our longer than average time between major overhauls, and lower than average maintenance cost.

Too often the lubrication is turned over to a dollar-per-hour grease monkey. This man does a good enough job on lubrication. But it is our belief that at the time the unit is lubricated it should also be given a careful inspection.

We use a twin post hydraulic lift. This is our grease rack. While the truck is on the grease rack, the mechanic doing the lubrication checks for loose universal joint, broken springs, leaky muffler and exhaust pipe, bolts needing tightening, etc. This procedure is followed every time the unit is lubricated.

While we have no accurate check, we are confident that the PM savings pays more than 50 per cent of the mechanic's salary. And more, we are getting a competent PM check every time the unit is lubricated. This would not be possible if we used a grease man who was not a qualified mechanic as well.

Tires Farmed-Out

WE farm out all tire repair and recapping. We believe that tire work is specialized work and can best be handled by the large, well-equipped shop which is manned by factory trained experts. Since the beginning of the war we have been recapping just as long as the carcass holds up. We leave this to the tire recapping expert. Our war-time experiencing with recapping has been such that we shall continue to recap all good carcasses.

Simplified Records

THE best fleet record system has always been the simple one; the (TURN TO PAGE 120, PLEASE)





Cheaper...Faster...Better...

IN A COMPLETE DEVILBISS PAINT SHOP

With a DeVilbiss Paint Shop in your own garage there's no waiting-no delay. Many paint jobs can be done while vehicles are tied up for mechanical repairs. And you get trucks back on the road with less loss in travel time and freight revenue.

In the DeVilbiss complete paint shop every item is designed for a specific job, and therefore produces the best possible result at peak efficiency, yet they all work together as a perfectly coor-

Every day more fleet operators are turning to DeVilbiss for complete paint shop modernization. DeVilbiss is helping them with this modern equipment that gets painting done and trucks out on the road without delay.

THE DEVILBISS COMPANY . Toledo 1, Ohio Canadian Plant: WINDSOR, ONTARIO

These four essentials PLETE PAINT SHOP

- A SPRAY BOOTH...providing adequate exhaust, scientific illumination and positive dust protection.
- 2. AN ASSORTMENT OF SPRAY **EQUIPMENT...** for factory quality results on all kinds of jobs with any spray material.
- 3. AN ADEQUATE AIR COMPRESSOR ... to provide ample low cost air for all paint shop and service requirements.
- 4. HOSE AND CONNECTIONS . . . designed and built specifically for spray painting service.

DE VILBISS means Quality in all four ..



AIR COMPRESSORS HOSE & CONNECTIONS

d.

is re

Scattered Dairy Maintenance

(CONTINUED FROM PAGE 118)

set up with the least number of forms to be filled out, and one where all the complicated bookkeeping is handled by the accounting department.

We have three forms and a monthly report, the latter being made up by the accounting department.

The first and most interesting form is a mimeographed maintenance rec-

ord sheet for each unit. (See illustration on page 43.) This form gives a complete physical description of the unit and then lists in detail work done on the truck. It is kept posted to date and on file in the shop and all data sent to the bookkeeping department.

The second form is a conventional truck defect report. Each driver carries a pad of them and each evening when he turns in his truck he makes out one of these forms in duplicate. One copy is kept at the repair shop and one goes to the bookkeeping department. When we have completed correction and repair on this unit, we fill in the bottom half with labor and parts replacement time and cost and send to the bookkeeping department.

The third form is a daily record for the plant filling station. On this form each truck served is listed by number, the amount of gas and oil marked down, and the speedometer reading. After each entry there is a space for the initials of the serviceman who handled the truck. At the end of the day the original of this form goes to the bookkeeping department and a copy to the maintenance shop, where it is filed for later reference.

From the information obtained from the above three forms, the auditing department makes up a monthly truck operating and maintenance cost report. A copy of this report goes to company executives, to the maintenance shop foreman at El Paso, and to the branch managers. The report lists each truck in the fleet, shows the make, number, year; miles traveled for the month, gallons of gas used, miles per gallon, quarts of oil used; dollar cost on gas, oil, grease, and antifreeze; dollar cost on labor and parts, and tires; total operating cost, operating cost per mile; the fixed charge per truck per month, the total cost and the total cost per mile.

The last double page of the monthly report gives a month's summary as to main plant and branches. Below this summary is a similar listing giving accumulated totals for the year.

Having this report to study monthly—a report which gives not only the picture at El Paso but at every branch where we farm out all repair work has been of great value to us in cutting our overall maintenance and repair cost.

END

(Please resume your reading on P. 44)

DRIVE SLOWGANS

By Buster Rothman

Keep up with the Jones's if you will But don't try to pass 'em on a hill.

Passing school zones take it slow Let our little shavers grow. Belmar, N.J. Street Sign





HOLD HOLD-OVER Plates maintain specified safe temperatures around the clock, they make possible longer routes . . . without the risk of spoilage. Because of their compactness and streamlining, they fit into any truck body with the greatest economy of space . . . thus increasing payload.

OPERATING COST - less than 10¢ per day!



Since KOLD-HOLD Plates contain no moving parts, they will give a lifetime of maintenance-free service. Economy of manpower is possible because undelivered loads need not be removed from the truck at night and reloaded next day. A simple "plug in" connection makes the truck a cooler room on wheels. WRITE TODAY for the latest KOLD-HOLD catalog.

Kold-Hold

Jobbers in Principal Cities

KOLD-HOLD MANUFACTURING CO.,

620 E. Hazel Street, Lansing 4, Michigan



She has to take chances ! ... YOU CAN PLAY SAFE!

Play it safe! Install Koppers American Hammered Porous Chrome* Piston Rings in your truck or bus engines. They are available now for most models. These are the rings that already have established spectacular mileage records, delivered full efficiency during every record-breaking mile in millions of miles of the toughest kind of service. They reduce cylinder wear by half, increase piston ring life four or even five times. Ask your American Hammered jobber for Porous Chrome piston ring sets. Koppers Company, Inc., Piston Ring Division, Box 626, Baltimore 3, Maryland.

American Historians 7038 STD.

*VAN DER HORST PROCESS

American Hammered Piston Rings

IN EVERY SIZE . OF EVERY TYPE . FOR EVERY PURPOSE

(CONTINUED FROM PAGE 67)

Clearance Angle

ONE of the liminations which beset radical kingpin offsets is that of clearance angle. By this is meant the maximum angularity in a vertical plane between the frames of the tractor and semi-trailer which will leave safe clearance between the end of the tractor frame and the bottom of the semi-trailer. As indicated in

Fig. 2, the 14-in. offset, at conventional plate height permits a clearance angle of 10 deg., which would seem ample for the worst conditions to be anticipated on the highway.

Traction

MAXIMUM traction is obtained, of course, where the maximum percentage of load occurs on the driving wheels. In a tractor-semi-trailer, assuming that the trailer axle carries the full legal load, maxim traction is secured with zero kingpin offset. In

the first example shown in Fig. 1, the tractor rear axle has 44.7 per cent of the gross weight in this condition and 43 per cent in the third example. If ideal load distribution could be attained, it would have 40 per cent. These differences, of course, are not great, but assuming .6 driving adhesion and 16,700 lb. weight on the driving wheels, as in the second example, the maximum, tractive effort would be 10,020 lb. Under the same conditions, with 18,000 lb. on the driving wheels the maximum tractive effort would be 10.800 lb. Considering the difference in gross train weight in the two instances cited, however, it is seen that the difference is too small to be of consequence.

skid

togg

This

by !

trac

he I

dist

offs

pro

load

wei

pro

gre

red

the

set

tog

po

pr

re

m

fi

ti

tl

Braking

UNLIKE traction, braking is afected seriously by weight distribution. In the conventional tractorsemi-trailer, only one axle drives, so that the percentage of load on this axle alone is significant from the standpoint of traction. Braking, however, is on all wheels and so variations in the imposed load on each axle affect the result.

In an ideal braking system, the braking force at all times would be proportional to the imposed load on each axle. So far, no braking system has appeared which is capable of instantaneously varying the braking force on each axle to cope with weight transfer due to inertia and gradient and variations in static loading due to changes in total payload or its distribution in the body. Therefore, the greatest safety may be expected from arrangements in which the variations in imposed loads are least. With the kingpin centered over the tractor rear axle, variations in the static loading of the trailer affect the tractor only at its rear axle, leaving the burden on the tractor front axle relatively uniform. With an appreciable kingpin offset, such variations affect both tractor axles and so produce less overall disturbance of proportionate loading.

Furthermore, advancing the kingpin forwardly reduces the tendency to jacknife, independently of these other effects. When a tractor-semi-trailer jacknifes as the result of a brake application, the tractor rear axle

(TURN TO PAGE 125, PLEASE)



You can count on SOL-SPEEDI-DRI

American industry has learned that it can depend on the uniformly high quality of Sol-Speedi-Dri—the field's original and foremost absorbent for all liquids. This quality is guarded carefully from mine to user by the most modern methods and equipment. The raw material for Sol-Speedi-Dri is obtained by selective mining, and is transformed, under constant laboratory control, into the finished product. There's no waste in Sol-Speedi-Dri. Packed


in special moisture-proof bags, every grain of Sol-Speedi-Dri comes to you at the peak of efficiency to give you the most for your money.

Sol-Speedi-Dri has been tested and proved by American industry. The result? More Sol-Speedi-Dri is used by the nation's shops and plants than any other material of similar nature! That's ample proof of Sol-Speedi-Dri's out-in-front performance. Remember, if Sol-Speedi-Dri is on the bag, quality is in the bag!

WHEN YOU BUY, BE SURE IT'S SOL-SPEEDI-DRI

Safety and Maintenance Co., Inc. No. 1 Wall Street New York 5, N. Y.

Warehouse Stocks Maintained in Principal Cities of the United States and Canada.



(CONTINUED FROM PAGE 122)

ird

ion

lb.

in

m.

lb.

ith

he

be

ly

in

skids sidewise in response to the toggle action about the kingpin. This skidding is sometimes increased by locking or partial locking of the tractor rear axle brakes which may be the result of excess braking force distributed to them. With a properly offset kingpin, and the consequent proportionate increase in front axle loading with any increase in total weight, the brakes may safely be proportioned to give the front axle a greater share of braking duty, thus reducing the danger of locking of the tractor rear brakes.

In addition, with zero kingpin offset, the sidewise component of the toggling effect originates at a point directly over the rear axle but at a point between the two axles with appreciable offset. In the latter case, the side-thrust is distributed between the two axles and accordingly the resistance to skidding of the rear axle materially increased (Fig. 3).

Summarizing these effects of kingpin offset on braking, it seems justifiable to conclude that both the effectiveness and safety of braking are promoted by a reasonable amount of kingpin offset—as much, in fact, as the limitations already discussed permit.

Steering

OPTIMUM steering must always be a compromise between ease and positiveness. The less weight on the front tires, the more easily the vehicle may be steered, but the greater the tendency for the front wheels to skid on slippery footing. Placing the kingpin directly over the tractor rear axle reduces the labor necessary to steer; but on slippery upgrades in particular, it introduces dangerous uncertainty of response.

As the kingpin is moved forward, the loading of the front axle increases, thus increasing its resistance to skidding and also the work required to turn the steering wheel. As shown in Fig. 3, however, the side-thrust on the front axle is correspondingly greater, since it is now affected by trailer inertia, from which it is virtually free with the kingpin centered over the axle. Fur-

(TURN TO NEXT PAGE, PLEASE)



Maintenance costs on brake systems can be reduced by using Puritan Super 60 Hydraulic Brake Fluid—developed especially for heavy duty service. Here is a brake fluid compounded from organic materials to withstand the extreme conditions of commercial service, not to deteriorate even after long gruelling use—and to be kind to the other parts of the brake system. See how Puritan Super 60 has all the characteristics you need in a brake fluid for your fleets.

PURITAN Super 60 BRAKE FLUID

BOILING POINT 370°F: No danger of brake failure due to vaporization.

POUR POINT 60°F BELOW ZERO: Remains free flowing and mobile even in Arctic weather.

NON-GUMMING AND NON-OXI-DIZING: Has a special base that does not gum or oxidize under any operating conditions. MOISTURE ABSORPTION: Capable of absorbing all moisture of condensation—thus protecting wheel cylinders and metal parts against corrosion.

rubber cups to swell or deteriorate.

MISCIBLE: Mixes completely with all other brake fluids. Safe to add to any hydraulic brake system.

You can keep your cars and trucks producing longer, your brake systems dependably safe, and reduce your maintenance costs by switching to Puritan Super 60. You'll be money ahead to make a fresh start by cleaning out old, gummy brake fluid with Puritan Hydraulic Brake Flushing Fluid and refilling with Puritan Super 60 Brake Fluid. Get both from your NAPA jobber.



(CONTINUED FROM PAGE 125)

thermore, in accelerating there will be a resulting tendency to oversteer and in braking to understeer. These effects will be largely if not completely offset by the increased tire adhesion due to increased burden, so that the net result will seemingly be slightly more effort required for steering with little or no compensating benefit as regards positiveness.

But, as previously noted, a definite kingpin offset does decrease the tendency to jacknife, which to a very real degree represents a steering factor.

Turning Radius

THERE are still other effects on steering which must be considered before we may judge the relative overall effect. It might seem that kingpin offset, to the extent that it pulls the whole trailer forward would shorten the total wheelbase and hence reduce the turning radius. This would be so if the distance from the kingpin to the trailer axle center were unchanged. But we have seen that as the kingpin is moved forward. some of its load is assumed by the tractor front axle and a correspond. ing amount is relinquished by the tractor rear axle. To compensate for this, so that the entire additional load on the front axle becomes increased legal gross train weight, the distribution of trailer weight between the kingpin and the trailer axle must be modified, imposing a slightly greater percentage on the kingpin as illustrated in Fig. 1.

This is done either by moving the kingpin or the trailer axle backward with relation to the trailer center of gravity. In the former case trouble may be anticipated both as to cab clearance and trailer throat clearance, so that the preferable procedure would be to move the trailer axle back. The distance which it must move back, of course, depends upon the effective wheelbase of the trailer, but in any case it will partially nullify the reduction in turning radius expected.

Fig. 4, however, illustrates the noticeable decrease in off-tracking results from a moderate kingpin offset. Since it is the total road width occupied on a turn which determines how sharp a curve or turn a vehicle may negotiate satisfactorily, it will be seen that kingpin offset makes sharper curves and shorter turns practicable.

Maneuvering

CLOSELY related to steering is the factor of maneuvering. Of this maneuvering, backing constitutes the trickiest part. The secret of effective backing of tractor-semi-trailers is to so handle the tractor that it directs the trailer wheels and then follows the trailer. This control is similar to that of a wheelbarrow, in that the direction taken by the trailer wheels is opposite to that toward which the tractor is directed and is controlled by swinging the kingpin from side to side, just as the handles of a wheelbarrow are swung.

With the kingpin directly over the tractor rear axle, this side movement of the kingpin is possible only to the extent that the tractor itself is moved sidewise; but with an appre-

(TURN TO PAGE 128, PLEASE)





GIVE YOUR SHOP FOREMAN A BREAK-

Could be your shop foreman takes the rap for a lot of things he can't help. Sometimes motor oil is to blame. So why not let him buy motor oil his way—on performance.

Valvoline has been pretested for you in millions of miles of actual service. Valvoline is doing a job in every type fleet you can name — transports, busses (gasoline and Diesel), taxis, pick-ups, salesman's cars and all the others.

How can Valvoline perform all these widely different jobs and do them well? Because Valvoline is made from the crude oil that rates highest for toughness and durability — 100% Pennsylvania crude. It's refined the slow, expensive way — by selective extraction. And Valvoline quality will pay off in extra miles of safe service — extra savings in shop costs — in your fleet.



FREE to Valvoline Users Valuable Laboratory Service

Analysis of crankcase drainings from any of your fleet units will tell how the unit's mechanical condition—and the way it is driven—are affecting oil mileage and engine safety. Hundreds of fleets depend on this trouble prevention service. Ask your Valvoline man for this Valvoline Fleet Control Laboratory Service free for your fleet.

FREEDOM-VALVOLINE OIL COMPANY

Dept. 41B Freedom, Pennsylvania

NEW YORK - WASHINGTON - TORONTO - PITTSBURGH - ATLANTA - CINCINNATI - DETROIT CHICAGO - LOS ANGELES - VANCOUVER, B. C. - REFINERIES AT FREEDOM AND BUTLER, PA.

This the

nter seen

ard

the

ond

the

for

onal

in-

the

een

nust htly

as

the eard rofe lible cab earoceiler it nds the paring

nore-

nes icle be

kes

the

his

the

ive

to

cts

WS

lar

he

els

he

ed

to

el-

he

ly

re-

(CONTINUED FROM PAGE 126)

ciable kingpin offset, this sidewise movement is materially augmented. making the train far more manageable. This is particularly noticeable in straight backing, in which case the centered kingpin makes exaggerated maneuvering of the tractor necessary to keep the trailer straight, whereas only a little is needed where adequate offset is employed.

Riding

EASE of riding is far from ideal in any tractor-semi-trailer, so far as the driver is concerned. Regardless of the trailer, the tractor driver rides on a short wheelbase with rear springs which must be relatively stiff when running light. Kingpin offset distributes a part of the fifth wheel load to the front axle, thereby reducing the extremes of loading on the rear axle. This may exert a favorable influence. In addition, the location of the fifth wheel trunnion

ahead of the tractor rear axle may also decrease the reactions due to trailer drag or over-run. Where the trunnion is directly over the tractor axle, the tractor in effect becomes a bell-crank whose fixed pivot is the rear axle, so that all of the reaction from the horizontal thrusts is resolved into vertical action on the front springs. When it is advanced, then these reactions are shared between the two sets of tractor springs. This, also may affect riding.

Offset Limitations

PREVAILING practice seems to limit kingpin offset to between 4 and 6 in. ahead of the tractor axle and most standard trailer models seem to have been designed with weight distribution and throat clearances of approximately this amount. Tractors, too, and the standard SAE CA dimensions seem to have been set up in most instances with such a degree of offset in mind. These circumstances, in themselves, limit the amount of kingpin offset which is practical, regardless of theoretical considerations. But, as we have already seen, the clearance angle also limits how far we may go.



flight condition without removing from car, truck or bus.

HI-RATE "188" FEATURES

- · Tests Before Charge
- 30 Second Test
- · Shows Exact Charging Time
- Dual Selenium Rectifiers
- Dual Heavy-Duty Transformers
- Full 100 Ampere Charging Rate
- 6 or 12-volts at snap of a switch
- New type Circuit Breaker projects both Battery and Charger
- High Rate Discharge for Desulphating



SOLD EXCLUSIVELY THRU THE NATION'S LEADING DISTRIBUTORS

MARQUETTE MFG. CO., INC., Minneapolis 14. Minn

WALL CHARGERS TRICKLE-MATIC




FIG. 5. Diagonal distance from kingpin center to corner of body is limiting dimension for cab clearance

One of the first dimensional limitations is the necessary cab clearance for jacknifing. The diagonal distance from the kingpin center to either corner of the body must not be greater than will allow adequate clearance to the cab when the trailer is jacknifed to the critical angle (Fig. 5). The formula for the solution of this maximum offset is given (TURN TO PAGE 130, PLEASE)



WOUR local Permite Jobber is an active part of a nation-wide system which maintains at all times a steady flow of Permite Replacement Parts to fleet operators everywhere.

You'll find your Permite Parts Jobber is a progressive business man, equipped to help you keep your fleet operating at peak efficiency. With his complete line of famous Permite

Replacement Parts, and a nearby extensive warehouse stock at his disposal, there are no annoying, costly waits for needed parts. You can count on always getting the RIGHT part for ANY MAKE of car, truck or bus.

See your Permite Jobber for high quality Permite Parts — correct fitting, easy to install, hard to wear out. They'll help keep your fleet rolling at minimum maintenance cost.

ALUMINUM INDUSTRIES, Inc.
Cincinnati 25, Ohio



REPLACEMENT P

PISTONS
PISTON PINS
VALVES

VALVE GUIDES
VALVE STEM KEYS
VALVE SPRINGS

WATER PUMPS
WATER PUMP
REPAIR KITS

CYLINDER SLEEVES
AND ASSEMBLIES
SPRING SHACKLES

TIE-ROD ENDS BOLT SETS BUSHINGS MUFFLERS
AND CLAMPS
TAIL PIPES

New Aviation Quality New Aviation Quality Speedometer Sets Amazing Economy Record!



The new Eclipse-Pioneer Electric Speedometer system greatly simplifies the problem of remote indication of m.p.h. or engine revolutions. Since it is entirely electrical, with three simple wire connections, accurate, trouble-free indication is possible even with present-day engine locations far removed from the front of the coach. Service and maintenance-free operation over incredibly long mileage is provided because there are no electrical brushes, commutators or sliding contacts. Furthermore, double-sealed, pre-lubricated bearings eliminate periodic lubrication and maintenance. Units are interchangeable between vehicles, making for maximum utility in fleets.

Simple changes of dial calibrations permit the use of the same units for m.p.h. and r.p.m. Clearly, this new product makes a big step forward in bus efficiency and economy—the kind of progress you would expect from Eclipse-Pioneer!

300,000 MILES OF SERVICE-FREE OPERATION



Eclipse-Pioneer

BUILDERS OF PRECISION INSTRUMENTS FOR THE AVIATION INDUSTRY FOR OVER 30 YEARS!



Kingpin Offset

(CONTINUED FROM PAGE 128)

in the figure and in conventional tractors it works out at about 14 in. in most cases.

It has been thought by many that round or oval-front trailers offered the possibility of greater kingpin offset for the same CA dimension but since the controlling dimension is the diagonal from the kingpin to the front corner of the body, it is the width of the body, rather than its shape which limits how far forward the kingpin may go while providing proper jacknifed clearance.




FIG. 6. Diagonal distance from kingpin to rearmost outer point of tractor tires is limiting dimension for determining trailer underbody clearance

Another limitation is that of trailer throat clearance. Not only must the trailer body clear the tractor cab, but the tractor tires must not interfere with the under parts of the trailer when jacknifed. Usually the support wheels are the parts most likely to interfere. As shown in Fig. 6, it is the diagonal distance from the kingpin center to the rearmost outer point on the outside tires which is the limiting dimension and may readily be solved in terms of maximum kingpin offset by the formula given in the figure. This is subject to great variations as between different trailers, but in almost all cases the trailer can be adapted to accept the maximum offset permitted for proper cab clearance and clearance angle.

It has been suggested that greater kingpin offset might be provided within these limitations by reducing the overhang of the front of the trailer beyond the kingpin. This, un-

(TURN TO PAGE 132, PLEASE)

Brutes INISHMENT

HALL-SCOTT Powered— PETERBILT TRUCKS Use LORD SHEAR TYPE ENGINE MOUNTINGS


The Hall-Scott Model "400" Engine is one of the most powerful truck engines developed in this country. Twelve of them, installed in Peterbilt Trucks, are helping to make an airfield out of a mountain for San Francisco, in one of the greatest earth moving projects on record.

The Half-Scott engine is supported by four Lord Tube Form Mountings—two at the gear cover, and two at the flywheel housing supports. They serve to isolate engine vibration, from the frame and the rest of the vehicle; absorb frame twist and prevent it from causing high stress in the engine; cushion road shocks; and reduce noise transfer to the cab and driver.

Whether you make powerful engines or delicate instruments, you can improve their performance, lengthen their life, and increase their sales, through the use of a Lord Vibration Control System. Bring your vibration problems to Lord-Vibration Control Headquarters. Write for Bulletin 103.

The Hall-Scott Model "400" Engine and one of the four Lord Tube Form Mountings which support it."

Twelve Peterbilt trucks powered by Hall-Scott "400" Engines, used by Guy F. Arkinson in the gigantic earth-moving job at Mills Field, San Francisco. Lord Mountings isolate engine vibration, absorb road shocks and frame twist, reduce breakdowns and improve performance.



LORD

with Vibration Control

LORD MANUFACTURING CO. . ERIE, PA.

Field Offices - Detroit + Chicago + New York + Washington, D.C.

Providence, R. I. . Burbank, Cal. . Philadelphia, Pa.

(CONTINUED FROM PAGE 130)

fortunately, will affect the cab clearance only, for the trailer throat clearance and the clearance angle will remain limiting factors, regardless of the trailer overhang. Moreover, thus moving the kingpin forward on the trailer frame will disturb the load distribution between the kingpin and the trailer axle, in compensation for which it will be

necessary to move the trailer axle further back. This will increase the effective wheelbase of the trailer and thereby aggravate off-tracking. In addition it will increase the bending moment on the frame of the trailer, necessitating somewhat heavier construction.

Coupling Height

SO FAR, only the horizontal location of the kingpin with reference to the tractor rear axle center has been considered; but as location alwas involves three dimensions, we must also consider transverse and vertical location. The first, of course, presents no problem, since in all cases it will be located on the longitudinal centerline of both the tractor and the trailer. The latter, however, is of considerable significance. From the standpoint of trailer stability, the ideal vertical location of the fifth wheel plate would be as high as possible. Exactly the opposite is true with respect to tractor stability. However, since the tractor is by its inherently lower center of gravity and its four-point support the more stable of the two, it is apparent that overall stability of the train calls for as high a fifth wheel as other considerations will permit.

These other considerations include the effect upon trailer floor height and consequent center of gravity height, effect upon clearance angle and effect of weight transfer on gradients and under acceleration and deceleration. Still another effect to be considered is the maintenance of proper clearance for the tractor tires when negotiating uneven surfaces.

Although drop-frame trailers are used to a considerable extent, the majority have flat floors for more convenient stowage and movement of load and for proper distribution of load toward the front of the body. Floor heights of trailers should be kept as low as practicable both for the sake of keeping the center of gravity down for safety and avoiding excessive load platform height. This definitely limits the height of the fifth wheel plate. Usually the upper plate is placed directly across the bottom of the frame, although

(TURN TO PAGE 134, PLEASE)



When a truck manager installs a Servis Recorder, a number of things begin to happen:

- —he gets on his desk every morning a little chart that shows all the truck did yesterday.
- -he then knows how often the truck stood idle, and exactly how long-all day.
- -he knows whether it was taken out at night without permission.
- —the chart shows him whether this truck has too much work to do compared with the others.
- -knowing the truck's route, he can tell whether it did any speeding (making up lost time).


—if the truck gets in after hours, the chart shows him whether extra pay for overtime is justified.

All this the SERVIS RECORDER does—and more. Write for our booklet —"Ten Ways of Getting More Work Out of Motor Trucks".

THE SERVICE RECORDER CO.

1375 Euclid Avenue • Cleveland 15, Ohio

The Servis Recorder
Tells Every Move Your Truck Makes



Better slack off a bit, you've got that bolt too tight!

MORE DELIVERIES PER DAY... LESS DRIVER FATIGUE......

VICKERS
HYDRAULIC POWER
STEERING

3

ıt

y

e

1.

٥,

f

e

re of of y. oe or of

of

at

AL.

VICKERS
HYDRAULIC DRIVE
FOR HOSE REEL AND
PRODUCT PUMP

Heavy front wheel loading on tank trucks makes hard work of manual steering. But steering is easy on these Socony-Vacuum trucks because they have "finger tip" Vickers Hydraulic Power Steering. This avoids driver fatigue—greatly improves maneuvering in cramped quarters.

Vickers Hydraulic Drive for the hose reel and product pump has solved several difficult problems. On any type truck it avoids complicated mechanical transfer from the power take-off. On semi-trailer type trucks, it provides the only fully satisfactory way to get power from the tractor engine to the product pump and hose reel. Hydraulic power can be applied wherever hose lines can be run.

When the driver of this truck is ready to make a delivery, he simply pushes the hydraulic control lever back. This starts the product pump and frees the hose reel. A valve in hose nozzle prevents product flow until house connection is made—the product pump discharging through a bypass valve. When nozzle valve is opened, the bypass automatically closes and product flows. Driver does not have to walk back to the truck. On completion of delivery, he closes nozzle valve, returns to truck and pulls control lever forward. That stops the product pump and engages the hydraulic drive to the hose reel, winding in the hose.


This Vickers Hydraulics application is engineered to deliver product in the shortest time with the least amount of effort for the driver.


Consider the advantages of Vickers Hydraulics for your drive problems, which may provide a better solution at lower cost and with less maintenance.

124

(Below) Vickers Hydraulic Motor drives product pump at extreme left. Hydraulic control valve is next to real.







VICKERS Incorporated

DIVISION OF THE SPERRY CORPORATION

1418 OAKMAN BOULEVARD . DETROIT 32, MICHIGAN

Sales Engineering and Service Offices: ATLANTA
CHICAGO • CINCINNATI • CLEVELAND • DETROIT
LOS ANGELES • NEWARK • PHILADELPHIA • ROCKFORD • ROCHESTER • SEATTLE • ST. LOUIS
TULSA • WASHINGTON • WORCESTER

ENGINEERS AND BUILDERS OF OIL HYDRAULIC EQUIPMENT SINCE 1921

(CONTINUED FROM PAGE 132)

some height might be gained for recessing it slightly.

In an attempt to standardize trailer coupling heights for the sake of promoting sidesway stability interchangeability of tractors and trailers and uniform load platform heights, a Subcommittee on Motor Vehicle Design of the Transportation & Maintenance Activity of the SAE

rendered a report which was published in the SAE Journal of April, 1937, setting the uncoupled height of the fifth wheel plate at tire height, plus coupled clearance of $2\frac{1}{2}$ in. plus tractor spring deflection of 4 in. or $6\frac{1}{2}$ in. above the tire height.

Fig. 7 illustrates the basis for this recommendation. However, it has been pointed out that this analysis of the problem does not take into consideration the transverse angular displacement of the tractor rear axle with respect to the tractor frame

when negotiating uneven surfaces, approaches the problem in profile alone.




FIG. 7. Cut and formula show bases for recommendation of standard coupling height of $6\frac{1}{2}$ in. above tire height




FIG. 8. Additional data for considering transverse angular displacement of tractor rear axle on uneven ground as it affects the coupling height

Accordingly, as shown in Fig. 8, an analysis has been made from this standpoint. It is apparent that the plate heights required for complete avoidance of interference between the tractor tires and the underside of the trailer may be considerably above those. On the other hand, practice seems to follow the principles enunciated in Fig. 7. In practice, interference between the tractor tires and the underside of the trailer does sometimes occur. The question therefore resolves itself into whether the advantage of the lower trailer floor heights resulting warrant the risk.

END
(Please resume your reading on P. 68)





SAFE DELIVERY OF FUEL OIL

While the transportation of stove and furnace oils does not present hazards comparable to the delivery of gasoline, the Sinclair equipment pictured above indicates the great precautions which most major marketers take in assuring safe delivery of their products. This delivery truck is equipped with S. & J. Internal Hydraulic Valves. Normally in a closed position, they are held open by hydraulic pressure against spring tension. They close instantly when the hydraulic pressure is released.

Should a fire occur while unloading, small fusible plugs installed in the hydraulic line will melt and release the hydraulic pressure when subjected to even as much heat as produced by an ordinary match. This is typical of the Sinclair conception of delivering petroleum products in residential areas—MAXIMUM SAFETY ALWAYS.





SHAND & JURS CO.

BERKELEY, CALIFORNIA

NEW YORK


CHICAGO

HOUSTON

LOS ANGELES


SEATTLE

SHAND & JURS





REPAIR with genuine Wagner Lockheed Brake Parts



REFILL with Wagner Lockheed
Hydraulic Brake Fluid

Turn out better brake jobs...help reduce automobile accidents. CoMaX lining is unsurpassed for quick, safe, smooth stops. It has exceptionally long-wearing qualities and is uniform in texture, noncompressible, ageproof and easy on the drums.

You can buy with confidence when you specify CoMaX. Available in sets, rolls, blocks, slabs or cut segments. Like Wagner Lockheed Hydraulic Brake Parts and Fluid, it is warehoused throughout the U. S. and Canada, and is available everywhere through Wagner jobbers.

Wasner Electric Corporation

6470 Plymouth Ave., St. Louis 14, Mo.

EVERY REPAIRMAN NEEDS

Bulletins HU-17G and HU-197 ... Tips for better Brake Service—free on request


LOCKHEED HYDRAULIC BRAKE PARTS und FLUID . MORAL COMOX BRAKE LINING . AIR BRAKES . TACHOGRAPHS ELECTRIC MOTORS . TRANSFORMERS . INDUSTRIAL BRAKES

B48-2

Engine Governors

(CONTINUED FROM PAGE 41)

Fig. 1 is a chart showing the general requirements of all governors for automotive engines. Referring to Fig. 1, the curve A-B-C-D represents the maximum horsepower available at wide-openthrottle at different engine speeds. Thus at each engine rpm, the curve shows the maximum power that the engine will deliver. The horsepower is shown on the vertical scale and the engine rpm



SOUTH BEND

14"Drill Press

South Bend presents this new 14"
Drill Press as a companion to the South Bend Precision Lathe. It is built with the same high standards of accuracy and skilled workman-

South Bend presents this new 14"
Drill Press as a companion to the
South Bend Precision Lathe. It is
built with the same high standards
of accuracy and skilled workmanship. Years of painstaking research
and experimentation have gone
into its designing. This has resulted in a superior tool that is
unsurpassed for accuracy, ease of
operation, versatility and dependable performance.

\$9800

f. o. b. factory, bench model with chuck, extension cord and switch; less motor.

FEATURES and SPECIFICATIONS

BELT TENSION RELEASE. Quick-acting belt tension release lever simplifies speed changes. Keeps tension correct.

BUILT-IN LIGHT. Provides shielded illumination for work area. Separate on-off switch.

BALL BEARINGS. Sealed type. No oiling. 2 on spindle drive unit, 2 on spindle.

QUILL BEARING ADJUSTMENT. Compensates for wear.

DEPTH GAUGE. Graduated in inches. Adjustable collars control feed and return.

RUGGEDLY CONSTRUCTED. Precision-built for industrial and all other types of shops.

TWO MODELS. Bench or floor type.

CAPACITY. Maximum drill size in iron or steel, ½". Drills to center of 14" circle.

CHUCK. Capacity 0 to ½"

SPEEDS. Four 707, 1305, 2345, 4322 r.p.m.



SOUTH BEND LATHE WORKS

BUILDING BETTER LATHES SINCE 1906 . 445 E. MADISON ST., SOUTH BEND 22, IND.

is shown on the horizontal scale. The curve shows that the available horse-power increases as the engine rpm increases, but after the "peak" horse-power at C the available horse-power reduces (from C to D) as the engine rpm is increased further.

The vertical doted line C-E represents optimum governor performance. This curve shows the variation in rpm as the load is varied from full-load at C to no-load at E. Since the line C-E is vertical, the rpm at full-load at C would be the same as at no-load at E: hence a truck equipped with a governor giving this performance could climb a hill with no loss in rpm. As the vehicle ascends the hill, the governor throttle would gradually open to maintain the constant rpm along the line E-C while the power (and load) increases from low-load at E to full-load at C. If the hill gets steeper, the engine rpm will reduce along the line C-B because the engine cannot deliver any power above this line which would be necessary to maintain the governed rom.

One of the two basic types of governors which is used extensively is the velocity-vacuum governor. This type of governor utilizes the forces accompanying the flow of air to the engine. Briefly, the governor throttle is offset so that the impact force of the air-flow tends to close the governor throttle against a calibrated spring. Thus when the engine speed tends to increase, the increased air flow tends to close the governor throttle against the force of the spring to maintain the governed speed.

Because velocity governors do not require a separate engine drive, they have the inherent advantage of low cost and simplicity of installation. However, because of the lack of an engine speed drive, they cannot hold the engine rpm as closely as speed-driven governors, which is the second type of governors now in use. A speed-driven governor is one that incorporates an engine-driven element as the controlling factor, so that the control is manifested in response to changes in engine rpm.

Presently, there are several kinds of speed-controlled governors and all give comparable performance. One of these is the well known fly-ball governor which utilizes centrifugally operated weights to move the governor throttle against a spring by means of suitable linkages. An excellent hydraulic governor has been developed in which a pump and a centrifugally operated bleed-valve control the pressure of oil that motivates a piston which in turn moves the governor throttle against a spring. In another type of speed controlled governor a diaphragm is used to

(TURN TO PAGE 138, PLEASE)



The pictures at the right illustrate the first Spicer Universal Joint and the Spicer automobile in which its efficiency was proved.

11

le

ll le re

1e

of

at

to

ed or

ng

nd

ed

m rs,

rs

is

en so

·e-

of ve

se

or ed

tle

ole

OV-

8


ed oil

irn a

on-

to

NAL



The Proneer LEADS THE WORLD

in Automotive Universal Joint and Propeller Shaft production!

The great preference for Spicer Universal Joints and Propeller Shafts is the result of many exclusive advantages, both in manufacturing experience and design.

Spicer revolutionized automotive power transmission in 1904 with the invention of the first practical universal joint.

Spicer developed the telescoping action so necessary in propeller shaft action.

Spicer developed the flange yoke and companion flange idea.

Spicer developed the outer casing of universal joints for better lubrication and protection.

Spicer introduced spring retainers that automatically compensate for packing wear.

Spicer pioneered the tubular shaft which enabled large diameters to be used with light weight.

Spicer developed the I-G type joint to seal in lubricant.

Spicer perfected cageless roller bearings, giving the Spicer Universal Joint far greater load capacity at higher speeds with less friction than any other type of similar product.

Today . . . the pioneer still leads the world!

SPICER MANUFACTURING • Division of Dana Corporation TOLEDO 1, OHIO

PASSENGER CAR AXLES - CLUTCHES - PARISH FRAMES - STAMPINGS - UNIVERSAL JOINTS SPICER "BROWN LIPE" GEAR BOXES - RAILWAY GENERATOR DRIVES

Spicer

FEBRUARY, 1948

TRANSMISSIONS

TORQUE CONVERTERS

Use postage-paid card inserted at page 61 for free information on advertised products

137

Engine Governors

(CONTINUED FROM PAGE 136)

power the governor throttle, and a portion of the manifold vacuum is used as a source of power for the diaphragm; a centrifugally controlled air valve determines when the suction can operate the throttle, so that in this governor, also, the control is based on the speed of the engine.

Referring again to Fig. 1, the line N-C represents the typical performance of any of the speed-controlled governors. With this type of governor the governed speed at no-load at N is about 150-200 rpm higher than at full-load at C. With present governors, it is not desirable to operate along the line C-E in which there is no variation in rpm because the vehicle will lurch when the driver shifts into the lower gears. Observe that the line N-C is straight all the way up to the wide-open-throttle power curve at C. This means that a speed-controlled governor does not "choke-off" the power when pulling a heavy load up a hill.

Referring to Fig. 1, the line B-M represents the typical performance of a velocity governor. With these governors the engine rpm at no-load at M is about 300-500 higher that the fullload engine rpm. Also, because velocity governors depend on the air resistance to move the governor throttle there is a slight power loss at full-load; this effect is shown in Fig. 1 since the curve M-B does not increase to meet the wideopen-throttle curve at C as with speed controlled governors. This characteristic will be noted by the driver when pulling a heavy load over a hill since it will be necessary to go into lower gears sooner than with a truck equipped with a speed-driven governor. Thus, although a velocity governor has the advantage of lower initial cost and is easier to install than a speed-controlled governor. they tend to lose more rpm and power than speed-controlled governors when the vehicle is climbing a hill.

END

(Please resume your reading on P. 42)

Quiz Answers

CCJ Quiz on P. 71

- Reo, which gets its name from the initials of Ransom E. Olds, has its plant at Lansing, Mich. Its advertisement has appeared on the front cover of the COMMERCIAL CAR JOUR-NAL for quite a few years.
- Diamond T. The gem of course is a diamond, and the company was founded by Charles A. Tilt. (The "T" in Diamond T stands for Tilt.)
- 3. Ford.
- Walter, builder of Snow Fighters, located at Queens, Long Island.
- Studebaker, which was in existence before the Civil War, was once a leader in the manufacture of carriages and wagons.
- White, which once built a steam car that was the chief rival of the Stanley Steamer.
- Chevrolet.. The Little Motor Car Co. of Flint, Mich., was the fore-runner of the Chevrolet.
- 8. FWD, or Four-Wheel-Drive.
- Dodge, founded by John and Horace Dodge and now maker of "Job-Rated" trucks.
- Mack, which uses a bulldog as a trade mark.

ARK. ADOPTS AASHO LIMITS

Arkansas adopted highway size and weight limits recommended by the American Association of State Highway Officials effective Feb. 1. These provide a single unit length of 40 ft, a tractor semi-trailer length of 50 ft, and other combination lengths of 60 ft. The weight limit remains at 18,000 lb per axle.



SEALED POWER GI-60Contracting Groove Insert

puts 1/32" of heat-resisting, wear-resisting steel armor plate at top of top ring groove



YOU can fix that worn top ring groove for keeps with the new GI-60 Contracting Groove Insert. It's not a spacer. It doesn't float. It is anchored securely at the top of the ring groove, which has been regrooved to an absolutely true surface 1/32 wider than before, with a 1/32 recess at the top. GI-60 locks itself permanently into this recess. It becomes a heat-treated shield of heat-treated spring steel. It resists wear and pounding better than aluminum, better than cast iron. It is the only dependable, economical answer to top ring groove wear.

New rings in old, worn top grooves are good money thrown away. They stick. They wear out fast. They cause cylinder wear. They waste gas. To widen the groove and use a wider ring changes the manufacturer's specifications—invites trouble. To use an ordinary spacer is simply to use a wider ring in two parts. GI-60 is the only proved satisfactory answer.

Your Sealed Power distributor can install GI-60 for you. He has the special tools required. GI-60 means profitable business for you and satisfaction for your customers. It is just as effective in new pistons as in old ones. Ask your Sealed Power Distributor or write direct.

MAKES OLD PISTONS NEW - KEEPS NEW PISTONS YOUNG



ı

ar

de

ind

gle iler

ion

ins

New Ring in Worn

Groove widened
1/32' and recessed
for GI-60 installed and in GI-60 reconditioned groove

New Ring in Worn

Groove widened

Gl-60 installed and in GI-60 reconditioned groove

SEALED POWER CORPORATION

MUSKEGON, MICHIGAN . STRATFORD, ONTARIO

FEBRUARY, 1948

Use postage-paid card inserted at page 61 for free information on advertised products

139



-for ALL tubes-BIG and Small

The latest, most practical achievement in highest quality heat element and control compactly enclosed in vulcanizing shoe. Assures correct, uniform, constant heat for strongest and most lasting repairs. Vulcanizing is done from the top down—the operator can see what he's doing—easy to place patch correctly. The lever lock is easily and quickly operated—provides the proper pressure on patch.

The Swiveling Shoe can be adjusted to any position—the tube lies in a normal flat position on the resilient thick rubber pad. It can vulcanize an injury of $8\frac{1}{2}$ inches with each cure. Makes it easy to splice inner tubes.

Ideal for truck and tractor tubes. Has a 16 inch clearance any size tube will fit in without folding or distorting. For vulcanizing all sizes of valve stems, 2 adapters are furnished.

No. 870-BISHMAN Heavy Duty Tube Vulcanizer. PRICE \$34.50

Ask your Jobber or write for folder

BISHMAN MFG. CO. . OSSEO 4, MINN.



FOR THE BEST IN SAFETY
LIGHTING AND
REFLECTING IT'S
EQUIPMENT...

DO-RAY
LAMP COMPANY
1458 S. MICHIGAN AVE.
CHICAGO 5, ILLINOIS

IT'S
DO-RAY
ALL THE
WAY

BUY BONDS

Fleetman's Library

STONEHARD RESURFACER FOLDER, a twocolor publication describing the heavyduty material for repairs and overlays to concrete and wood floors. Illustrations show typical applications. Write the Stonehard Co., 403 N. Broad St., Philadelphia 8, Pa.

REPS PIPE AND STUD EXTRACTORS, fourpage bulletin describing and illustrating master set No. 210 pipe and stud extractors. Photographs show how the device is used to ream and extract broken pipes and screws. Reps Tool Co., 94 Allyn St., Hartford, Conn.

More Efficient Small Tool Grinding, a 4-page brochure showing how the grinder is used to sharpen tools and finish work. Available from Corlett-Turner Co., 1001 S. Kostner Ave., Chicago, Ill.

CABLE CATALOG, showing the Andrews line of automotive cable and electrical products. The Andrews Mfg. Co., St Louis, Mo.

TITEFLEX CATALOG, a 10-page, illustrated publication showing Titeflex hose for automotive gas lines, oil lines, air lines and oil filter lines. Write Titeflex, Inc., 525 Frelinghuysen Ave., Nework, N. J.

Gas Welding Wire Catalog, a 3-color 24-page brochure devoted to gas welding and its use. Covers the complete Page line, gives the application, procedure, proper torch adjustment, physical properties or each gas welding rod. Write Page Steel & Wire Division, American Chain & Cable Co., Inc., Monessen, Pa.

23 IDEAS, a folder showing use of Kleer Vu products throughout the industry. The publication suggests these plastic envelopes for holding forms, instruction cards, looseleaf material, notes and similar data which should be protected from dirt, grease and wear. Write American Plastic Products Co., 2907 S. Main St., Los Angeles, Cal.

BARRETT BRAKE SCHOOL

Attention is directed to a statement in the article "Service Schools for Fleetmen" appearing in the January issue. We mentioned that the Barrett Brake School consisted of a 10-week course of instruction. Actually the course consists of 10 days instruction.

Cleaner's Dandy

H

tur

fine

ma

with

20,0



Quaker Dry Cleaners of Pittsburgh rate an oscar for the handsome appearance of the newest addition to their Diamond T fleet, a model 509 SC

HIGHWAY'S 20,000 LB. RUNNING GEAR

- 1. One-piece forged axle
- 2. Twin bearings
- 3. 7" brakes ¾" lining
- 4. Variable rate spring suspension
- 5. Spring steel radius rods, adjustable
- 6. Cam shafts roller bearing mounted





HIGHWAY'S PROVEN TANDEM

- Equalizer beam construction reduces each bump 50%
- Ball & Socket Joints max. flexibility — min. stresses
- 3. Below-load suspension eliminates brake chatter
- 4. Fixed wheel centers assures perfect axle alignment



Whether it's single or tandem you need, Highway Trailer has the best answer!

HERE'S why it pays you to do business with today's Highway Trailer Organization: Highway is a manufacturer of trailers! Highway converts raw materials into the finest of castings—produces axles, brakes, supports and many other components under one roof—with one overhead—with one profit! Naturally you get more for your money!

Take axles as an example. Study Highway Trailer's new 20,000-lb. single axle. Consider Highway's thoroughly proved

tandem. Both tops in the field!
Give your business the benefit of
Highway's more than 30 years of


successful manufacturing experience—Highway's network of factory branches and distributors—and Highway's unexcelled manufacturing facilities! Write for all the facts about the new Highway Clippers and Freightmasters! It means money in your pocket—every year for many years!

HIGHWAY TRAILER COMPANY

General Offices, Edgerton, Wisconsin
Factories at: Edgerton and Stoughton, Wisconsin
Parts Depots: Edgerton, Wisconsin and Chicago, Illinois
Commercial Truck Trailers
• Earth Boring Machines
Winches and other Public Utility Equipment




HIGHWAY AMERICA'S TRAILERS



WAUKESHA MODEL 6-MZA
HIGH POWER ENGINE

Six cylinders, 41/4 in, bore x 43/4 in, stroke, at 8600 rpm.



Hose Wagon's performance at a West Side Pier fire in New York City

Adverse weather conditions are no excuse. Whether it's a fire-fighting truck ... bus ... or cross country merchandise transport truck—it's carrying payload. And it is up to the engine to take it through.

The new Model 6-MZA Waukesha Engine can and does take it through!

Streamlined ... compact ... smooth. Designed for use with modern 70-75 octane gasoline. Packed with power! Built to develop and deliver high power and high speed!

Every feature of modern construction and design. Drop forged, heat treated 7-bearing crankshaft. Hardened alloy exhaust valve seats. Aluminum pistons. Controlled turbulence combustion chamber. High duty precision bearings. Built-in centrifugal governor and full pressure oiling system. Send for Bulletin 1126.

WAUKESHA MOTOR COMPANY, WAUKESHA, WISCONSIN .

NEW YORK . TULSA . LOS ANGELES


WAUKESHA ENGINES

Chevrolet for '48

(CONTINUED FROM PAGE 89)

A steering column gearshift is now available on models equipped with 3-speed transmissions. A new parking brake on these models is foot-operated. The foot pedal is securely locked in position by means of a self-energizing lock. A slight pull on the release handle is required to release the brake. Removal of the hand brake and gearshift levers from the floor area on ½ and ¾-ton models makes it easier for the driver to enter or leave through the right hand door.

Engine improvements include a heavier, more rigid crankshaft, new main and connecting rod bearings, modified bearing caps, an aluminum alloy camshaft gear and new Buna N valve stem oil seals.



The propeller shaft bearing support.
Rubber-mounted bearing is a single row type permanently sealed and lubricated

New thin wall babbitt bearings are said to give more than double the life of previous bearings. Main bearings are interchangeable and are precision finished for ready installation. Front, front intermediate and rear intermediate main bearing caps are now more rigid, an improvement reducing bearing deflection and increasing bearing life.

Engine valve stems are now equipped with Buna N synthetic rubber seals, eliminating the necessity for valve spring cap covers. This is said to result in quieter valve operation.


END

(Please resume your reading on P. 90)

'47 HAD LOWEST DEATH RATE

The year 1947 ended with a traffic death toll estimated by the National Safety Council at 32,500. This is 1,200 less than the 33,700 killed in motor vehicle accidents in 1946 and 7,469 less than the 39,969 killed in 1941.


While travel figures are not yet available for the entire year, it has been estimated that mileage in 1947 ran about 10 per cent above 1946 and about 12 per cent above 1941. This would mean a 1947 fatality rate (deaths per 100 million vehicle miles) of between 8.5 and 9, the lowest in U. S. history.



Exploded view of the new synchronizer for 3rd and 4th speeds. The new transmission has helical gears



NOW: A Fast & Accurate Pin Fitting Machine for the Service Industry



TOBIN-ARP have developed a revolutionary new machine for fitting pins in connecting rods and pistons of all internal combustion engines. This machine fills a long felt need in the service industry.

It bores the wrist pin bushings and pin holes in the piston. Its novel means of holding the piston and rod is by air and hydraulic pressure. The piston or rod can be located in the machine in a few seconds and centered with an accurate expanding mandrel used on the inside of the bushing or piston holesthe clamping arrangement holds the rod or piston in the exact position it is centered.

The cutter revolves at a

high speed and with the hydraulic feed produces a perfectly round hole, glass smooth. Cutter is set with the use of a comparator wherein the piston pin is used as a gauge. Comparator is graduated to .0001 so operator can select the proper clearance or press fit.

TOBIN-ARP MODEL P-MIOO PISTON-PIN FITTING MACHINE

It eliminates any guess work and does a more accurate job faster than ever before possible. The operator knows definitely what clearance his connecting rod bushing has over the pin diameter, or if the pin is a pressed fit in the piston he knows exactly the press fit.

This machine has no gears, racks, screws, levers or handles—everything is operated by oil, air and electricity, making it a very fast machine. A set of six new over-sized pins can be fitted to six old pistons and six old rods in from 18 to 20 minutes.

Send for Complete Particulars

TOBIN-ARP MANUFACTURING CO.

2845 Harriet Ave. So.

Minneapolis 8, Minn.

Detroit Dispatch

(CONTINUED FROM PAGE 72)

Ford Six Rumor

We have a report—and we can give it no greater credence than that—that Ford will enlarge the bore of its six cylinder truck engine to 3½ in. (present bore is 3.3 in.), giving it about 100 hp. and greater torque, particularly at low speeds. It probably won't be announced till some time in midsummer.

Chevrolet P-D Model

Chevrolet will have something new to offer in the way of a package delivery model in the near future. No details are available as yet, however.

Jiggleless Instruments

AC Spark Plug Division of General Motors has come up with a solution for taking the jiggle out of needles in dashboard instruments. A colorless silicone solution which AC used in making gunsights for the Army Air Forces during the war acts as a lubricant and prevents sudden movement of the needle without affecting its accuracy.

Canadian Agreement

Through an agreement with the Canadian government, truck shipments from the United States through Canada in bond to points in the eastern U. S. are being resumed. The arrangement had been in effect during wartime and had been terminated at the end of 1945. The new agreement came about as a result of the Geneva Trade Agreement and will reduce the distance trucks must travel to eastern points by about 110 miles,

Cross License Plan

Most truck and automobile manufacturers will continue to exchange patents under the extension of the industry cross licensing plan for another year. AMA reports that 17 motor vehicle builders are in the new agreement which covers patents owned on Jan. 1, 1940, with certain exceptions. All signatories are able to use patented inventions included in the plan without compensation or fear of infringement suits.

(Please resume your reading on p. 74)

WARD LAFRANCE CORP.

The new Ward LaFrance Truck Corp., Elmira, N. Y., has acquired all the business and assets of the former Ward LaFrance Truck Division of Great American Industries, Inc., New York. The new corporation is controlled by Joseph G. Grossman, president, and will be operated by him and A. Ward LaFrance, vice-president, both of whom have been identified with Ward LaFrance equipment for the past 30 years. They will continue the production of heavy-duty trucks, fire engines, and trolley coaches. All communications should now be addressed to Ward LaFrance Truck Corp., Elmira, New York.





a new Ferret Set

A new design...strong...adaptable... they squeeze into close places easily

(All units 3/8" Square Drive)
1/4" and 5/16" Single Broached Sockets

- -Double Broached Sockets from %" to %" -Speeder Wrench -8" Ratchet

n

0 e-in i-

e-

g-tg

rer sts

ne d

ed ut

)

ce 13-

m

A. of

rd

of ey W

ck

- -Sliding Tee
- -Nut Spinner
- 1—Universal Joint 3", 6", and 12" Extensions

Complete in a metal box, 19½" x 5¾" x 1¾" — specially designed for this set. Rich red enamel finish.

Yes, a new Ferret set . . . new in design . . . way over par in performance - and they're twice as strong as you would expect such slim, slender handles and thinwalled sockets to be.

They squeeze into tight places and get those hardto-reach nuts and bolts that defy the ordinary type wrench. Newly designed by Snap-on engineers, they make quick easy work of many of the tough jobs on modern motors and engines.

Be sure to ask your "Snap-on" man to show this set the next time he calls.

SNAP-ON TOOLS CORPORATION Kenosha, Wisconsin

INTERNATIONAL DIVISION: KENOSHA, WISCONSIN, U. S. A.



Washington Runaround

(CONTINUED FROM PAGE 74)

Due to the unanimous approval given the bill by the House Interstate and Foreign Commerce Committee, the ICC, and organizations of shippers and carriers, early approval by the Senate is anticipated.

As to other legislative matters, The Reed-Bulwinkle bill will probably be approved during the current session despite substantial opposition in some quarters. It will be remembered that this legislation authorizes carriers to enter into joint

rate-making agreements without fear of anti-trust prosecution, provided they comply with ICC regulations governing such agreements. However, a presidential veto of such legislation is a definite possibility.

Federal Highway Roundup

Highway development appears to be one of the few topics that may remain relatively free of politics during this election year. While this may not be true when details of highway programs are discussed, there seems to be general agreement between the Administration and Congress on the need for a strong construction program and continued Federal aid.

The President in various messages submitted to Congress last month repeatedly emphasized Administration support for highway measures. For example, in his Economic Report, he declared that "at least 45 per cent of our highways leading into cities need to be rebuilt within 10 years."

On Capitol Hill, Republican bills have been introduced to extend the Federal-aid highway program beyond the end of the fiscal year 1949.

Meanwhile, the Public Roads Administration, in a year-end report, announced that improvement of the nation's highways proceeded at a faster pace in 1947 than in the previous year.

Reviewing the progress of the highway program, Public Roads Commissioner Thomas H. MacDonald said contract awards authorized by the states during the year called for \$895,000,000 worth of work on 44,700 miles of road. This was approximately \$150,000,000 more than the cost of road construction contracted for in 1946.

The 1947 total included contracts for Federal-aid projects to cost \$640,000,000 and 19,800 miles in length.

Expenditures for State - administered highway work under way during the year amounted to approximately \$890,000,000.

At the year's end, Commissioner Mac-Donald said, Federal-aid projects costing more than \$700,000.000 were under construction, and plans had been approved for additional projects costing around \$350,000,000, on which work is expected to start this year. The total estimated cost of Federal-aid projects programmed by the States for construction but not yet advanced beyond the planning stage was nearing \$750,000,000.

The urgent need for better highways throughout the nation was emphasized by steadily mounting floods of traffic on main rural roads and urban thoroughfares, PRA stated.

For example, truck-hauling on rural roads during the past year was estimated at 86 billion ton-miles, as compared with a total of 73.5 billion ton-miles in 1946.

Commendable progress was made by the States, in cooperation with municipal authorities, in the planning and actual start of construction on expressways designed to speed the flow of traffic in urban areas and at the same time reduce accident hazards, Commissioner MacDonald added.

Work was begun during the year on urban expressways and multi-lane rural highways in Massachusetts, Connecticut, New York, New Jersey, Pennsylvania, the District of Columbia, Florida, Ohio, Texas and California.

Commenting on contract price trends, Commissioner MacDonald noted that construction costs for various classes of road work have risen 180 to 193 per cent above 1940 costs.

Radio Allocations Delayed

The proposed decision of the Federal Communication Commission on permanent allocation of radio frequencies to highway users, including the trucking industry, is (TURN TO PAGE 148, PLEASE)



● The Pierce Road-Speed Governor limits only one performance feature of your car or truck—high gear top-speed—if miles-per-hour restriction is your purpose.*

The Pierce Road-Speed Governor is centrifugal (flyball)—driven from the propeller shaft of the car—thus controlling positively only in relation to the speed at which the wheels are turning—regardless of gear, road conditions or load. It fits any standard automotive engine.

Set it at any speed you wish. Your vehicle has every ounce of power built into it to reach and maintain governed speed in any gear. Write for full particulars.

*The same type of governor, driven from the distributor, will give complete engine RPM protection without reduction of engine power or vehicle performance in any gear. In this manner of installation, the unit is positive engine protection only—not a miles-per-hour governor.

THE PIERCE GOVERNOR COMPANY, INC.



It takes QUALITY PERFORMANCE to get an ENCORE . . .



and YORK-HOOVER BODIES get "encore orders" time after time



The fact that fleet operators everywhere keep reordering York-Hoover Bodies is proof of their confidence in and approval of the York-Hoover product. Specific purpose design for low "per package" delivery cost, experienced and skilled engineering for dependability, and honest workmanship for economical maintenance and low depreciation—all contribute to this customer confidence and approval.



To meet this healthy, steadily growing demand, York-Hoover has increased plant and production facilities so that we hope to say "prompt deliveries" in the not-too-distant future.



Washington Runaround

(CONTINUED FROM PAGE 146)

not likely to be issued for at least another month. In fact, as this issue went to press, the Commission was still receiving briefs from interested parties. FCC officials told COMMERCIAL CAR JOURNAL that it is barely possible that the proposed decision will be handed down during the next 30 days, but that it is impossible to predict an accurate date due to the heavy work load now facing the agency.

Even after the proposed decision sets forth the frequencies to be used by high-

way users operating radiotelephone units the Commission will still have considerable work ahead. The reason for this being the fact that interested parties are given another opportunity to comment on the proposed decision before the Commission prepares its final report.

52 Transport Reserve Units

In a year-end progress report, the Transportation Corps states that 52 reserve units have been furnished by the trucking industry as part of the TC's Highway division reserve establishment.

These units scattered through 26 states and the District of Columbia include: 13 Highway Transport Divisions; 12 Transportation Truck Battalions (Heavy); 24 Transportation Truck Companies (Heavy); and 3 Transportation Truck Companies (Petroleum).

Emphasizinp the part played by state associations, the report states that the leading association in the total number of units affiliated is the Motor Truck Association of Southern California with a total of nine units affiliated in the Los Angeles area. The Ohio Association of Commercial Haulers is next with four units in Columpus.

"In the near future," the report continues, "a program for the commissioning of officers directly from industry will be put into effect. It is hoped through this program to encourage the experienced operators, maintenance personnel, driver instructors, terminal managers, and other qualified personnel to accepted commissions within these affiliated organizations. A recent Department of the Army circular has authorized certain Transportation Corps officers to serve over-age in grade. This will allow certain trucking industry personnel who would otherwise be disqualified to take an active interest and to participate in the organization of these highway units."

The Transportation Corps admits, however, "that the program has a long way to go with several hundred additional units varying from skeleton organizations of a few officers up to and including units of officers and enlisted men at full strength."

Transportation Corps officers hope that in the near future they will be able to visit states not already contacted and bring additional units into the program.

Interested associations or truck companies who desire to participate on the program are urged to contact Ray G. Atherton of the American Trucking Association, or Colonel Ross B. Warren, Chief, Highway Transport Service, Office Chief of Transportation, Washington 25, D. C.

END

(Please resume your reading on P. 77)

NEW SYNTHETIC RUBBER

A new synthetic rubber which may equal or surpass natural rubber in tire treads was described recently by John P. Coe, vice-president and general manager of United States Rubber Co.'s synthetic rubber division. He said two large plants are now being equipped to produce the new rubber, which results from research conducted by the synthetic rubber industry under sponsorship of Office of Rubber Reserve.

"Preliminary data have indicated tire tread quality substantially improved over anything achieved heretofore with natural rubber," Mr. Coe said. He added that even the most conservative chemical engineers rate the new rubber as "at least equal to natural, according to preliminary data."

Secret of this improvement in man-made rubber, Mr. Coe indicated, is a sharp reduction in temperature of the chemical reaction by which the GR-S is produced from butadiene and styrene. The new rubber is made at temperatures between zero and 40 deg. F, instead of at the customary 125 deg.



The new "Knock-Out"

1/4 h.p. portable electric driver takes the labor out of cutting valve seat recesses. Just hold on top of tool—
no pressure required—
and feed cutter down to set depth. It's that simple and almost that fast.



FITS ALL "KNOCK-OUT" RESEATER SETS



Can be used with the "Knock-Out" Reseater Set you now have! Or if you have some old style reseater tool you'll want to replace it with a modern power driven "K-O" Reseater Set. Three set sizes—one to fit any requirement.

ASK YOUR JOBBER or Mail the Coupon TODAY!

K. O. LEE Company

1102FIRST AVE. S. E., ABERDEEN, SOUTH DAKOTA
Please send illustrated bulletin describing in detail the "K-O" R-5 Power Drive and Reseater Sets.

City.....State.....

Name......Address.....

ABERDEEN, SO. DAK.



Hear the beat of that Diesel on the grade? Telling its own story of how Lo-Ex pistons cut costs. 3 ways—

T-SLOT, CAM-GROUND, LO-EXPANSION—pioneered by Alcoa. The T-slot, cam-ground piston of Lo-Expansion alloy gives you closer fit—better compression—at high temperatures without excessive cylinder wall wear.

HIGH HEAT-TRANSFER—Lo-Ex alloy pulls heat from the piston head $2\frac{1}{2}$ times faster than cast iron. That means no localized "hot spots". The piston does its share of cooling—your engine oil is

used more as a lubricant, less as a thinned-out refrigerant.

LIGHT WEIGHT—The lighter weight of Lo-Ex pistons saves engine wear. Bearing loads are cut, vibration held down.

Lo-Ex pistons give you economy—and trouble-free operation—longer than any other pistons. When you order replacement pistons—whatever trade name you buy them under—specify Lo-Ex pistons of Alcoa Aluminum—the finest aluminum piston castings. Aluminum Company of America, 1916 Gulf Building, Pittsburgh 19, Pennsylvania.

LO·EX Pistons of Alcoa Aluminum



en

(CONTINUED FROM PAGE 36)

be kept on a strictly economic basis, with a minimum of distortion from the arts of persuasion and the ties of personal loyalty.

Source of Earnings

THE major source of earnings on capital invested in a truck replacement is cost savings. A new truck

should be bought when the reduction in future expenses will be great enough to earn a satisfactory return on the capital outlay. Earnings should exceed the standard of capital productivity for alternative marketing investments discussed above.

The replacement decision, to be sure, is contingent upon two absolute standards of minimum satisfactory performance: capacity and appearance.

Physical capacity to do the required job effectively (i.e. reliability,

safety, etc.) is not usually determining. Increased repair expenditures could keep old equipment in good working order for almost indefinitely. If old trucks are brought to virtual par with new trucks in service adequacy, then the question is: at what stage does the rejuvenation cost too much? If maintenance is not carried to this parity point, some allowance must be made for the added losses of sub-standard performance. Whether it pay to maintain to the point of performance parity with new trucks is a different problem from ours. Thus it is not the standard, but the cost of keeping trucks up to standard that governs replacement.

The second absolute standard, appearance, is also not determining. Repainting can keep even the oldest of trucks reasonably pleasing in appearance.

Thus neither of these standards is controlling. The real test of truck replacement investment must be profitability of the investment, as shown by estimated cost savings.

Graphic Analysis

THE essence of the economic replacement analysis can be shown by a simple graph. (Fig. 1). The costs of continued use of a vehicle are a function of age and mileage. Hence the behavior of costs with increased use is the key to determination of the cost savings that should govern replacement. Fig. 1 shows cost curves in terms of annual cost for a constant route for a hypothetical \$5000 truck. The curves are theoretical and are designed solely to illustrate the method. They do not portray actual cost behavior of a specific truck. The shape of actual curves differ widely among operators depending upon operating conditions, account classification, standards of preventive maintenance, etc.

The capital wastage cost curve declines sharply at first and then falls off more and more gradually as the truck gets older. The curve shows the market-price depreciation, based on the expected decline in disposal value during each year.

The maintenance cost curve represents the increase in annual maintenance and repair expenditures which will occur over most of the life.

(TURN TO PAGE 152, PLEASE)


Another First by Teleoptic Teleoptic's 'OK-PASS'



Here's a new Teleoptic lamp that will earn-for the truck operator—the thanks of all motorists. Ends flashing of headlights and specifically tells the driver behind whether or not it is safe to pass. Truck driver merely presses a button; when he lets go, light goes out.

ASK YOUR JOBBER

THE Teleoptic Company



IT'S THE "Spring-back" THAT COUNTS



PARISH

Heat-Treated Frame

The Keel of the Chassis

Made of special steels and alloys, formed by high-tonnage presses, heat-treated, tested and straightened by competent master craftsmen, *PARISH FRAMES* have a quality that makes them different—the "Spring-back."

Because of the resilience of PARISH Heat-Treated FRAMES the parts attached to them are held in correct relation to each other in spite of the stresses and strains caused by a rough road underneath, or a heavy load above; and "spring-back" immediately to their original position. They have a strength value 125% greater than frames made from commonly used steels and last years longer.

When buying new trucks and trailers or replacing worn-out frames, insure longer, trouble-free operation by specifying *PARISH Heat-Treated FRAMES*—the frames with the "spring-back"—the "keel of the chassis."

PRESSED STEEL HEAT-TREATED FRAMES FOR TRUCKS AND TRAILERS

PARISH PRESSED STEEL CO. Subsidiary of DANA CORP. READING, PA.

Western Representative: F. Somers Peterson, 57 California St., San Francisco, Cal.

ed al

VI.

(CONTINUED FROM PAGE 150)

The operating cost curve rises gradually at a declining rate. This cost might include customary operating expenses such as gasoline, lubricants, tires and incidentals.

The unreliability cost curve reflects an estimate of the direct and indirect losses from increasing undependability as indicated on road breakdowns and idle time for repairs. It is presumed to rise continuously as the truck ages.

The combined cost curve for the old truck is the sum of the several component cost curves. It declines at first, reaches a low point and then rises when rising maintenance operating and unreliability costs more than offset the declining capital wastage costs.

Average combined cost of new truck is shown in Fig. 2 by the horizontal line. It represents the expected future average annual cost of a new truck. It is computed by dividing the total estimated cost of the new truck (without interest) throughout its expected useful life by the number of years in its expected useful life.

The point of economic replacement is determined by prospective cost savings from replacement as a percentage of the net capital expenditure required to obtain these savings. Cost savings are shown by the spread between the curve of combined cost of the old truck and the line of life-time average cost of the new truck, bevond their point of intersection. To get the rate of return on investment this cost saving must be related to net capital outlay, i.e. the original cost of the new truck minus the present disposal value of the old truck. When this rate of return equals the minimum standard return (determined by the profitability of alternative uses of company capital funds) then it is economically sound to make the replacement investment. This point is diagramed by the arrow.

Now let us dig into the concepts and estimating methods upon which the method sketched above is built.


Future Costs


FOR estimating capital earnings of a truck replacement it is not past costs, but future costs which are relevant. True, the records of historical cost are valuable for making this estimate. But they are valuable only to the extent that past costs and present costs can serve as a guide to estimating future costs.

In the case of recurring costs, such as maintenance, losses from breakdowns, gasoline, tires, and other operating items, the costs which were incurred in the past serve as a valid starting point in estimating costs which will be incurred in the future. But past costs of one specific truck are not necessarily the best guide. Average cost of a number of trucks under similar operating conditions probably constitutes a better indication of the cost which will be incurred in the future. These averages need to be adjusted to foreseeable changes in wage rates and materials prices, etc.

Should the cost unit for comparison of old and new trucks be cost per year, per mile, or per service unit?

(TURN TO PAGE 154, PLEASE)





• Every set of American Brakeblok lining is "frictionengineered" to meet the requirements of specific makes and models of vehicles.

All the braking factors peculiar to each car, truck or bus are carefully taken into consideration to make sure each set of lining has the right combination of braking values for maximum safety and economy. Altogether, American Brakeblok manufactures twenty-five different types of friction material—assuring a correct brake lining for every fleet unit.

American Brakeblok is an entirely different and better kind of lining—a lining that's the same all the way through. It wears smoothly, evenly... provides constant friction value throughout its life... has stable braking characteristics under the highest temperatures and pressures of heavy-duty service. And the fact that it is non-compressible under all braking pressures eliminates the need for frequent adjustments.

For best results, always reline with American Brakeblok. Your maintenance records will prove it pays. Just call your nearby NAPA Jobber—give him precise information on the make and model of vehicle and its braking system. He'll supply you promptly with American Brakeblok axle sets, "friction-engineered" to meet your exact needs.

3 DISTINCT TYPES OF HEAVY-DUTY BRAKE LINING



REGULAR: Recommended for vehicles with manual brake systems. Also usable on vacuum or air brake systems, but may produce needlessly severe brake action, thus shortening service life. Available in rolls, complete sets and axle sets.



1,000 SERIES: Engineered primarily for vehicles with vacuum power booster systems. Also recommended for air brake systems where there is need for greater deceleration than is provided by 2,000 series. Available in axle sets only.



2,000 SERIES: Designed to give maximum mileage and efficiency when operating under extreme braking conditions with air brakes or powerful vacuum systems. Available in axle sets only.

"C" SERIES: Thick blocks to be used on air brakes only (or powerful vacuum systems).





American Brakeblok is distributed through 39 NAPA Warehouses, assisting jobbers everywhere to give prompt, complete service.



AMERICAN BRAKEBLOK DIVISION

American Brakeblok

(CONTINUED FROM PAGE 152)

Each of these cost units is satisfactory under some circumstances.

Cost per service unit (e.g. ton mile) is usually more adaptable to a variety of route conditions. But even so it fails to reflect them completely and it often is less closely related to truck cost behavior than some other unit. If size balance of the fleet has been substantially attained and replacement is confined to trucks of equal size for approximately the same route, then cost per year is an adequate basis for a comparison of future costs of the old and new truck.

Averaging Costs

TO make a valid comparison for purposes of a replacement decision all costs of the new truck must be life-time and averages. Why is this so? If we compared the cost of operating an old truck for the next

year with the cost of a new truck for the first year of its life, we would arrive at thoroughly misleading con. clusions. It is incorrect to consider only the costs which will be incurred early in the new truck's life, when maintenance and repair charges, for example, are known to be low. The decision to keep the old truck in operation makes only a short period commitment, to use the old truck for another year or even less. But the alternative decision to buy a new truck makes a long-term commitment to incur costs of running this new truck throughout its economic life. You are committed to the whole course of the maintenance curve, not just to its low initial phase. Hence it is the lifetime average level of the curve that is relevant for the new truck.

The economic life of the new truck is unknown; yet it must be forecast for this and other purposes. "Economic life" varies not only among makes but also among users depending upon type of service and standards of preventive maintenance. Ultimately it depends also upon the way the replacement decision is made.

To estimate economic life it is necessary to consider probable obsolescence. This involves a guess at the age (in years or miles) at which cost savings (over and unborn new truck) will give a high enough payout to justify replacement of the truck you now consider buying. It is obviously impossible to do this accurately, yet it will be better done if we recognize the concept we are guessing at. Actually we do, or should do this each time we set a depreciation rate. In a sense the only sure way to find the point of economic replacement by experience is to go past it. War conditions have given some operators this instructive experience, so that they have a historical bench-mark for estimating future economic life, to be modified for changed conditions.

In using past replacement experience as a bench-mark adjustments must be made to take account of the changed construction of new trucks and changed operating conditions. But the biggest hazard is the rate of future obsolescence. Hence it is probably safer to err in the direction of underestimating economic life.

(TURN TO PAGE 156. PLEASE)

ROAD TIME PAYS DIVIDENDS

Keep Em Rolling Paying





Repair lay-up time is reduced more than 40% when trucks are Hypressure Jenny steam cleaned before your mechanics start working on them. That means you get them back on the road in practically half the time. Periodic Hypressure Jenny steam cleaning often reveals worn and damaged parts for repair before dangerous, time-consuming, road failures occur... increases pay loads by ridding chassis of as much as 400 lbs. extra weight due to accumulated road dirt... assures more economical operation... reduces fire hazards. Besides keeping your fleet "rolling and paying," Hypressure Jenny further adds to your profits by cleaning garage floors, runways, grease racks, pits, tools, machinery, walls, windows and skylights 8 to 10 times faster and better than by hand methods.

Write today for further particulars and the address of your nearest Hypressure Jenny Dealer.

HYPRESSURE JENNY DIVISION

HOMESTEAD VALVE MANUFACTURING CO., P. O. BOX 90 CORAOPOLIS, PA.



WHITAKER LABEL Assures Quality Cable




(CONTINUED FROM PAGE 154)

To make a forecast of the economic life of a new truck might appear to beg the question, but, actually it does not, because the question at hand is whether the specific truck now in operation has reached the end of its economic life. To make estimates of the normal economic life of a group of similar trucks and to use

such estimates in determining the economic life of one particular truck is, therefore, fully defensible for a new truck.

It is clear that the amount of the average life-time cost of the new truck, and, therefore, the conclusion drawn from the cost-savings comparison itself will be greatly affected by the length of span over which the average is computed. Hence, determination of the period of probable economic life of a new truck justifies the best possible forecasting.



APITAL wastage is the disappearance of investment value as a result of use or the passage of time. It must be taken into account to get net earnings for estimating capital productivity. For capital budgeting purposes, the element of return on money should be viewed not as a part of capital cost but as the unknown end product of our analysis. Since it is the magnitude of the capital return that determines what the replacement decision should be, this element is, for present purposes, not considered a "cost" of capital. Return on a \$10,000 net investment for truck replacement is the cost savings. If they were \$2000 a year, the investment return would be 20 per cent.

The original acquisition cost of a truck that is now in operation is sunk and irrecoverable. It can in no way affect the future money outlays or the future real profits of the com-The depreciation charges shown on the books (though they can affect the timing of the company's recognition of its profits or losses) are similarly independent of the company's real future costs and real future profits. Hence, the acquisition value and the accrued depreciation must be dismissed entirely from consideration in the comparison of future costs of an old truck with future costs of a new truck. These bookkeeping values may be perfectly sound for financial bookkeeping and income tax purposes. Nevertheless, the book value of an old truck is not of any significance in making a decision on whether to replace or not.

The only real future capital wasteage costs of a present truck will arise from the future decline in the disposal value of that truck. For example, if a truck can now be sold for \$8000 and next year can be liquidated for only \$6000, then the additional capital loss which the company will incur by keeping that truck in operation for another year is \$2000. The capital cost of retaining a present truck in operation is its future decline in liquidation value. This holds true no matter what the cost of the truck was when originally purchased, no matter when that purchase took place, and no matter how much depreciation has been charged for financial accounting purposes.

(TURN TO PAGE 158, PLEASE)



The New, Improved WABER TUBE is Guaranteed not to go flat because of cuts, puncture, rim pinches or blow outs occurring as a result of road hazards.


Read

WRITTEN GUARANTEE WITH EVERY TUBE

Equip Your Trucks and Cars with Waber Tubes To-day! Your Profit from longer tire wear and maintained schedules will begin tomorrow!




Under new, U.S. Patent, an important new principle has been added to the well known Waber Tube.



THE WABER COMPANY

FOR ON-THE-JOB PERFORMANCE use the HALL-SCOTT "400"



- 1. High Torque-Low R.P.M.
- 2. Long Life
- 3. Minimum Maintenance
- 4. Gasoline or Butane Equipment
- 5. Clean Operation



MOTOR DIVISION

ACF-BRILL MOTORS COMPANY

Factory and Main Office: Berkeley 2, California
New York Branch: 254 W. 31st Street



AUTOCAR



KENWORTH



MACI



INTERNATIONAL



DART



PETERBILT

Branches

Boston, Philadelphia, Chicago, Dallas, Los Angeles, Soattle, Berkeley

(CONTINUED FROM PAGE 156)

The problem of estimating capital wastage cost for the old truck consists, then, of (a) surveying the market to see what the truck in question can now bring, and (b) estimating the amount which will be realized if the truck is kept longer (e.g. sold one year hence).

Fig. 3 illustrates the kind of esti-

mate of the behavior of normal disposal value that is needed for this purpose. It portrays disposal value of a light truck as a function of age. The top curve shows estimated disposal value at the end of each year. The bottom curve described by the bars, shows the loss in disposal value during each designated year. This derivative curve represents the capital wastage cost which will be incurred by retaining the old truck in operation. It is this shrinkage in market value which is relevant for

determining whether the present truck should be replaced. The capital wastage curve in Fig. 1 was developed in this way from normal values.

Shifts in the disposal value curve may occur as a result of rising prices of new trucks or from a dramatic change in the shortage of new and used trucks. As we approach the end of this shortage epoch the probability of a break in used truck prices should be included in the replacement cost comparison. These shifts complicate the estimates of future decline in disposal value. The economic method is capable of dealing with this problem, within the limits of accuracy of forecasts of the shifts. Fig. 4 illustrates the technique. Curve A represents the disposal value function now, Curve B is this forecasted curve one year hence. To estimate the future capital wastage we must hop from the age two value on Curve A to the age three value on Curve B, instead of moving down one year on Curve A as in a normal market. Thus on the diagram the estimated future decline in disposal value is the distance D instead of the normal wastage C. For very old trucks the age decline becomes negligible and the market shifts may become relatively more significant in estimating capital workage.

Even when the company's policy is to trade-in or to junk retired equipment, rather than sell it second-hand, it is, I think, sounder to have the market price of used trucks be the criterion for replacement decisions. Trade-in values are often distorted by new truck scarcities or veiled concessions. Junk prices are correct enough if this is the best obtainable price. but junk sales to keep trucks from competing with you is an incorrect value guide for replacements.

True, the truck you have owned since birth has more value to you than a truck of the same vintage bought second-hand. You know your own truck's care and condition and you rightly suspect the worst of the used vehicle. But it is not the level of the disposal value curve, but its rate of decline that affects this replacement test. If a constant premium were added to the disposal value curve to reflect high use value from known condition of the truck, the capital wastage function would

(TURN TO PAGE 162, PLEASE)

They Go Together...

THE NEW 1948 TRUCKS and ANTHONY HYDRAULIC EQUIPMENT...



ANTHONY MODEL D-50 GARBAGE BODY.

MODEL D-6 CONTRAC-TOR BODY— SUPER HOIST.

Anthony Company has simplified the entire problem of matching the proper dump bodies with the proper sized trucks. It is easier to recommend and sell Anthony Hydraulic Products on 1948 trucks because they are built to "go together."

Write for "Easier Dump Truck Sales."



ANTHONY MODEL JIR-14 ROCK BODY



MODEL X-150 ALL STEEL PLATFORM BODY WITH HOIST.



ANTHONY "SUPER"
HOIST—HEAVY DUTY.
"J" BODY.



"LO-DUMPER"



MODEL D-18 STREET DEPT. AND HIGHWAY BODY.



MODEL TH-88 SEMI-TRAILER HOIST. "R" BODY.



ANTHONY
'LIFT GATE" LOADS-UNLOADS TRUCKS.





ANTHONY COMPANY Dept. D-83, Streator, III.

> Distributors throughout America

ALLOY WHEELS

Reduce Weight Up To 55 lbs. Per 20 Inch Wheel Assembly

TO AD PROVED TO TO THE PROVED TO

de-

nal

rve ces

tic nd the

fts le-

nic

th ic-


A

on

he

op

The casting of Permold Aluminum Alloy Wheels is made possible by skill and experience — 27 years of foundry experience — utilizing the correct alloy, heat treating to obtain maximum strength, and with constant quality control for metallurgical uniformity.



perMold

This mark on inside of spoke identifies genuine Permold Aluminum Alloy Wheels.

Specify

ALUMINUM ALLOY WHEELS

(CONTINUED FROM PAGE 158)

remain the same. Moreover, disposal value rather than your own use-value becomes the relevant value eventually, and this analysis is designed to find out whether or not "eventually" is "now."

The total capital wastage cost which will be incurred by buying a new truck is its original acquisition cost, less its ultimate re-sale value. Since the unit of cost comparison in this illustration is one-year, the appropriate capital wastage cost for the new truck will, therefore, be the average annual capital wastage cost over the entire period you expect to own

Are the two concepts of capital destruction fully comparable for our purposes? I think so. For the new truck capital wastage is the difference between original cost and eventual disposal value, averaged annually over the expected economic life of

Eight cubic

the new truck. For the old truck. wastage is the present disposal value less the amount of money which could be realized later, if not replaced now. (Shown by bars in Fig. 3.) Both represent the additional real costs of the alternatives being compared. The added capital shrink. age of keeping the old truck is the decline in disposal value. This is the future cost controllable by the decision to keep it another year. Its original cost is sunk and therefore irrelevant. But for a new truck not yet purchased it is its original cost (less ultimate disposal value) that is the comparably fully controllable future cost.

The two concepts of capital wastage are also consistent as life-time totals. The annual capital shrinkage figures shown in wastage curve of Fig. 1 will add up to original cost less ultimate disposal value (i.e. at the end of projected economic life). The vital difference between a market disposal value curve and a book value curve as shown in Fig. 5, is in the time distribution of values not in the aggregate amount accounted for. Disposal value is based on economic facts of the market place; this is illustrated by curves A and B of Fig. 4. Both curves are based on the same ultimate disposal value at the end of a 7-year projected economic life. Hence both show the same aggregate life-time capital wastage. The disposal value estimate is based on economic facts of the market place. The capital shrinkage derived from it (curve C) is high the first year, then falls to zero the last 3 years of economic life. The year to year distribution of capital wastage indicated by the conventional straight line depreciation is quite different. It is exactly the same each year (as shown in Fig. 5 by Curve D, derived from curve B, Fig. 4). It is this timedistribution, not the life-time aggregate which does not square with market facts, and hence cannot be used in projecting the added capital wastage of operating the old truck another year.



DUMP BODIES and HYDRAULIC HOISTS

Marion Bodies and Hoists are "Designed On The Job" to meet actual work conditions, by engineers with the field experience and the practical "know-how" to solve "tough-nut" loading, hauling and dumping problems.

There is a Marion Body and Hoist for every hauling job. . . designed to fit all makes of truck chassis. Write direct, or to your nearest Marion Distributor, for literature, prices and information.

MARION METAL PRODUCTS CO., MARION, O.

Maintenance Costs

THE relevant comparison of the maintenance costs of the old truck and the new truck is between (a) expected future maintenance costs of (TURN TO PAGE 164, PLEASE)

If trucks could talk, here's what they'd say . .



Do you want LOWER operating costs? Then equip your fleet with Fram filters and cartridges—and watch repairs drop, lay-ups go down, while operating hours go up!

That's pretty strong talk—but Fram has the stuff to back it up. Fram cleans the oil that cleans the motor, keeps out dirt, dust, grit, sludge and abrasives, thereby prevents much unnecessary wear. On thousands of trucks, on hundreds of fleets, Fram filters and cartridges are doing a valuable day-in, day-out job.

So if you haven't found out about Framnow's the time to do it! You take no risk when you do. Read Fram's guarantee . . . it gives you complete protection. Then call your Fram distributor today and start saving on breakdowns, overhauls, replacements and repairs.

NOTE: If your fleet already has filters, install genuine Fram replacement cartridges to get maximum filter performance. Fram Corporation, Providence 16, R. I. In Canada: J. C. Adams Co., Ltd., Toronto, Ont.

GUARANTEE

Install Fram filters on your fleet. If you feel, within 90 days, that you can afford to operate without them, your purchase price will be cheerfully refunded,

FRAM FILCRON FILTER

Cleans the Oil that Cleans the Motor

FEBRUARY, 1948

Use postage-paid card inserted at page 61 for free information on advertised products

163

(CONTINUED FROM PAGE 162)

the old truck during the next year, and (b) average annual future maintenance cost of the new truck over its expected economic life. Both of these items of comparison are, necessarily, estimates. But for both of them, the historical records of past costs will be valuable aids to projection. In most instances the individual maintenance cost records for the old truck will be

less valid as a basis for estimate than will be average past maintenance costs for a number of similar trucks in similar operating circumstances. These past costs, even though they are averages, should not, however, be taken as estimates themselves. Rather, they are starting points only, which need to be modified, adjusted, and improved in the light of whatever additional knowledge and judgment are available at the time of the estimate. Changes in wage rates, in parts prices, and in routes, all are

factors which will affect future costs and should be taken into account in developing the estimate.

In estimating the expected maintenance for the old truck during the next 12 months, it is well to separate major repairs from recurring maintenance. The cost of a contemplated major repair should be amortized over the expected life of that repair job to obtain its annual average cost. Sometimes the added life can best be estimated in mileage then converted to years. The estimate of recurring maintenance expected for the next year can be developed from life cycle curves for similar trucks in the same service. These must be adjusted to reflect wage rates and parts prices expected during the next year. This actuarial figure needs also to be modified to take account of the history and condition of the individual truck under consideration.

Maintenance cost probably does not increase indefinitely with age. The average age of parts does not continue to increase after the truck has been properly maintained over several hundred thousand miles. The level and shape of the maintenance cost curve will differ among companies depending on standards of preventative maintenance, methods of classifying accounts and character of truck route.

The shifts of the curve caused by changes in wages, productivity and parts prices are also a major consideration in forecasting maintenance costs. These shifts are illustrated by Fig. 6. Projection involves hopping from curve to curve as well as moving to a higher age bracket.

For the new truck an estimate of life-time average annual maintenance cost is needed. It should be built up by adding estimates of maintenance costs during each of the years of expected service. This will include anticipated major overhauls as well as all recurring maintenance and repair expense. In developing this estimate, consideration should be given to average maintenance expense of similar trucks in their various years of service in the past, but adjustments should be made to give effect to expected price levels, wage rates, labor efficiency and shop conditions. Maintenance inaccessability that is characteristic of many new models must also modify the maintenance

(TURN TO PAGE 166, PLEASE)



The man sitting behind the wheel in the driver's seat of a truck or a bus has many anxious moments.

That is especially true at this season of the year when roads are slippery and TRACTION is ZERO.

It is hard to imagine a more helpless feeling than the sensation of knowing that trouble lies immediately ahead. One such experience will last a man a lifetime.

You cannot control the weather nor road conditions, but you can equip your trucks or buses to reduce driving hazards down to a minimum. Nature does not always provide proper TRACTION. To be on the safe side, you can carry your own TRACTION, and the means of dispensing it at the flip of a switch.

By installing and using Elston Electric Sanders you eliminate anxiety and uncertainty from the minds of your drivers—you also protect your property and save time.

Elston Electric Sanders are approved by Underwriters' Laboratories.

Your Dealer Has Them



TRACTION IS NEEDED



HIGHWAY SAFETY APPLIANCES, INC.

"Our Experience with WORLD BESTOS Hetro Blocks and Truck Sets has been EXCELLENT"





• Some of the busiest highways in the country are traveled daily by the 43 interstate transportation units of the Merchantville (New Jersey) Express Company. For years this company has been a user of World Bestos Hetro Brake Blocks and Truck Sets.

Mr. Harry J. Collins, president of the Merchantville Express Company, has this to say about these World Bestos heavy duty brake linings: "Our experience with your materials has been excellent. Our vehicles have no difficulty stopping in the heaviest traffic. Our cost per mile for brake lining is very low. We feel that Hetro Blocks are giving everything as to wearing qualities and stopping ability that a truck operator could ask for."

Hetro Brake Blocks afford such performance because they wear slowly in even the most severe service while providing a stable, resilient friction under all operating heats and pressures. Try a set of Hetro Blocks and compare them to those you now use. The difference will repay you!

BRAKE LININGS



BRAKE BLOCKS

WORLD BESTOS

CORP.

6288

NEW CASTLE . INDIANA

r

ie

of

of

y

of

e

X-

lle

en of

ct

is.

AL

(CONTINUED FROM PAGE 164)

estimate based on past experience. This life-time total of maintenance expense should then be averaged over the expected life of the truck.

Operating Costs

LIKE maintenance costs, the future operating costs must also be estimates. To an important degree historical cost records can form the groundwork for the estimates. Better estimates can be developed from averages of much similar trucks than are obtainable from the records of one individual truck.

The expected cost of gas and oil for the old truck during the next twelve months can best be determined by first estimating a per-mile cost and then multiplying the permile cost by the expected annual mileage. Past costs of the same truck and average costs of similar trucks in similar operating conditions will serve as a basis of estimate. Tire cost should also be estimated on the basis of per-mile tire costs. For new

trucks a life-time average should be developed by parallel methods.

Many fleet operators find that operating costs (gas, oil and tires) rise only slightly with truck age. Much depends on maintenance and care standards. Omission of these costs from the replacement comparison is a warranted simplification if this cost curves rises only slightly. Estimating errors of more differentiating costs may make operating cost differences negligible. However, if future new trucks promise significant fuel savings omission of these costs will make the test fail to detect operating cost obsolescence.

Unreliability Cost

OLDER trucks may be more unreliable. Losses which result from truck break-downs or other idle time occasioned by lay-ups for repairs should therefore be included in the comparison. Developing estimates of this cost will involve two steps: (1) Estimating the idle time in terms of days, and (2) placing a money valuation on the losses, largely on idle time in the form of a per-idle-day cost. The first is comparatively easy

if good records of past experience are available. Dependability will be affected by maintenance standards, hence changes must be reflected. The second requires much guess work, for the indirect costs should be included, and they are often large and hard to quantify. One approach is to use the day costs of a comparable unit from the relief fleet. Another is to take the market rental figure. To these must be added costs of idle crew, towing costs, etc., for on-the-road breakdowns.

Unreliability costs may be such an important difference that even a rough evaluation is much preferable to omission of the cost from the comparison.

Earnings and Investment

A ONE-YEAR cost comparison using the foregoing estimates of cost will provide the answer to the question of whether replacement is justified on the basis of capital earnings in the form of future cost savings. In general terms the answer can be stated thus: The present truck should be replaced if its expected (TURN TO PAGE 168, PLEASE)

finally—a fuel pump with no diaphragm fatigue!

HYGRADE

Fuel Pumps

Hygrade fuel pumps have always given trouble-free performance. Precision manufacture, rigid quality control and the finest in steel alloys have earned for Hygrade the quality name in pumps.

And now—Hygrade introduces a new, amazing, one-piece, diaphragm. It defies gasoline, alcohol, benzene. It takes the meanest, sharpest changes of temperature without a twinge. Road tests have proven it lasts longer because there's no distortion! Hygrade fuel pumps can cut your down-time and your cost-per-mile. Try them and see.


fuel pumps • kits and parts carburetor kits and parts complete line of fuel filters

HYGRADE DIVISION • Standard Motor Products, Inc. 35-35 Thirty-Fifth Street, Long Island City 1, New York.





IT KEEPS ENGINES CLEANER!



IT'S QUAKER STATE OIL



The longer you work with trucks and buses, the more you realize that most engine troubles are caused by:

- a. Wear of working surfaces
- Do Clogging deposits on working surfaces

That is why a modern lubricant for truck and bus engines must perform two functions well. ■• It must combat wear effectively by doing a better, more lasting lubricating job.

2. It must prevent "dirt," in the form of sludge, gum and sticky "varnish," from being deposited on engine working surfaces.

Quaker State HD Oil is made especially to do this double-duty job under the severe conditions usually encountered in truck and bus service.

It is a real "double-duty" oil that not

only *lubricates* but *cleans* engines—helps keep them in better shape with less servicing. It will pay you to prove these facts by trying Quaker State HD Oil in your equipment.

QUAKER STATE HD OIL AND SUPERFINE LUBRICANTS

- Use Quaker State HD Oil for trucks, buses, taxis, tractors.
- Use Quaker State Motor Oil for passenger cars.

QUAKER STATE OIL REFINING CORPORATION . OIL CITY, PENNSYLVANIA

(CONTINUED FROM PAGE 166)

costs (both capital and operating) during the next year are higher than the average annual costs (both capital and operating) of a new truck by a sufficient margin to yield an adequate cost-savings return on capital. Otherwise the present truck should be retained and kept in operation.

In order to get an earnings rate you must determine amount of capital tied up in the replacement investment. This can be obtained by finding total outlay for the new asset (including all acquisition and installation charges) and subtracting from this the present disposal value of the asset which is displaced by the new acquisition. This is the amount of money on which the company will forego earnings elsewhere if the truck is now replaced. This net outlay is the correct concept for these reasons:

1. The annual savings is a com-

parative figure representing the superior efficiency of the new truck over the old. Therefore, the outlay to which it is related should also be a comparative figure, showing the additional investment required to achieve these savings.

2. The current disposal value of the old truck is the amount of capital which the company will receive if it is decided to replace it.

3. The eventual liquidation value of the new truck when it is replaced many years hence has no bearing for this calculation, since that money is still tied up and must show earnings to justify the investment. It is relevant only for determining the depreciable total from which to calculate annual capital wastage, which is an entirely different problem.

4. The book value of the old truck is not relevant for determining the net amount of present investment. If the truck were sold and replaced with a new one it would not be the book value but the present disposal value which would become available for

investment elsewhere.

Obsolescence

A PROBABLE consequence of making motor vehicle replacements compete on a payout basis with alternative investments of the company's capital is a substantial reduction in retirements, so that obsolescence may become the dominant cause of truck replacements.

Truck obsolescence comes from several sources. Substantial improvements in fuel cost, in legal load, in maintenance accessibility, in cab comfort or in speed could make some existing equipment obsolete. Advances in body design so as to save motions and incorporate the latest material-handling equipment could make bodies and trucks obsolete.

To determine whether such improvements have actually made your existing truck obsolete requires exactly the same kind of analysis we have just discussed. The only economic test of obsolescence is cost savings, translated into return on investment. Only by comparison of (1) the added costs of continuing to run your old truck with (2) the full lifetime cost of the new truck can this acid test be applied. If costs are in terms of service units, an exten-

(TURN TO PAGE 212, PLEASE)



There's a type and size for nearly every car and truck in America. At Jobber's.

Write for free bulletin listing U. S. heavy duty replacement axles for Army Surplus trucks.
The U. S. Axle Co., Inc. Pottstown, Pa.





FIRESTONE Advanced Rims are designed to interchange with ALL former types of flat base rims without change in spacings. For example, dual mounted 10.00 or 11.00 tires on Firestone R-5° Rims have the same clearances, the same loaded radius as with standard flat base rims. Rims can be paired indiscriminately with other types of flat base rims — without danger of mismatched duals or clearance damage. Firestone R-5° Full Advanced Rims are the only new wide base rims that will completely interchange with your

old rims.

Firestone Advanced Rims increase tire mileage as much as 40 per cent. You can have this extra tire mileage without a penny's cost. Simply specify "Firestone R-5" Full Advanced Rims" on your next truck order.

Listen to the Voice of Firestone every Monday evening over NBC
Copyright, 1947, The Firestone Tire & Rubber Co.

COMPARISON
OF
CLEARANCE
NEW 7.5 R-5° RIM
DISTANCES
10.00 TIRES-DUALS
7.33V (9-10") TYPE R RIM

INTERCHANGE ON SAME WHEELS WITH ALL FLAT BASE RIMS



FIRESTONE ADVANCED RIMS ASSURE TOP TIRE MILEAGE

su-

the

of piive

lue ed

is

reate

ck he If

ith

ue

ık-

nts

ith

m-1C-

30-

int

m

m-

ıd,

ab

ve est

ld

m-

ur

X-

we

00-

st

on

of to

ıll an

re

n-

AL

Penn Drake

GUMOUT

keeps trucks on the road longer . . . increases fleet efficiency



- * Cleans carburetors
- * Prevents gas-line freezing
- * Eliminates water
- * Reduces carbon formation
- * Makes starting easier
- * Maintains engine efficiency

Fleet owners, in steadily increasing numbers, are now using Gumout to keep equipment operating longer at top efficiency.

Gumout is composed of 100% active ingredients . . . powerful undiluted solvents. One pint to ten gallons of gas, every 1,000 miles, dissolves all gum and foreign deposits . . . keeps carburetors and fuel systems sparkling clean for efficient, economical operation.

Gumout also freeze-proofs the entire fuel system. It absorbs water present in gas tanks and fuel lines.

Also, Gumout is the perfect bench cleaner . . . will do a superb job in your service shops. It's another right hand for your mechanics.

Gumout is supplied to fleets in 5 gal. pails; 15, 30 and 55 gal. drums (sold in pint cans by gas stations and garages everywhere). Write today for full details and list of users.

PENNSYLVANIA REFINING CO.

2692 Lisbon Road • Cleveland 4, Ohio Butler, Pa. • Edgewater, N. J.

Vehicle Replacement

(CONTINUED FROM PAGE 168)

sion of our basic method to include labor costs will provide a positive test of obsolescence. It will not detect all kinds. Style and cab comfort obsolescence, for example, will be missed. But it will catch any that has direct impact on the unit costs that can be included in the analysis. These are for most operators the significant kinds of obsolescence.

This index of obsolescence has wide error margins unless used skeptically. For example, theoretical savings in drivers' time are rarely actually realized in full. Speed obsolescence will be largely a fiction until billions have been spent in highway improvement. Estimates of life expectancy of the new model, which affect the findings on obsolescence importantly, involve a rough forecast of the timing of unborn technical advances which will in turn make the new model obsolete. But this is a limitation implicit in all obsolescence criteria.

Replacement Test

WHEN should a replacement test be made? There can be no rigid rule. But an understanding of the underlying economics of the retirement test, coupled with intimate knowledge of the truck's condition. will indicate when it appears sufficiently likely that a new truck would pay out, to warrant a cost comparison analysis. Except for "lemons," replacement need not normally be investigated until the truck is near the end of its forecastal economic life (e.g., 3/4 depreciated). It is desirable to check it again about once a year. This routine should be set aside and a replacement analysis . should be made when a major overhaul is contemplated, when maintenance wages and parts rise drastically, when a dramatically new model becomes available, or when the market price of used trucks appears likely to fall very fast.

Limitations of Method

No method of determining when to replace a vehicle is without its limitations.

Now that I have called attention to (TURN TO PAGE 214, PLEASE)

CLAROFICATION

IS MAXIMUM ECONOMY

MR. FLEET OPERATOR: When you received your Autocar, Brockway, Buda, Diamond T, General Motors or Mack motor equipped with a WGB ClarOfier, you obtained the best filtration that money can buy—provided you use genuine WGB Cartridges, which are covered by patents preventing duplication. But if you use substitutes, which are prevented from using the WGB principle, you cannot expect WGB economy or motor protection.

The results which induced these manufacturers to equip their fine motors with WGB Oil ClarOfiers were obtained by use of the complete unit. It is not WGB filtration unless genuine WGB Cartridges are used. Substitutes cost more, because they do less. Be fair to yourself, to your motor and to the WGB ClarOfier. Use genuine WGB Cartridges and you'll get the economy, efficiency and motor protection which the manufacturer intended you to have.





Demanded for new trucks

.a requirement for old.

the best brake is AIR



Buyers of new trucks are specifying Bendix-Westinghouse Air Brakes in ever-increasing numbers, because they have learned that these brakes start paying their own way from the first mile. The operators of older vehicles are also following the swing to AIR. They recognize the obvious value of adding that extra margin of modern safety to a vehicle that has already rolled up thousands of miles. On old or new vehicles service costs are less, payloads safely made larger, scheduling more efficient, and driver satisfaction greater. The first mile or the 100,000th—the Best Brake is AIR—and the best Air Brakes are, of course, built by Bendix-Westinghouse.

BENDIX-WESTINGHOUSE AUTOMOTIVE AIR BRAKE COMPANY, ELYRIA, OHIO

the best All brake is

Bendin-Westinghouse

PERFECT GASKETS

We ring the bell again!

ANOTHER group of handy assortments by Perfect Parts — Gaskets for Exhaust Pipe Flanges, to fit practically all popular passenger cars on the road today. Packed 10 and 20 to a box. Each number boxed separately. Car name in bold type for quick spotting. In three Attractive Display Assortments to give you the widest coverage at a minimum investment.


See your jobber - TODAY

PERFECT PARTS, INC. 55 Amsterdam Avenue New York 23, N. Y.



Comparing FEATURE for FEATURE The KING' System of MOTOR Tune-up is the BEST Buy

• Many of our customers that have used the "KING" System of Motor Tune-up for many years say that comparing feature for feature the "KING" System gives the most for the money. When checking into testing equipment many are surprised at the amount of "KING" Equipment they can get for their money. Why not find out how you can modernize your shop with the "KING" System and make it really efficient without spending a large sum of money?



Ask Your Jobber or Write Us

The ELECTRIC HEAT CONTROL Co. 9127 INMAN AVENUE . CLEVELAND 5, OHIO GOOD. "KING" PRODUCTS SINCE 1914

APRIL
ISSUE
OF
COMMERCIAL
CAR
JOURNAL
Will be
the 12th
"FLEET
OPERATORS'
REFERENCE
ANNUAL"

Don't
Miss It

The

Vehicle Replacement

(CONTINUED FROM PAGE 212)

the defects of other methods I must pay for my fun by pointing out the deficiencies of my own plan. The limitations summarized below are not all peculiar to the economic method. Most apply with equal or greater force to other methods.

1. Errors of Estimating Costs. Since the replacement criteria are forward looking, the analysis is based on projections. These projections of future costs will have error margins. The size of these estimating errors will depend in part on how much knowledge you have of past patterns of cost behavior, and in part on ability to forecast the impact of future changes in conditions. Nevertheless, there will be less error from moderately good estimates of a correct concept will be than from the fictitious accuracy of precise figures on an irrelevant concept, which is, I believe, the alternate to this approach.

2. Errors of Estimating Economic Life. The estimate of the life-time unit cost of the new truck hinges on the accuracy of the projection of the length of its economic life. Dependent as it is on future durability, maintenance cost and obsolescence, this mortality estimate is bound to be inexact.

3. Requires Research and Analysis. To make good cost projections requires some research in cost behavior, based on records of past performance. But the records need not be different or more detailed than you want for other purposes. The only change is to subject them to economic and statistical analysis. The "economic" method also requires paper work analysis of individual vehicles to reach a replacement decision. But this is a small cost when so much is at stake. Actually, the entire replacement analysis can be put on a one-page form.

4. Requires Training. To get the full benefits of this replacement plan it is necessary that your staff and your superiors know what they are doing and why. They must have some understanding of the economic analysis and capital budgeting concepts on which it is based.

END

(Please resume your reading on P. 38)



WHY EXPERIMENT? Laboratory tests prove Wolf's Head is Best



rt

ot d. er

8. re ed of 8. rs h 18

n of r m

r-

le 28

1

).

C

e n

e

ŀ

0

Piston removed from engine operated under heavy duty service using a competitive heavy duty oil. Condition of piston. Compression ring stuck. Oil ring 100% carbon-filled. Coating of black varnish on piston skirt.



Piston in its existing condition was then reinstalled in same engine and operated under heavy duty service for only 25 hours using Wolf's Head Heavy Duty Oil. Result: Compression ring free. Carbon dissolving. Varnish disappearing.

Experimentation with different oils can prove very costly, but you do not have to turn your fleet units into individual testing laboratories. Wolf's Head has been tested for you time and time again in world famous laboratories . . . and consistently proven superior on all five essential heavy duty factors. That's why it pays to use Wolf's Head Heavy Duty Oil. It shortens down-time, lowers costs . . . by lengthening the life of the engine.

Remember. The fleet on the road is the fleet that makes money. So send for your copy of the free booklet describing these tests. Read for yourself how Wolf's Head can step-up the performance of your fleet. Wolf's Head Oil Refining Co., Inc., Oil City, Pa., New York 10, N. Y.

LABORATORY CONTROL SERVICE

gives fleet operators specific recommendations for their units, based on analysis of crankcase oil. Helps to establish correct drain periods, conserve engine life, reduce lay-ups ... frequently reveals unsuspected engine troubles. Free and without obligation.

MOTOR OIL AND LUBES

100% Pennsylvania WOLIS HEA -"Premium Grade"



P.G.C.O.A. Permit No. 6 SNYDER — THE TANK THAT MADE TRUCK OPERATION SAFE & PROFITABLE MAXIMUM FIRE HAZARD PROTECTION — LESS REFUELING, FASTER, LONG SERVICE RUNS

SNYDER SADDLE TANK CAPACITY 75 TO 125 GALS.

SNYDER SAFETY TANKS

were born when Truck Transportation struggled as an infant industry. SNYDER progressive engineering research continually uncovering exclusive improvements (patents No. 218-1772—2273737 others pending) leads Truck Transportation into BIG BUSINESS, improvements available only in SNYDER SAFETY TANKS . . U. L. approved.

WHEN YOU BUY A TANK-BUY A SNYDER TANK-AND YOU BUY THE BEST.

For Catalog and Address of Your Nearest Distributor, Write:

SNYDER TANK CORPORATION

P. O. Box 14, Buffalo 5, N. Y.

SNYDER TANK CORPORATION P. O. Box 2390, Birmingham, Ala.



DECAL

for FLEET MARKING Costs less than hand lettering. Does not tie up equipment.

Quantities - 50 pieces or more any

Can reproduce any art work.

Prompt Delivery

EXCELLO SPECIALTY CO. 4101 East 100 St. Cleveland 5, Ohio



CLIX ENGINE PROTECTION

Pressure Clix

Signal device for lost oil pressure— lost air pressure in braking system on gasoline and Diesel engines.

Thermo Clix

Instant alarming device when temper-ature of the engine reaches the danger point.

Write for descriptive folder today!

THE NASON CO.

7663 Epworth Blvd.

Detroit 4, Mich.

BLACK GOLD Metallized

BRAKE LININGS

are guaranteed not to score brake drums

L. J. MILEY COMPANY
18 S. Sangamon St., Chicago 7

CCJ Newscast

(CONTINUED FROM PAGE 94)

HOME TOWN NOTES

Baltimore: A new Highway Trailer Co. direct factory sales and service branch at

Detroit: A new Borg-Warner Service

Houston: U. S. Equipment Co., 41 Jacinto St., now handles Ruger hydraulic cranes

Jacksonville: Southeast Wheel & Rim Co., Inc., is new distributor for Brown Industries (Spokane, Wash.) aluminum trailers.

handles Kentucky Trailers. Company has branches in Indianapolis, Evansville, Nashville and Knoxville.

St. Louis: Borbein-Young and Co., wheel, rim, brake and spring specialists, have opened an ultra modern plant at 3663 Forest Park Ave.

Tampa: Mack Trucks, Inc., has a new direct factory branch.

ATA REGIONAL MEETINGS

ing executives of the trucking industry will discuss current operating problems have been scheduled by the American Trucking Associations, Inc. The meetings are designed to supplement the annual business sessions of the association and will place primary emphasis on highway safety and courtesy. Dates and places are as follows:

New York City, Hotel New Yorker, April 8-10; Atlanta, Ansley Hotel, April 13-15; Detroit, Hotel Statler, May 10-14; Fort

6401 Erdman Ave.

Parts Co. warehouse at 1345 East Milwaukee Ave.

and presses.

Louisville: Louis Augustus, Inc., now

Eight regional meetings at which lead-

2-4; Salt Lake City, New House Hotel, June 8-10; San Francisco, Palace Hotel, June 14-16; Boston, Statler Hotel, July 12-14 (also tentative). The Detroit meeting is to be combined

Worth, May 18-20 (tentative-no hotel an-

nounced); St. Paul, St. Paul Hotel, June

with the annual spring meetings of ATA's Department of Safety and the Equipment and Operations, Customer Relations, Accounting and Freight Claim sections.

(TURN TO PAGE 218, PLEASE)







It's rumored that...

more than 1,450 fleets are now using Perfect Circle's Fleet Survey Plan! Right, and with its help they've been able to cut operating and maintenance costs. For information on how the Fleet Survey Plan can help you, see your P. C. representative or write: The Perfect Circle Companies, Hagerstown, Ind., U.S. A. and Toronto, Ont., Canada.



by Hart Pressed Steel Corp. enables you to build to any design!

Parts for this new Full View Single Unit are the result of thousands of dollars expended on development, testing, and engineering — designed to be competitive for the body builder and more economical for the fleet owner.

Gain uniformity of style regardless of where built! Get immediate delivery of replacement parts for quick repair.

HART PRESSED STEEL CORP. ELKHART, INDIANA

THE Complete



Incorporated in each "Oldfarge" Tool is the "know how" developed during 25 years of tool making. The skill and experience gained during these years, together with the development of "Oldfarge Grey Metal"—an unusually tough steel altoy, has resulted in tool values that are tops. They are the choice of discriminating mechanics everywhere; you, too, can experience the pleasure of using them. Their design, temper and finish make them a joy to handle.

Ask your supplier or write us direct

QUALITY TOOLS CORP., New Wilmington, Pa. New York Office: 11 Warren St. • Phone Worth: 3640

Specify **Double-Duty** TRUCK CHAINS Columbus McKinnon Chain CORPORATION TONAWANDA, N. Y.



Fluid Carriers

THE DAVISBILT PRODUCTS CO.

Affiliated with Liberty Products Corp.



hand or power hydraulic control FOR ALL MOTOR TRUCKS

CARL H. FRINK, MFr., CLAYTON, 1000 Fil., M. Y DAVENPORT-BESLER CORP., DAVENPORT, IOWA FRINK SNO-PLOWS OF CAN. Ltd., TORONTO, ONT



Revolutionary NEW washing method for Automotive and Industrial Cleaning.

A real money-saver and money-

Write for further information.

J. P. MANUFACTURING, Inc. 330 E. FRONT ST., YOUNGSTOWN, OHIO

ZEHR .

COLLAPSIBLE TRUCK BACKS



safe . . . easy and simple to handle. Zehr Truck Truck Backs all - welded 910 steel designed for great strength and long continuous service.


They are theft-proof, rust-proof and flexible.

Write for details and prices.

ZEHR PRODUCTS COMPANY 2130 East Hazzard Street, Philadelphia 25, Pa.

HydrauLock THE standard BRAKE LOCK

Pull Out Dash Control. Step On Brake Pedal. Your Brakes Are Locked! Write for information.





HARD FACED VALVES

Your used valves rebuilt for

better performance and economy.

LONGER SERVICE

UNPROTECTED VALVES

Prompt, Personalized Service BCHAUST . INTAKE . SODIUM-COOLED GASOLINE . DIESEL

					-			-	-			
OLEVI	ELA	ND	H	ARE	FA	CIN	G.	110	COR	POP	LAT	TED
21.77												
Please				-	-							
	941	-		******	111011	- Gran		NI CO	1101	0		

					2		-									Е	3											
CHTY .	 														9	1	1	A	T	E								
MARIE		 					,	*	×				0.								*	н	*			E.	6	
HAME			8		ě	t		k			*	×					*	*		×		×	×	¥	×			

SEMA ADOPTS NEW STANDARD FOR SAFETY EQUIPMENT ITEMS

Safety Equipment Manufacturers Association, at its annual meeting recently in Chicago, announced that its members are committed to the manufacture of all items of safety equipment in conformity to National Commercial Standards.

Recently the American Association of Motor Vehicle Administrators announced its "One Test for the Entire Country" plan, under which AAMVA will certify to the individual States all items of equipment conforming to the requirements of either SAE Specifications or National Commercial Standards for After-Market Equipment, to the end that eventually all equipment will be approved according to uniform specifications at one central point rather than to have approvals handled in each state individually as has been done in the past.


As the original sponsors of National Commercial Standards for after-market equipment, SEMA will sponsor Commercial Standards additional to those already adopted with the end in view of Commercial Standards for all items of equipment required to be approved by the Interstate Commerce Commission or the various

Additionally, all items of equipment so constructed by SEMA members and certified by AAMVA as having been laboratory tested and found to comply with National Commercial Standards will be covered by a Re-examination Service under which the testing laboratories will semi-annually reexamine samples purchased on the open market to insure all-time compliance with adopted standards.

As soon as original laboratory tests can be brought up-to-date and re-examinations can be scheduled, SEMA members will mark each item of equipment and each carton in which each item is packed with a distinctive mark indicative of such original laboratory testing and re-examination.

Such labeling of products and cartons, when coupled with the "One Test" supervised from AAMVA headquarters, SEMA believes, will go far toward insuring the universal production of high-quality equipment which may truly be designated "safety" and will provide the vehicle user with a ready means of identifying equipment constructed to his needs and con-, forming to the requirements of all states through or in which his vehicles will operate.

(TURN TO PAGE 220, PLEASE)



hesion—outstanding durability.

Ditzler Color Division, Pittsburgh Plate Glass Company, 8000 W. Chicago Ave., Detroit 4, Mich.

4 1/4

"ATTENTION WHITE OWNERS"

Make old crankshaft pulleys stay tight on worn shafts by a special bushing and puller combined. Easy to install and remove. No driving. Any lathe hand can make it. Tried and approved by a large fleet owner. Satisfaction guaranteed on all models. Complete plans \$5.00. Address Jarvis Brothers, Mechanical Research Division, R. D. 2, Finleyville, Pa.

Belden

Gutmotte WIRE







Trailer Makers

(CONTINUED FROM PAGE 68)

to brake-operating valves is diminished.

Another problem was presented by an operator who had had a costly experience with a failure in a wheel chamber which was beyond the control of all valve equipment. Under this condition air pressure was quickly lost when brakes were applied. leaving both truck and trailer without brakes. By reducing the aperture on the air intake to the trailer tank without affecting the speed of emergency braking, a condition was created wherein all lines to trailer wheels may be broken without loss of air except during actual brake application. And if the brake application is attempted, the loss of air pressure from the truck tank is so reduced as to require almost a full minute to become impotent. Not just a minute in time but a minute of brake application. Mr. Seale pointed out that since 60 mph is 88 ft a second, sometimes 20 seconds can be a long time.

Still another development was revealed by Mr. Seale. Under present conventional arrangements, he explained, the trailer brakes go into emergency operation if the air supply to the trailer is broken. But if the control or service line to the trailer is broken the emergency application is not made and it is then not possible for the driver to operate the trailer brakes. Applying the truck brakes under this condition might result in a costly jackknife. Work has been done on this problem, according to Mr. Seale, to the point where a service line valve has been developed and successfully tested in the laboratory. With this unit, if the service line to the trailer is broken, any attempt to apply the brakes will close the air supply line to the trailer to prevent loss of air from the truck and will also put trailer brakes into emergency operation. An operating model of the unit will be road-tested in about 30 days.

Seven Resolutions

IN a series of resolutions passed at the business session, the Association

1. Emphasized to Congress and Federal officials the dangers of arbitrarily limiting supplies of trailer materials, especially steel, in the voluntary allocation program;

2. Resolved to broaden the scope of its public relations activities and work in harmony with motor carriers and their associations in furtherance of their highway safety and courtesy program;

3. Called for the repeal of automotive excise taxes in the present session of Congress:

4: Urged the planners of European aid to consider the advantages of trailers and to develop the art of transportation abroad along the same lines which have proved successful in the United States;

5. Promised to aid the National Defense Program, particularly in design engineering:

6. Endorsed the principle of Federal and State labor-management laws recently en-(TURN TO PAGE 222, PLEASE)

UNITS

GRICO

19842 W. Eight Mile Rd. Detroit 19, Michigan





U.S. Pat. No. 2,093,547 — Conadian Pat. No. 223,568
INTERNATIONAL CHAIN & MFG. COMPANY
YORK, PENNSYLVANIA



Pre-Insulated
STEEL BUILDINGS

Prompt delivery complete in one package 24' and 40' clear span or any multiple. Any length, multiples of 8'.

GARAGES • WAREHOUSES

THE PIONEER COMPANY


Century Building • Pittsburgh 22, Pa.



HOLLAND Improved

Landing Gear
Load Lifting
power unequelled by any
other type. 4"
more ground
clearance than
other types.
Fast, easy operation.
SAFE — SIMPLE

HOLLAND HITCH COMPANY HOLLAND, MICHIGAN, U.S.A.



Standard TRUNNION AXLE
Standard Problems Vanish!...
Heavy Hauling Problems Vanish!...

- Adds years to life of trailer
- Makes possible lower frames—for easier loading

Make a decisive move towards low maintenance costs and a high degree of satisfaction by specifying Standard Trunnion Axles. Axle alignment maintained by wider spacing of frame bearings, making for lower upkeep costs and greater strength. Compactness of design enables use of eight wheels in line, within minimum space, allowing removal of inner tires without removal of axle from the trailer. Also makes possible lower trailer frames for easier loading and greater strength. Write, wire or phone today for complete information.

EXPORT BRANCH: 4900 Euclid Ave., Cleveland, Ohio
PHONE: HENDERSON 0414. CABLE ADDRESS: STANFORAX, C. O. BRANDES, Mgr.



MONTGOMER

AMA









Trailer Makers

(CONTINUED FROM PAGE 220)

acted and pledged to help bring about their successful administration;

7. Opposed President Truman's high budget figures, called for governmental economies, and urged tax reduction.

Buhner Predicts Bright Future

SPEAKERS were featured at the three days sessions. Ed. J. Buhner, president of the American Trucking Associations, Inc., noted a "clearly marked" trend to truck transportation during the last two decades and predicted this trend will be accelerated during the next decade because of a rapid population growth and a movement toward decentralization of business and life from city to suburbs.

"While other forms of property transportation may suffer and I think will suffer substantially from the decentralization," Mr. Buhner said, "I know for certain that highway transport will benefit. We are completely flexible. No longer do producers and distributors have to hug the center of cities, and build their plants along rail lines or sidings."

Highway Planning

P. D. McLEAN, assistant director of the National Highway Users Conference, said that long range state highway planning is "the highway user's answer to the highway 'promoter' who wants all the emphasis put on building of highways and little or none on how they can be reasonably financed. Our problem is to find out which roads most need improvement and how we can pay for the job without taxing some drivers off the roads."

L. C. Allman, vice president of the Frue-

hauf Trailer Co., declared that the public is being deprived of the full use of existing highways because of hodge-podge state vehicle size and weight laws.

"It is about time," Mr. Allman said, "to stop this business of accepting any old vehicle size and weight figures because they happen to represent a little increase in what the present state laws may be. Let us liberate roads and streets from strangulation by ultra-conservative highway measures and from danger of prostration by unwarranted financial burdens."

(TURN TO PAGE 224, PLEASE)










Profit earners for your shop"

handy, reliable

K-D TOOLS



K-D MANUFACTURING CO., LANCASTER, PA., U.S.A.

HAMILTON, ONTARIO, CANADA

HAVING GLASS TROUBLE?

We can solve your problems with hard to break, shatter-resistant PLEXIGLAS*, the clear plastic which is becoming increasingly popular for truck and car doors. It will last the life of the vehicle when properly handled.

The use of PLEXIGLAS in motor vehicle glazing has been permitted in some states and should be checked with your state inspector.

Make	Net Price
Ford Door	\$8.45
Chev. Door	7.85
Dodge Door	7.85
(EH) Mack Door	10.19
LFT Mack Door	12.45
White Door	8.45
	7.85
	5.40
International	8.83
	Ford Door Chev. Door Dodge Door (EH) Mack Door LFT Mack Door

Others \$2.75 to \$12.50. Prices on request.

Terms C.O.D. or cash with order, F.O.B. Aberdeen

ABERDEEN AUTO PARTS

Box 283-C

Aberdeen, Md.

Phone Aberdeen 258

*PLEXIGLAS registered trade mark of Rohm & Haas Company.





FOR TRUCKS, TRAILERS AND BUSES.
THE DAYTON STEEL FOUNDRY CO.
DAYTON, OHIO



Trailer Makers

(CONTINUED FROM PAGE 222)

No Substitute for Courtesy

WALTER W. BELSON, director of Public Relations for the American Trucking Associations, Inc., reminded the industry that "there is no substitute for actual courtesy and safety on the part of truck drivers. They are the trucking industry, so far as the public is concerned, every time they roll out into the streets or highways. No amount of publicity, no breast-beating in print or over the air, no loud protestations of virtue can influence the opinion of a man formed through an unhappy personal experience with a truck. There is only one formula for meeting this problem. That is to step up our safety activities as an industry to a point not heretofore reached. That should be the program of everyone with a direct or indirect interest in the trucking industry's welfare.

President's Report

In the president's annual report, outgoing association president Julius L. Glick, of Truck Engineering Corp., said that the industry had had a good year in 1947, producing 55,000 motor, freight vehicles. This output fell short of the 1946 total but was far ahead of the prewar record of 41,869 units produced in 1941. He pointed out that the industry's products were brought to customers at prices which were only about 17 per cent above the prewar level, in contrast with an average jump of 71 per cent in prices of all manufactured goods.

Officers and directors elected for 1948 are as follows: President, Harrison Rogers, Rogers Bros. Corp.; western vice president, John C. Bennett, Utility Trailer Mfg. Co.; eastern vice president, J. Cottrell Farrell, Easton Car & Construction Co.; treasurer, W. E. Grace, Hibbs Mfg. Co.; directors, L. C. Allman (Fruehauf), Bert P. Bates (Highway), F. A. Schotters (Trailmobile), R. C. Tway, Jr. (Kentucky), E. J. Ziegler (Keystone), C. A. Persinger (Wilson), L. A. Myers, Jr. (Black Diamond), Christopher Hammond, Jr. (Steel Products), J. L. Glick (Truck Engineering).

END

(Please resume your reading on P. 71)

J. H. JENKINS DIES

J. H. Jenkins, 49, district manager for The Autocar Co. at Charlotte, N. C., died Jan. 17 in that city following an operation.





Better—but not more expensive!

SHULER AXLES

SHULER AXLE CO. LOUISVILLE, KY.

DUNK 'EM IN GUNK H-S





SPEAKER TUBE REPAIRS

One Reliable Source for all your needs
Electromatic Vulcanizer * Match Patch Vulcanizer * Match Patches * Electro-Patches
* Rubber Rivets * Replacement Valves *
Electro-Timer * Casing Patches * Convertible
Tire Valves * Valves and Caps * Matorists'
Kits * Solvents * Beveled Patches.

J. W. SPEAKER CORP. • Milwaukee 12, Wis.

FLARES
FOG LAMPS
REFLECTORS
STOP LIGHTS
MARKER LIGHTS
CLEARANCE LIGHTS
DIRECTIONAL SIGNALS
SEALED BEAM CONVERSION KITS

ARROW SAFETY DEVICE CO.



NO DETERIORATION PROMPT DELIVERY

eschenbach & rodgers, lig.

HAULING CONTRACTORS 520 N. SEVENTH AVE. SCRANTON 3, PA.

October 7, 1947

Reynolds Metals Company Truck & Trailer Div. (Plant 14) Louisville, Kentucky

In June of this year we purchased four Reynolds all Gentlemen: aluminum bodies through the Campbell Body Works, Olyphant, Penna. These bodies are 16 feet long and 71 feet wide and are equipped with a 4" aluminum diamond tread plate flooring.

Three of these trucks have been equipped with an Anthony Hydraulic Tail Gate and are used in the delivery of Jane Parker Bakery Goods to A & P Stores in lower New York State. These trucks have traveled in the past four months 24,480 miles, or 255 miles per day for six days a week. They have not deteriorated one iota in appearance during this mileage and cannot be distinguished from a truck just out of the factory.

The other truck has been used in the delivery of groceries, produce and bakery products to various A & P Stores, and like the three mentioned above, is still a brand new truck, despite the fact that 25,340 miles have been traveled in four

Another feature of the Reynolds all aluminum body with Anthony Tail Gate and chassis is that the overall weight is but months.

At the present time you cannot buy a truck body within a radius of 135 miles from Scranton in less than three months 9700 lbs. delivery, whereas we have given our order on Tuesday for the Reynolds Body through the Campbell Body Works and delivery was made on Saturday, just four days later. This immediate delivery still obtains.

We cannot praise the Reynolds aluminum body too highly and we are looking forward to years of steady usage.

Yours very truly,

ESCHENBACH

Hugh J/ Rodde

Assembly from stock parts. For name of nearest distributor write Reynolds Metals Company, Truck & Trailer Division, 2000 South Ninth Street, Louisville 1, Ky.

THE LIGHTWEIGHT

CHAMPIONS OF THE ROAD"



REYNOLDS ALUMINUM TRUCK



NEW LOW COST DRILL GRINDER

Anyone can do expert drill grinding with this simple-to-use drill grinding attachment—fits on any bench grinder—saves buying new, twist drills—saves time and materials that dull bits waste. Grinds bits from 3/16 to 11/4.



CRACKED **BLOCKS?**

AMS new metallic powder treatment repairs eracks with a HARD, METALLIC, OHEMICAL-WELD. Once set, will last forever. Func-tions tafely with anti-freeze. (Will not wante.)



THE ZO-TITE PRODUCTS CO. Dept. CC, Ozone Park 16, N. Y.



MONKEY LINKS

Fit all types of Tire Chains. Made in 5 sizes.

Order them

FLOWER CITY SPECIALTY CO.

Rochester, N. Y. fark Reg. U.S. Pat. Off

Introducing

(CONTINUED FROM PAGE 96)

... CHARLES W. SELF, PAUL R. WARREN, and John Macksey as new zone sales managers for The General Detroit Corp. with headquarters in Cincinnati, Boston, and St. Louis, respectively.

.. A. J. NELSON as manufacturer's agent in the Rocky Mountain area for Kold-Hold Mfg. Co., Lansing, Mich.

.. ROBERT KLARE as manager of Federal-Mogul Corp.'s Greenville, Mich., plant, and ELMER PETT as works manager of the St. Johns, Mich., plant.

.. ROBERT E. CARBAUH as sales manager of a new department for the development and promotion of fire control equipment by Titeflex, Inc., Newark, N. J.

.A. A. LUNDCREN as Burd Piston Ring Co. representative in southern California, Arizona, and Clark County, Nevada, with headquarters in Fontana, Calif. FRED P. RAPP covers the northern California territory and the balance of Nevada from headquarters in San Francisco.

.. A. E. KRASICK of Minneapolis, as national field supervisor of the Spark Plug Division, Hastings Mfg. Co.

.. W. FRANKLIN MEYER and ROBERT J. CLARKE as divisional managers for Hastings Mfg. Co. with headquarters in Houston, Texas, and Chicago, respectively.

.. W. F. Newberry as assistant director of sales, Detrex Corp., Detroit, and LERoy CAMEL as new sales manager of the Industrial Products Division.

. CLARENCE S. BEESEMYER and PHILIP S. MAGRUDER as executive vice-presidents, the General Petroleum Corp., Los Angeles.

... DAVID C. LEGAULT as assistant sales manager of Airtex Automotive Division. Chefford Master Mfg. Co., Inc., Fairfield,

... EDWARD QUEKELS as director of the newly-created product development and service department of Bear Mfg. Co., and WALTER V. HALL as sales manager.



With Fleet Forms it's easy to keep complete service and cost records for every vehicle in your fleet. So simplified any attendant can keep these records. So complete you can see the whole story at a glance. Schedules inspections and periodic maintenance, plus dozens of other types data...on one record.

Write today for free samples and prices

FLEET FORMS CO. COLUMBUS 1, ONIO 1410 H. HIGH ST.



RUGER.

Hydraulic FLOOR CRANES

and Arbor Presses

RUGER EQUIPMENT CO., Inc.

2425 St. Clair Ave. Cleveland 14, Ohio

P. O. Box 3821 Portland 8, Ore.



Differential NoSPIN



driving Provides greater traction, greater driving safety, less tire wear. Easily installed in your

DETROIT AUTOMOTIVE PRODUCTS CORP. 8701 Grinnell Ave. Detroit 13, Michigan



Willard

Dependability and Performance Mean

QUICK STARTS LONG LIFE LOW COST PER MILE



Willard Heavy Duty Transport Batteries

Designed particularly to withstand severe vibration and cycling service in commercial applications. Heavy plates, Sturdy hard rubber containers. Willard Safety-Fill Construction. Willard Rubber Insulation and glass fibre retaining mats for severe, high mileage service. Selected wood separators and glass fibre retaining mats for normal service.

WILLARD STORAGE BATTERY COMPANY

Cleveland .

Los Angeles

Dallas

Memphi

Portland

Toronto

YOU GET MORE WORK DONE WITH FWD TRUCKS

THEY SPEED CONCRETE MIXING AND HAULING AT LOW COS



Keeping mixers on the move between central mixing plants and pouring points, speeds operations — makes more money for you. So does a mixer that has FWD four-wheel-drive power and traction to maneuver fast and safely on the job — even when

it's off the road, over rough ground of construction sites.

Mount your mixers on FWD fourwheel-drive trucks and you have what it takes to keep going — up and over steep grades, through loose sand or sticky gumbo, over rough and rocky ground, working on or off the road. You speed all operations — you get more work done, more profitably — with mixers mounted on FWDs.

See your nearest FWD Distributor or write for complete information.



THE FOUR WHEEL DRIVE AUTO CO., Clintonville, Wisconsin

Canadian Factory: Kitchener, Ontario

WORLD-WIDE SALES and SERVICE

America's Foremost Heavy-Duty Truck

